



- ! Drop Point
- Ⓐ Helispot
- ☁ Mobile Weather Unit
- 🔊 Repeater
- Ⓐ Other
- ) Division Break
- Uncontrolled Fire Edge
- Contained Line
- Completed Dozer Line
- Completed Hand Line
- Access or Improved Road
- Repair Line
- Completed, Not Controlled (handline)

- Repair Status**
- Completed - Inspected
  - In Use - Fire Management
  - Completed - Ready for Inspection
  - In Progress
  - Repair Needed
  - No Repair Needed
  - Other - See Comments
  - Unknown
  - Completed - Inspected
  - In Use - Fire Management
  - Completed - Ready for Inspection
  - In Progress
  - Repair Needed
  - No Repair Needed
  - Other - See Comments
  - Unknown

**REPAIR**  
RANCH 2  
CA-ANF-003289  
08/21/2020

Feature/Category	Repair Status	Length (feet)	Length (Miles)
Access or Improved Road In Progress	Completed - Inspected	3229.32	5.73
Access or Improved Road Repair Needed	Completed - Ready for Inspection	4795.59	9.09
Access or Improved Road Unknown	Unknown	3968.36	0.75
Air Tanker Release Point	Completed - Inspected	6209.27	1.22
Completed Dozer Line	Completed - Inspected	1963.45	0.37
Completed Dozer Line	Completed - Ready for Inspection	9720.98	1.84
Completed Dozer Line	Repair Needed	9742.48	18.45
Completed Dozer Line	Unknown	12319.95	2.33
Completed Hand Line	Repair Needed	6924.53	1.31
Contained Line	Completed - Inspected	6234.83	1.18
Contained Line	Completed - Ready for Inspection	59279.18	2.09
Contained Line	No Repair Needed	4292.3	0.03
Contained Line	Repair Needed	6882.25	1.30
Contained Line	Unknown	7876.49	1.49
Other	Completed - Ready for Inspection	1337.93	2.53
Other	Repair Needed	15262.52	2.96
Other	Unknown	20988.41	3.98
Repair Line	Repair Needed	681.69	0.13

Scale: 0 0.5 1 2 Miles  
1:18,000  
Map Updated 8/20/2020 22:45