



- Culvert
- Dip Site
- Drop Point
- Dozer Push
- ⊕ Fence - Cut/Damaged
- Gate
- ⚠ Hazard Tree
- ⊕ Helibase
- Helispot
- Hot Spot
- Internet Access
- Landmark
- ⊕ Mobile Weather Unit
- ⊕ Repair Point
- ⊕ Repeater
- ⊕ Retardant in Avoidance Area
- ⊕ Retardant/Mud Pit
- ⊕ Road Repair
- ⊕ Staging Area
- ⊕ Structure Wrap
- ⊕ Water Source
- ⊕ Restricted Water Source
- ⊕ Water Development or Draft Site
- ⊕ Other
- ⊕ Division Break
- ⊕ Uncontrolled Fire Edge
- ⊕ Contained Line
- ⊕ Completed Dozer Line
- Completed Hand Line
- Road as Completed Line
- Access or Improved Road
- Proposed Dozer Line
- Planned Fire Line
- Aerial Retardant Drop
- Fence
- Repair Line
- Road Repair
- Contained, Not Controlled
- Restoration Sites

- Repair Status Point
- Completed - Inspected
- In Use - Fire Management
- Completed - Ready for Inspection
- In Progress
- Repair Needed
- No Repair Needed
- Other - See Comments
- Unknown
- Completed - Inspected
- In Progress
- Repair Needed
- No Repair Needed
- Other - See Comments
- Unknown
- Rotary TESP
- - trackdata_sbr_2

REPAIR
BOBCAT
CA-ANF-003687
10/30/20

N
W S E

0 1 2 3 4 Miles

1:55,000

Map Updated: 10/29/2020 22:14