

Repair Status Point
● Completed - Inspected
● Completed - Ready for Inspection

Repair Status Line
● Repair Needed
● No Repair Needed

Repair Status Line
● Unknown
● Camp
● Culvert

Repair Status Line
● Dip Site
● Drop Point
● Dozer Push
● Hazard

Repair Status Line
● Hazard Tree
● Helispot
● Mobile Weather Unit
● Repair Point

Repair Status Line
● Repeater
● Safety Zone
● Spot Fire
● Staging Area


Repair Status Line
● Stream Crossing
● Structure Wrap
● Water Source
● Water Development or Draft Site

Repair Status Line
● Value at Risk
● Other

Repair Status Line
● Uncontrolled Fire Edge
● Contained Line
● Division Break
● Completed Dozer Line
● Completed Hand Line

Repair Status Line
● Road as Completed Line
● Access or Improved Road
● Fence
● Road Repair

Repair Status Line
● Other
● Private Lands within the Forest Boundary
● National Forest Boundary
● USDA Forest Service



0 0.5 1 2 Miles
Scale: 1:35,000 Name: NAD 1983 California Teale Albers
Contours 40 ft

