


	Repair Status Point ● Completed - Inspected ● In Progress ● Repair Needed	Repair Status Line — No Repair Needed — Completed - Inspected — Completed - Ready for Inspection — In Progress	Repair Needed — No Repair Needed — Other - See Comments	○ Bridge ● Camp ○ Culvert ● Dip Site — Gate	● Drop Point ● Dozer Push ● Fence - Cut/Damaged ● Landing or Log Deck ● Safety Zone	● Hazard ● Hazard Tree ● Helispot ● Landing or Log Deck	● Repair Point ● Resource Location ● Road Repair ● Safety Zone	○ Sling Site ○ Staging Area ○ Stream Crossing ○ Water Development or Draft Site	▲ Value at Risk ● Other	— Uncontrolled Fire Edge — Contained Line — Completed Dozer Line — Completed Hand Line	— Road as Completed Line — Access or Improved Road — Line Break Completed — Fire Break Planned or Incomplete	○ Aerial Retardant Drop ○ Ridge/Geographic Feature — Road Repair ○ Other	— National Forest Boundary — USDA Forest Service — Private Lands within the Forest Boundary
--	---	---	--	---	---	--	---	--	----------------------------	---	---	---	---



0 0.5 1 2 Miles
Scale: 1:35,000 Name: NAD 1983 California Teale Albers
Contours 40 ft

USDA
US Forest Service