


Branch XIX



	Repair Status Point	Repair Needed	Repair Status Line	Repair Needed	Bridge	Dip Site	Gate	Internet Access	Repair Point	Stream Crossing	Other	Completed Hand Line	Completed Burnout	Other	Private Lands within the Forest Boundary
	Completed - Inspected	No Repair Needed	Completed - Inspected	No Repair Needed	Camp	Drop Point	Hazard	Landing or Log Deck	Repeater	Structure Wrap	Division Break	Ridge/Geographic Feature	National Forest Boundary	National Park Service	
	Completed - Ready for Inspection	Other - See Comments	Completed - Ready for Inspection	Other - See Comments	Closure	Dozer Push	Unimproved Landing Area	Lookout	Safety Zone	Water Source	Contained Line	Access or Improved Road	Repair Line	USDA Forest Service	
	In Progress	Unknown	In Progress	Unknown	Culvert	Fence - Cut/Damaged	Helispot	Mobile Weather Unit	Spot Fire	Value at Risk	Completed Dozer Line	Completed Plow Line	Road Repair		

Branch XIX	1	2	3
Branch XX	4	5	6
Branch XXI	7	8	9

0 0.5 1 2 Miles

Scale: 1:35,000 Name: NAD 1983 California Teale Albers

Contours 40 ft

Page Number: 2