



	<b>Repair Status Point</b> <span style="color: green;">●</span> Completed - Inspected <span style="color: blue;">●</span> No Repair Needed <span style="color: yellow;">●</span> Completed - Ready for Inspection <span style="color: red;">●</span> In Progress <span style="color: purple;">●</span> Unknown	<b>Repair Status Line</b> <span style="color: green;">—</span> Completed - Inspected <span style="color: blue;">—</span> No Repair Needed <span style="color: yellow;">—</span> Completed - Ready for Inspection <span style="color: red;">—</span> In Progress <span style="color: purple;">—</span> Unknown	<b>Repair Needed</b> <span style="color: red;">—</span> Repair Needed <span style="color: blue;">—</span> No Repair Needed <span style="color: purple;">—</span> Unknown	Bridge Dip Site Gate Helispot Repeater Stream Crossing Division Break H Completed Hand Line M Fire Break Planned or Incomplete Road Repair USDA Forest Service Bureau of Land Management Bureau of Land Management CA Dept. of Fish and Wildlife Other State Lands	Camp Drop Point Hazard Hazard Tree Mobile Weather Unit Staging Area Other Completed Dozer Line M Line Break Completed Repair Line Private Lands within the Forest Boundary National Forest Boundary Bureau of Indian Affairs	Access or Improved Road Value at Risk Contained Line Ridge/Geographic Feature Aerial Retardant Drop Aerial Retardant Drop Other National Forest Boundary Bureau of Indian Affairs	Fuel Avoid Driving Through Invasive Plant Fuel Avoid Driving Through Invasive Plant	Branch 1 Branch 2 Branch 3 Branch 4 Branch 5 Branch 6 Branch 7 Branch 8 Branch 9	0 0.5 1 2 Miles Scale: 1:35,000 Name: NAD 1983 California Teale Albers Contours 40 ft		
	Page Number: 6										