



DIV S

DIV R

	<b>Repair Status Point</b>	Completed - Inspected	No Repair Needed	<b>Repair Status Line</b>	Completed - Inspected	Repair Needed	No Repair Needed	Bridge	Drop Point	Helispot	Road Repair	Stream Crossing	Branch Break	Completed Dozer Line	Line Break Completed	Road Repair	Private Lands within the Forest Boundary
In Progress	Repair Needed	Completed - Ready for Inspection	Unknown	Camp	Dozer Push	Safety Zone	Sling Site	Culvert	Fence - Cut/Damaged	Repair Point	Sling Site	Value at Risk	Dip Site	Gate	Contained Line	Uncontrolled Fire Edge	Division Break
Other - See Comments	Other - See Comments	Other - See Comments	Other - See Comments	Landing or Log Deck	Water Development or Draft Site	Staging Area	Division Break	Resource Location	Staging Area	Division Break	Division Break	Division Break	Division Break	Division Break	Division Break	Division Break	Division Break

Branch XII	4	3
Branch XI	4	5
Branch X	6	7
Branch IX	8	9

0 0.5 1 2 Miles  
 Scale: 1:35,000 Name: NAD 1983 California Teale Albers  
 Contours 40 ft

USDA  
 US Forest Service  
 Page Number: 7