



Repair Status Point		Repair Status Line		Repair Needed		Camp		Dozer Push		Helipoint		Retardant/Mud Pit		Stream Crossing		Contained Line		Access or Improved Road		Repair Line		USDA Forest Service			
	Completed - Inspected		Completed - Inspected		Repair Needed		Camp		Dozer Push		Helipoint		Retardant/Mud Pit		Stream Crossing		Contained Line		Access or Improved Road		Repair Line		USDA Forest Service		
	Completed - Ready for Inspection		Completed - Ready for Inspection		No Repair Needed		Culvert		Fence - Cut/Damaged		Mobile Weather Unit		Road Repair		Value at Risk		Completed Dozer Line		Fire Break Planned or Incomplete		Road Repair		Private Lands within the Forest Boundary		
	In Progress		In Progress		Unknown		Dip Site		Gate		Repair Point		Safety Zone		Completed Hand Line		Aerial Retardant Drop		National Forest Boundary		Bureau of Land Management		Non-Profit Conservancies and Trusts		Other Federal Lands
	Repair Needed		No Repair Needed		Other - See Comments		Drop Point		Helibase		Staging Area		Division Break		Completed Road as Completed Line		Ridge/Geographic Feature		Bureau of Indian Affairs		Bureau of Indian Affairs		Bureau of Indian Affairs		Bureau of Indian Affairs

Scale: 1:35,000 Name: NAD 1983 California Teale Albers

Contours 40 ft

Page Number: 8