



	Repair Status Point	Repair Needed	Repair Status Line	Repair Needed	Camp	Dozer Push	Helipoint	Retardant/Mud Pit	Stream Crossing	Access or Improved Road	Repair Line	USDA Forest Service	Bureau of Land Management
	Completed - Inspected	No Repair Needed	Completed - Inspected	No Repair Needed	Culvert	Fence - Cut/Damaged	Mobile Weather Unit	Road Repair	Value at Risk	Fire Break Planned or Incomplete	Road Repair	Private Lands within the Forest Boundary	Non-Profit Conservancies and Trusts
	Completed - Ready for Inspection	Unknown	Completed - Ready for Inspection	Other - See Comments	Dip Site	Gate	Repair Point	Safety Zone	Division Break	Aerial Retardant Drop	National Forest Boundary	Other Federal Lands	
	In Progress	Unknown	In Progress	Dip Site	Helibase	Staging Area	Repeater	Road as Completed Line	Branch Break	Completed Hand Line	Ridge/Geographic Feature		

0 0.5 1 2 Miles

Scale: 1:35,000 Name: NAD 1983 California Teale Albers

Contours 40 ft

Page Number: 8