

Column1	Column2	Column3	Column4	Repair Points	Column5	Column6	Column7	Column8	Column9
ID	Type	Collector	Comments	Latitude	Longitude	Repair Status	Repair Comments	PointDateTime	ArchClearance
1	Structure Wrap	FOBS-T McDonald	3 small structures, wrapped w/ sprinklers	36° 07.55301370' N	118° 17.56124096' W	Repair Needed		2020-09-04 17:01	Not Cleared
2	Structure Wrap	FOBS-T McDonald	Structure, wrapped w/ sprinklers	36° 06.76494974' N	118° 17.77598521' W	Repair Needed		2020-09-04 17:24	Not Cleared
3	Structure Wrap	FOBS-T McDonald	Structure, wrapped w/ sprinklers	36° 07.09342559' N	118° 17.83049617' W	Repair Needed		2020-09-04 18:28	Not Cleared
4	Structure Wrap	FOBS-T McDonald	Structure, wrapped w/ sprinklers	36° 07.15244765' N	118° 17.87402842' W	Repair Needed		2020-09-04 18:32	Not Cleared
5	Structure Wrap	FOBS-T McDonald	2 structures, 1 wrapped, 1 partial wrap, both	36° 07.29806396' N	118° 17.71812504' W	Repair Needed		2020-09-04 18:48	Not Cleared
6	Structure Wrap	FOBS-T McDonald	Structure, 1 outbuilding, wrapped & sprinklered.	36° 02.25961057' N	118° 19.90332239' W	Repair Needed		2020-09-04 23:03	Not Cleared
7	Structure Wrap			36° 11.20278019' N	118° 34.26617450' W	Repair Needed			Not Cleared
8	Dozer Push			36° 10.71167697' N	118° 32.09792037' W	Unknown			Not Cleared
9	Dozer Push			36° 10.83780283' N	118° 32.37839051' W	Unknown			Not Cleared
10	Dozer Push			36° 10.79111227' N	118° 32.54060043' W	Unknown			Not Cleared
11	Dozer Push			36° 10.92498555' N	118° 30.84629264' W	Unknown			Not Cleared
12	Dozer Push			36° 11.35058166' N	118° 18.79516610' W	Unknown			Not Cleared
13	Dozer Push			36° 08.12790752' N	118° 17.98557976' W	Unknown			Not Cleared
14	Dozer Push			36° 07.89194517' N	118° 18.20178768' W	Unknown			Not Cleared
15	Dozer Push			36° 07.90770001' N	118° 19.25211695' W	Unknown			Not Cleared
16	Dozer Push	Bates	Large clearing for parking	36° 07.89518904' N	118° 18.20030413' W	Unknown			Not Cleared
17	Dozer Push	FOBS Dockins	skidder push	36° 09.28763021' N	118° 18.15782291' W	Unknown			Not Cleared
18	Dozer Push			36° 07.61281529' N	118° 18.40789193' W	Unknown			Not Cleared
19	Dozer Push			36° 07.82522864' N	118° 18.30567969' W	Unknown			Not Cleared
20	Dozer Push			36° 07.84991671' N	118° 18.40590042' W	Unknown			Not Cleared
21	Dozer Push	Bates	Large pad for engines	36° 08.12004695' N	118° 19.41908647' W	Unknown			Not Cleared
22	Dozer Push			36° 08.06965246' N	118° 19.30818881' W	Unknown			Not Cleared
23	Dozer Push			36° 07.79883301' N	118° 19.58730003' W	Unknown			Not Cleared
24	Dozer Push	FOBS Bates	Dozer pushed out large area	36° 05.03542531' N	118° 29.85186028' W	Unknown			Not Cleared
25	Dozer Push	FOBS Bates	Large pushed out area around stacked dead and	36° 04.96461244' N	118° 29.74900928' W	Unknown			Not Cleared
26	Fence - Cut/Damaged	FOBS Bates	Private fence cut	35° 59.71545820' N	118° 31.44729016' W	Repair Needed			Not Cleared
27	Dozer Push	FOBS Bates	Heavy timber push to the west of dozer line	36° 07.99406262' N	118° 36.82595740' W	Repair Needed			Not Cleared
28	Fence - Cut/Damaged	FOBS Bates	Cut private fence	36° 08.52285107' N	118° 37.49920863' W	Repair Needed			Not Cleared
29	Dozer Push	FOBS Bates	Large pushed out area	36° 06.19516554' N	118° 37.48214481' W	Repair Needed			Not Cleared
30	Dozer Push	FOBS Bates	200' x 200' pushed clean	36° 06.19016657' N	118° 38.04135517' W	Repair Needed			Not Cleared
31	Dozer Push	FOBS Bates	100' x 200' clearing pushed	36° 05.89033165' N	118° 38.76636635' W	Repair Needed			Not Cleared
32	Dozer Push	FOBS Bates	200' x 400' clearing pushed out	36° 06.37011352' N	118° 41.74242991' W	Repair Needed			Not Cleared
33	Dozer Push		1 blade wide	36° 07.68894030' N	118° 18.32943790' W	Unknown			Not Cleared
34	Repair Point	REAF Archer	Drainage impacted by dozer line heading North of	36° 07.92313004' N	118° 17.84416396' W	Repair Needed			Not Cleared
35	Repair Point	REAF Archer	Dozerline heavily impacted intermittent stream.	36° 07.85378233' N	118° 18.27270182' W	Repair Needed			Not Cleared
36	Fence - Cut/Damaged			36° 10.11917938' N	118° 42.28297560' W	Repair Needed			Not Cleared
37	Repair Point	Ingstad	Down Powerlines	36° 11.01999523' N	118° 41.35529277' W	Repair Needed			Not Cleared
38	Repair Point			36° 11.29627364' N	118° 40.45653867' W	Repair Needed			Not Cleared
39	Repair Point	Ingstad	Down Powerlines	36° 09.68534893' N	118° 37.14967070' W	Repair Needed			Not Cleared
40	Stream Crossing	Ingstad	Water Crossing, Type 3, Hardline	36° 11.29928804' N	118° 40.23528956' W	Repair Needed			Not Cleared
41	Repair Point	Ingstad	SR - Water Bars	36° 08.64961214' N	118° 36.99994723' W	Repair Needed			Not Cleared
42	Fence - Cut/Damaged		Repair fence. Active grazing area	36° 24.45908474' N	118° 49.70580711' W	Repair Needed			Not Cleared
43	Culvert		Drainage blocked by dozer bypass of cattle guard	36° 21.72593780' N	118° 50.71699051' W	Repair Needed			Not Cleared
44	Repair Point	Ingstad/Horwedel	dozer line water bars needed	36° 08.05470660' N	118° 36.85944657' W	Repair Needed			Not Cleared
45	Repair Point	Ingstad/Horwedel	multiple snags on dozer line	36° 07.82197919' N	118° 37.09439700' W	Repair Needed			Not Cleared
46	Repair Point	Ingstad/Horwedel	needs water bars	36° 07.81879558' N	118° 37.05865078' W	Repair Needed			Not Cleared
47	Repair Point	Ingstad/Horwedel	slash pile needs dispersing	36° 07.81853282' N	118° 37.02752937' W	Repair Needed			Not Cleared
48	Repair Point	Ingstad/Horwedel	hiking trail needs repair	36° 07.78123621' N	118° 36.9360518' W	Repair Needed			Not Cleared
49	Repair Point	Ingstad/Horwedel	dozer line water bars needed	36° 08.05470660' N	118° 36.85944657' W	Repair Needed			Not Cleared
50	Repair Point	Ingstad/Horwedel	water bars needed	36° 08.53968722' N	118° 37.15324981' W	Repair Needed			Not Cleared
51	Repair Point		Down Powerlines	36° 11.07670711' N	118° 38.07342733' W	Repair Needed			Not Cleared
52	Fence - Cut/Damaged	Ingstad/Horwedel	gate needs repair	36° 10.15714082' N	118° 37.87865159' W	Repair Needed			Not Cleared
53	Fence - Cut/Damaged	Ingstad/Horwedel	gate needs repair	36° 11.38761058' N	118° 37.93355101' W	Repair Needed			Not Cleared
54	Fence - Cut/Damaged	Ingstad/Horwedel	damaged fence - fox farm rd	36° 11.24518070' N	118° 37.99361859' W	Repair Needed			Not Cleared
55	Fence - Cut/Damaged	Beidl	Fence Cut	36° 20.20304324' N	118° 50.32800646' W	Repair Needed	3 strand barbed wire and t-post fence line.		Cleared for Repair
56	Fence - Cut/Damaged	Beidl	Wooden and Wire Fence by Rental Cabin	36° 18.03915936' N	118° 48.61251091' W	Repair Needed			Cleared for Repair
57	Repair Point	Beidl	Range Gate	36° 24.76808834' N	118° 50.15211728' W	Repair Needed			Cleared for Operations
58	Repair Point	Beidl	Natural Mineral Lick	36° 25.08930822' N	118° 50.48867043' W	Repair Needed			Not Cleared
59	Repair Point	Beidl	Pre-existing Road Turns Off Ridge Top Here	36° 25.88332051' N	118° 51.10727228' W	Repair Needed			Not Cleared
60	Repair Point	Beidl	likely on another old line or road	36° 25.90635920' N	118° 51.16871809' W	Repair Needed			Not Cleared
61	Repair Point	Beidl	old road or line	36° 25.93643599' N	118° 51.25666934' W	Repair Needed			Not Cleared
62	Repair Point	Beidl	Good Hope Mines	36° 19.56570270' N	118° 48.94670069' W	No Repair Needed	Information only point. Delete from repair		Not Cleared
63	Repair Point	Beidl		36° 19.29671388' N	118° 48.75033954' W	Repair Needed	Safety zone. Excavator work.		Cleared for Repair
64	Repair Point	Beidl	Safety Zone	36° 19.04481629' N	118° 48.83518393' W	Repair Needed	Excavator work.		Cleared for Repair
65	Repair Point	Beidl	Broken Gate	36° 19.19291491' N	118° 50.10521046' W	Repair Needed			Not Cleared
66	Repair Point	Beidl	Dozer Parking	36° 19.21769881' N	118° 49.76728882' W	Repair Needed	Small dozer parking/staging area. Knock down berms and rake out tracks. Hand crew.		Not Cleared
67	Repair Point	Beidl	Damaged Gate	36° 18.31164330' N	118° 48.71780603' W	Repair Needed	Damaged wooden gate made of 4x4, 2x6 and 1x6 milled lumber. Hand crew work.		Cleared for Repair
68	Repair Point	Beidl	Damaged Culvert	36° 18.24823337' N	118° 48.79607960' W	Repair Needed	Damaged pvc culvert in road/dozer line - approximately 10" in diameter. Hand crew		Cleared for Repair
69	Repair Point	Beidl	Irrigation Line	36° 17.99345048' N	118° 48.72990886' W	Repair Needed	Damaged irrigation line. Schedule 40 PVC 3/4 inch. Hand crew.		Cleared for Repair
70	Repair Point	Beidl	Power Box	36° 17.97563701' N	118° 48.72352680' W	Repair Needed	Damaged SCE buried power box - plastic lid completely smashed. There is also a broken schedule 40 PVC irrigation 2.5" main line nearby. Power company and hand crew.		Cleared for Repair
71	Repair Point	Beidl	Power Box	36° 17.99527759' N	118° 48.68545860' W	Repair Needed	Damaged SCE buried power box. Ground line cut and exposed. Power company. 4889 on lock box at green gate. DINS collected data on the burnt trailers. Local says		Cleared for Repair
72	Repair Point	Beidl	Burnt Structures	36° 17.21758177' N	118° 48.29506723' W	Other - See Comments	owner was Caleb ?? who died about three		Not Cleared
73	Fence - Cut/Damaged	Beidl		36° 19.21982836' N	118° 49.15008589' W	Repair Needed	Three strand barbed wire and wood/t-posts.		Cleared for Repair
74	Repair Point		Footbridge damaged by dozer	36° 26.80339714' N	118° 51.55268800' W	Repair Needed			Cleared for Operations
75	Dozer Push	Elissa Kretsch	Single blade re opening old road	36° 23.86617712' N	118° 46.46383016' W	Repair Needed			Not Cleared
76	Culvert	Beidl		36° 19.19265597' N	118° 49.00720794' W	Repair Needed	Remove berms - make sure culvert not		Cleared for Repair
77	Culvert	Beidl	Culvert	36° 19.19401130' N	118° 49.10936493' W	Repair Needed	Remove berms - make sure culvert not		Cleared for Repair
78	Repair Point	Ingstad	culvert repair	36° 04.67418457' N	118° 46.25506472' W	Repair Needed		2020-09-27 19:04	Not Cleared
79	Repair Point	Ingstad	culvert repair	36° 04.89424661' N	118° 46.47846042' W	Repair Needed		2020-09-27 19:04	Not Cleared
80	Repair Point	Ingstad	culvert repair	36° 05.06272965' N	118° 46.64979111' W	Repair Needed		2020-09-27 19:07	Not Cleared
81	Fence - Cut/Damaged	Ingstad	fence repair	36° 04.66947960' N	118° 45.76163738' W	Repair Needed		2020-09-27 19:08	Not Cleared
82	Fence - Cut/Damaged	Ingstad	fence repair	36° 04.79098007' N	118° 45.73733460' W	Repair Needed			Not Cleared
83	Fence - Cut/Damaged	Ingstad	fence repair	36° 04.97629779' N	118° 45.25746213' W	Repair Needed			Not Cleared
84	Repair Point	Ingstad/Horwedel	water bars needed	36° 08.47424571' N	118° 37.21647830' W	Repair Needed			Not Cleared
85	Repair Point			36° 09.60940616' N	118° 37.03802156' W	Repair Needed			Not Cleared
86	Repair Point	Ingstad/Horwedel	water bars needed	36° 09.82950514' N	118° 37.65881116' W	Repair Needed			Not Cleared
87	Repair Point	Ingstad	SR - Water Bars	36° 07.77617355' N	118° 36.97818004' W	Repair Needed		2020-09-27 19:15	Not Cleared
88	Water Development or Draft	Ingstad	drafting site	36° 11.34063125' N	118° 39.99676083' W	Repair Needed		2020-09-27 19:20	Not Cleared
89	Fence - Cut/Damaged	Fobs Ingstad	25 ft, 4 strand, 1 t post	36° 12.53453048' N	118° 44.79072158' W	Repair Needed			Not Cleared
90	Repair Point	Wingate/Gern	Log deck near Giant Sequoia	36° 06.90520326' N	118° 38.14903229' W	Repair Needed	Use excavator to pull cut trees back on line with minimal ground disturbance near base of		Not Cleared
91	Stream Crossing	Wingate		36° 07.44180382' N	118° 37.40418809' W	Repair Needed	Dig out stream crossing		Not Cleared
92	Stream Crossing	READ Gern/Wingate	Blocked Drainage	36° 07.45247617' N	118° 37.34402945' W	Repair Needed	Dig out blocked drainage channel		Not Cleared
93	Stream Crossing	READ Gern/Wingate	Blocked Drainage	36° 07.42986517' N	118° 37.41251124' W	Repair Needed	Dig out drainage channel, pull out logs		Not Cleared
94	Stream Crossing	READ Gern/Wingate	Drainage blocked	36° 07.49245534' N	118° 37.46207851' W	Repair Needed	Clear inlet and outlet		Not Cleared
95	Stream Crossing	READ Gern/Wingate	Blocked Drainage	36° 07.69904749' N	118° 37.57148747' W	Repair Needed	Dig out material blocking drainage, remove		Not Cleared
96	Stream Crossing	READ Gern/Wingate	Blocked Drainage	36° 07.81300278' N	118° 37.68671512' W	Repair Needed	Remove material blocking drainage		Not Cleared
97	Stream Crossing	READ Gern/Wingate	Blocked Drainage	36° 07.82798713' N	118° 37.79803521' W	Repair Needed	Remove material blocking drainage		Not Cleared
98	Stream Crossing	Beidl	Hand Line	36° 16.29277728' N	118° 45.28456168' W	Repair Needed	Delete me. Should be repair point instead of stream crossing.		Cleared for Repair
99	Repair Point	Beidl	Broken Irrigation Lines	36° 16.57132378' N	118° 46.16581821' W	Repair Needed	Broken PVC 1" pipe and flexible 1/2" tubing at		Cleared for Repair
100	Repair Point	Beidl	Hand Line	36° 16.28924405' N	118° 45.28386397' W	Repair Needed	two locations across driveway used as fire		Cleared for Repair
101	Repair Point	Beidl	Log Pile	36° 17.927900					