



Structure ID	Comments	Latitude	Longitude
7	Lookout?	36° 27.78010638' N	118° 38.21330102' W
10	5 Structures with metal roof	36° 27.94219076' N	118° 38.63571573' W
34	LARGE wood shake 3000sq foot house with guest house. Hydrant at east side of main house, roof sprinklered	36° 27.55477381' N	118° 39.16703483' W
35	good access, metal roof structure with LPG.	36° 27.93408354' N	118° 38.90338892' W
36	Cabin #107 metal roof cabin with good clearance. LPG to front of residence	36° 27.92633470' N	118° 38.88391417' W
37	Cabin #104 metal roof wood structure. Wood piles to front of residence. Good clearance	36° 27.89960778' N	118° 38.87228441' W
38	Cabin #105 with wood roof. good clearance. hose bib. Defensible	36° 27.91263271' N	118° 38.88330945' W
39	Cabin #72 metal roof log cabin with LPG to front. defensible space around property. wood pile under deck	36° 27.92665168' N	118° 38.87593443' W
40	Green metal roof structure with good clearance. Difficult engine access	36° 27.93778075' N	118° 38.87479577' W
73	#102&103. Metal roof with red siding. Type 6 access. No prep necessary. Residents home but are going to evacuate. LPG tank on N and SW side of property.	36° 27.89387580' N	118° 38.88551961' W
74	#100. Blue metal roof with wood siding. Type 6 access. Good clearance. LPG on north west side of property. Multiple hose bibs. Shed on north side.	36° 27.91340572' N	118° 38.84356286' W
75	#97. Homer cabin. Metal roof with wood siding. Good clearance, no prep needed. Wood pile and LPG tank on west side of property.	36° 27.90598747' N	118° 38.80235644' W
76	#98. Metal roof with brown siding. Deck under construction. Type 6 access. Good clearance. LPG tank on south side of property. Wood pile on east side.	36° 27.91457244' N	118° 38.80767710' W
85	Silver City resort. 10 cabins and store accessed from wrap around street. Two (2) 2000 gallon water tanks on E side of store.	36° 28.02107263' N	118° 38.83031429' W
86	large metal roof cabin. access from resort. LPG tank on site. Wood pile. Has defensible space	36° 28.06910096' N	118° 38.85435552' W
87	Sawtooth cabin. metal roof. water source to front of property. defensible space provided. Access from resort	36° 28.06921697' N	118° 38.90117168' W
88	white chief cabin. access from resort loop. metal roof structure w/large defensible space. water source at sawtooth cabin	36° 28.07350672' N	118° 38.90849448' W
89	Florence peak cabin. Metal roof structure w/access from resort. water source to front. good defensible space	36° 28.02400979' N	118° 38.91871592' W
90	Cabins #94-96. wood roof structures with good clearance, water source near by from hydrant	36° 27.90681060' N	118° 38.74312784' W
91	Three (3) structures with metal roofs. wood pile adjacent to house. access from road. hose bib to front of house.	36° 27.92646367' N	118° 38.74803385' W
92	Cabin # 92 with three structures. wood roof. hose bib at front of main house. LPG tank to the rear. defensible space. access from the road.	36° 27.95677937' N	118° 38.74427412' W
93	Cabin # 92. metal roof structure. LPG tank at front of house. hose bib. Good access. defensible space	36° 27.95529847' N	118° 38.74355511' W
94	Cabin # 90. metal roof structure with back house. LPG tank to south of house. wood pile against deck and larchwood pile 50 R to the west of house.	36° 27.96859417' N	118° 38.74980747' W
95	Cabin # 89. metal roof structure with wood deck. LPG tank to rear. wood pile to rear. Metal on rear structure. good dispensable space. hose bib in front. access off road	36° 27.98411390' N	118° 38.76159076' W
96	Cabin #78. metal roof structure with wood deck. LPG tank to south. needs clearing around house.	36° 27.92921441' N	118° 38.78856930' W
97	Cabin #81. metal roof structure. wood pile to rear. LPG tank in rear. good clearance.	36° 27.95139668' N	118° 38.79773225' W
98	Cabin #70. metal roof structure (green building). good clearance around water source to front LPG tank to the north. Wood pile to North.	36° 27.97817801' N	118° 38.85316060' W
99	Cabin #74 with red metal roof and wood shake siding. good clearance around structure. water source to front	36° 27.97473962' N	118° 38.86741757' W
100	Cabin #110. Metal roof. Access off main road. no prep needed	36° 27.98521266' N	118° 38.91781862' W
101	Cabin #112. Three metal roof structures with wood siding. Needs prep work. Access off of main road	36° 27.97863696' N	118° 38.94808874' W
102	Cabin #116. Bow legged bunch cabin with access off main road	36° 28.04795933' N	118° 38.99562613' W
103	Cabin #1. Red metal roof. LPG to front. good clearance with access off main road.	36° 28.00130022' N	118° 39.14383881' W
104	#2 wood shake roof structure	36° 28.01579607' N	118° 39.15113448' W
105	#3 three structures, wood shake roof needs prep around house. good access from main road	36° 28.01265232' N	118° 39.15487708' W
106	#5 wood roof two structures access shared with #4. LPG to front	36° 27.99558869' N	118° 39.17396980' W
107	#83. Blue metal roof with grey siding. Good clearance no prep necessary. Stand alone. Wood pile to north side of property.	36° 27.92618890' N	118° 38.80766900' W
108	#84. Green metal roof with wood siding, green door/window shutters. Good clearance. Building material stacked on and blow deck. LPG tank on NW side. Wood pile beside deck. Nees	36° 27.93196437' N	118° 38.79957119' W
109	#85. Brown metal roof with green siding. Good clearance. Access for type 6. LPG tank on west side of structure. Wood pile on north side. Stand alone.	36° 27.94555149' N	118° 38.79967426' W
110	#79. Metal roof with wood siding. Trees close to home. poor clearance. LPG tank on west side of structure. Wood piles on all sides.	36° 27.96350416' N	118° 38.79996235' W
111	#75. Metal roof with wood siding. Type 6 access. Good clearance. Water source to front. LPG tank on east side of structure.	36° 27.92266072' N	118° 38.83876780' W
112	#69. Metal roof with vinyl siding. Type 6 access. Good clearance. Wood pile below structure on south side.	36° 27.96898379' N	118° 38.85021279' W
113	Metal roof with wood siding and green front door. Poor clearance. Type 6 access. Hydrant to west side of property.	36° 27.97140837' N	118° 38.83211350' W
114	#67. Under construction. No siding as of 10/9. Water source 100' to west of structure. Needs prep. Type 3 or 6 access.	36° 27.97851976' N	118° 38.8894872' W
115	#62. Brown metal roof with green siding. Construction materials on south side of structure. Needs prep. Type 6 access. LPG 50' to south of structure.	36° 27.95947443' N	118° 38.91416080' W
116	#66. Metal roof with green siding. Poor access. Construction materials on and below deck. Needs prep. Wood piles on all sides of structure. LPG tank to NW 30' from structure.	36° 27.94330008' N	118° 38.90317727' W
117	#65. Brown metal roof with light green siding. Poor access. Needs prep. Pine needles on and around structure. LPG tank and welding tanks to north of structure.	36° 27.93483331' N	118° 38.91586885' W
118	#64. Blue metal roof with wood siding type 6 access. Well manicured. Poor tree clearance. LPG tank to NE side of structure, 30' away.	36° 27.94524626' N	118° 38.93201844' W
119	#60. Green metal roof with wood siding. Type 3 or 6 access. Good clearance. Construction materials below home and deck. LPG tanks to NW side of property 40' away.	36° 27.98923947' N	118° 38.95160675' W
120	#59. Brown metal roof with brown siding. Type 6 access. Great clearance. Stand alone property. LPG tank to NE side 40' away.	36° 27.99643008' N	118° 38.97458281' W
121	#7. Shake shingle roof with green siding. Type 3 or 6 access. Needs prep. Needle cast on roof and around property. LPG tank on west side of structure.	36° 27.94984631' N	118° 39.30090654' W
122	#4. Wood shake roof with maroon siding. Type 3 or 6 access. Needs prep. Needle cast on roof and deck. Good clearance. LPG tank to South of property.	36° 27.94333999' N	118° 39.33937971' W
123	#6. Metal roof with green siding. Type 3 or 6 access. Poor tree clearance. No prep necessary. 1 out building to south. LPG on west side of property.	36° 27.90672221' N	118° 39.34007672' W

- Structure
- TRA
- Trail
- Stream/River
- Road
- Sequoia NP Sequoia Groves

# Silver City Structure Defense

## SQF Complex

### CA-SQF-002622

1:2,000

Map Updated: 10/20/2020 5:57