



NAD83 UTM 11N
 Prepared by: CAIMT12 9/6/2021 22:35

<ul style="list-style-type: none"> Check Point Dip Site Mobile Retardant Base Helibase Sling Site Division Break Branch Break Incident Command Post Drop Point Camp Value at Risk Other Landmark 	<ul style="list-style-type: none"> Gate Structure Wrap Stream Crossing Road Repair Resource Location Repair Point Fence - Cut/Damaged Repair Status Point Completed - Inspected In Use - Fire Management Repeater Safety Zone Hazard Completed Dozer Line 	<ul style="list-style-type: none"> H - Completed Hand Line M - Completed Mixed Construction Line R - Completed Road as Line Access or Improved Road Repair Line Fire Edge Contained Line Repair Status Point Completed - Inspected In Use - Fire Management Completed - Ready for Inspection In Progress Repair Needed No Repair Needed Other - See Comments Unknown Forest Service Land Bureau of Land Management Lands Private; Local Government; Undesignated 	<ul style="list-style-type: none"> Other - See Comments Unknown Completed - Inspected In Use - Fire Management Completed - Ready for Inspection In Progress Repair Needed No Repair Needed Other - See Comments Unknown Forest Service Land Bureau of Land Management Lands Private; Local Government; Undesignated
---	---	---	--

Suppression Repair

French

CA-CND-002796

9/07/2021



French
 CA-CND-002796
Repair
 9/07/2021