



FeatureCategory	Comments	RepairStatus	RepairComments	LengthFeet	LineWidthFeet	ArchClearance	LandOwner
Completed Dozer Line	READ Quan notes. dozerline off forest land; along road	Repair Needed	Pull Berms. Spread light slash over line.			Not Cleared	
Completed Dozer Line	Surveyed by READ Quan. Tracked by Dozer along road	No Repair Needed	Tracked by Dozer only along road. Minimal impact			Not Cleared	
Completed Hand Line		Unknown				Not Cleared	
Completed Hand Line		Unknown				Not Cleared	

FeatureCategory	Label	Comments	LatWGS84_DDM	LongWGS84_DDM	RepairStatus	RepairComments
Dip Site	Solar Dip		33° 26.790' N	117° 20.361' W	Unknown	
Dip Site	Stable Dip		33° 29.490' N	117° 22.111' W	Unknown	
Dozer Push		READ Quan notes. Dozer push in stream area	33° 29.435' N	117° 22.249' W	Unknown	
Drop Point	Staging	Confirm Location	33° 29.929' N	117° 21.370' W	Unknown	
Other	Entry Road	READ Quan notes. Entry road to Miller Mountain	33° 29.303' N	117° 21.818' W	No Repair Needed	entry to Miller Mtn. B. santarosae population
Other	Aerial Retardant Report Location	Lead READ will report	33° 28.943' N	117° 23.138' W	No Repair Needed	
Repair Point	Handline Repair	Handline intersects with Forest Road 8S02	33° 29.099' N	117° 22.720' W	Repair Needed	not repaired; cover w brush and improve drainage. needs repair; block entrance, knock berms down
Repair Point	Handline Repair		33° 29.078' N	117° 22.488' W	Repair Needed	READ Quan Recommended Repair
Repair Point	Dozer Line	Steep Dozerline approx. 30'. Needs water management feature.	33° 29.488' N	117° 22.251' W	Repair Needed	Needs water bars. (Soft soil). Hand Crew needed.

Repair Status Point

- Green circle: Completed - Inspected
- Yellow circle: In Use - Fire Management
- Red circle: Completed - Ready for Inspection
- Yellow circle: In Progress
- Red circle: Repair Needed
- Blue circle: No Repair Needed
- Grey circle: Other - See Comments
- Purple circle: Unknown

Repair Status Line

- Green line: Completed - Inspected
- Yellow line: In Use - Fire Management
- Red line: Completed - Ready for Inspection
- Yellow line: In Progress
- Red line: Repair Needed
- Blue line: No Repair Needed
- Grey line: Other - See Comments
- Purple line: Unknown
- Blue line: TES_plants_Chaparral_08282021
- Red line: FireRetardantAvoidance_Terrestrial

Datum: NAD 1983 UTM Zone 11N