







Point

					,
Stading Area	Label	Comments Darking area	Kepairstatus	Repair Comments Dozer pilsh 150' v 50'	LandOwner
Staging Area		Yellowstone Lodge; misc pump kit supplies	Unknown	page, 100 x 00	101
Value at Risk		Upper Still water Wooden foot bridge	Unknown	Wrapped with sprinkler	102
Value at Risk Water Source		Concrete and steel bridge below dam	Unknown		103
Water Source		Moon Lake Boat Ramp	Unknown		105
Water Source			Unknown		106
Water Source			Unknown		107
Water Source		2 pumpkins: 1500 & 1800 gal	Unknown		109
Water Source		Oreek	Unknown		110
Water Source		Hells Cýn. Cr. & Petty Mtn. Rd	Unknown		111
			Unknown		112
Drop Point	DP-10		No Repair Needed		113
	Yellowstone Spike		Unknown		133
oint	DP-71		Unknown		134
	DP-70		Unknown		135
	DP-68		Unknown		137
oint	DP-64		Unknown		138
	20	Wood bridge need sprinkles underneath	Unknown		46
	DP-21 DP-2	IMay need to move	Unknown		47
Drop Point	DP-23	י ט טעמוט ו	Unknown		49
	DP-50	Junction of Bear Wallow and Moon Lake Rd	Unknown		50
	DP-48		Unknown		51
	DP-90		Unknown		52
	DP-24		Unknown		53
Drop Point	DP-46		Unknown		54 55
	DF-32		Unknown		56
Drop Point	DP-61		Unknown		57
	DP-81		Unknown		58
	DP-1		Unknown		09
Drop Point	DP-42 DP-44		Unknown		6.I 62
	DP-65	Div R	Unknown		63
	DP-64	Parking and pumpkins	Unknown		99
	DP-82	Center of Long Park	Unknown		29
Drop Point	DP-83	059 trail	Unknown		68
	DP-62 H-1		Unknown		69 73
	H-2		Unknown		74
	H 4 H		Unknown		75
	H-5		Unknown		76
	H-10	7,600 ft	Unknown		22
	H-15	10,300 ft	Unknown		78
Helispot	H-18 H-7		Unknown		80
	F.3		Unknown		81
	H-13		Unknown		82
	H-12	C C C	Unknown		83
Helispot	H-14	1ype 2 & 3	Unknown		84 86
	COW - 65' AGL		Unknown		87
Repair Point		Dozer push through dry creek bed	Repair Needed	Clean out creek bottom,	88
Repair Point		Koad sign post burned up. Sign is still here, mostly undamaged.	Kepair Needed		88 80
3110		Road sign post burned up. Road sign burned, unreadable.			
Repair Point		Needs replaced.	Repair Needed		91
Repair Point		Road sign post burned up. Sign present and unharmed.	Repair Needed		92
Repair Point		Burned sign post. Sign down, blistered slightly, peppered with buckshot.	Repair Needed		93
		Burned signpost. Uncertain what, if anything,			
Repair Point		was posted on this signpost.	Unknown		94
Repair Point		Koad sign. Still standing, but chared and crackled. Stillwater Repeater	Kepair Needed Unknown		96 96
	CMD-8		Unknown		97
Repeater	Repeater	: : : : : : : : : : : : : : : : : : : :	Unknown		98
Sling Site		Possible Div B sling site	Unknown		99

		Line	1		
FeatureCategory	Comments	RepairStatus	RepairComments	LengthFeet	LandOwner
Completed Dozer Line		Unknown		20076	1
Completed Dozer Line	Improved ATV Trail	Unknown		5114	10
Completed Dozer Line	·	Unknown	Berms & slash	722	11
Completed Hand Line		Repair Needed	Waterbars and slash pulling needed	225	115
Fence		Repair Needed	Wooden fence posts replacement from burnout operation, 4 strand barbed wire, 80 wooden posts burned	1451	116
Fence		Repair Needed	4 strand barbed wire fence. Wooden posts intermixed with metal T posts, burned from burnout operation. 10 wooden posts	102	117
Fence		Repair Needed	BIA/FS boundary fence, wooden posts burned from burnout operation. Wooden posts intermixed with metal T posts. 97 posts burned, 30" hinged joint fence with 1 strand barbed wire on top and 1 strand on bottom.	3000	118
Fence		Repair Needed	BIA FS boundary, 58 wooden posts need replacement from burnout operation. Fence is a 6 strand barbed wire fence with very few metal Tposts mixed in (1/10 metal t posts).	856	119
Completed Hand Line		Repair Needed		553	12
Access or Improved Road	Existing 2-track access road, minor dozer work to facilitate access	No Repair Needed	No impacts, no repair needed	7509	122
Completed Dozer Line	Road prep on existing road	Unknown	Minimal slash , steep section needs water bars and pull vegetation to stop OHV intrusion	13481	123
Fence	Hazards include Ponderosa snag patch and stump holes	Repair Needed	FS/BIA boundary fence damaged during burnout operation. Wooden posts intermixed with metal t posts. 100 wooden posts burned. 32" sheep fence (jointed hinged fence) with 1 strand of barbed wire on top.	1724	123
Access or Improved Road	Existing 2-track access road, minor dozer work to facilitate access	No Repair Needed	No impacts, no repair needed	8304	124
Fence	Hazards include Ponderosa snag patch and stump holes	Repair Needed	4 strand barbed wire headed west. Mostly wooden posts, all burned, unsure how far west the burnout operation continued. 25 posts in this small section. Recommend total new fence.	359	124
Access or Improved Road	Access road	No Repair Needed	No impacts, no repair needed	1680	126
Access or Improved Road	Access road	No Repair Needed	No impacts, no repair needed	4166	127
Access or Improved Road	Access road	No Repair Needed	No impacts, no repair needed	14097	128
Access or Improved Road	Access road	No Repair Needed		2192	129
Completed Hand Line		Repair Needed		72	13
Access or Improved Road	Access Road	No Repair Needed	No impacts, no repair needed	9167	130
Access or Improved Road	Access road	No Repair Needed	No impacts, no repair needed	1893	131
Proposed Burnout	Cow Park Line	Unknown		2578	131
Completed Hand Line		Repair Needed		209	14
Completed Hand Line		Repair Needed		344	15
Completed Hand Line	060 trail, line prep. Abandoned line, ties into meadow & 227 road	Unknown	Slash	1153	18
Other	Contingency: road as line	Unknown		4159	19
Completed Dozer Line		Unknown		6659	2
Other	Contingency: trail that is being prepped	Unknown		2520	20
Access or Improved Road	Existing road, not fire line, for transportation purposes	No Repair Needed		4499	21
Access or Improved Road	Existing road, not fire line, for transportation purposes	No Repair Needed		897	22
Access or Improved Road	Existing road, not fire line, for transportation/access purposes	Unknown		9180	23
Access or Improved Road	Existing 2-track access road, minor dozer work to facilitate access	Repair Needed		10532	24
Access or Improved Road	Test	Unknown		12735	25
Access or Improved Road		Unknown		8042	26
Access or Improved Road	Existing 2-track access road, minor dozer work to facilitate access	No Repair Needed		1553	29
Completed Dozer Line		Unknown	Berms & slash	3571	3
Active Burnout		Unknown		4684	30
Other	Contingency: long park meadow	Unknown		7393	31
Other	Contingency: road to be prepped	Unknown		4589	32
Other	Contingency	Unknown		1436	33
Other	Contingency: saw line, not yet done	Unknown		5662	34
Other Other	trail to be prepped for potential burn Downed and felled trees near road can be chipped or bucked for fire wood.	Unknown Repair Needed		12666 4622	35 36
Planned Fire Line	Additional felling may be required.	·		9098	37
		Unknown			_
Planned Fire Line Planned Fire Line		Unknown		14606 5133	38
	Dozor hoded reed	Unknown	Minimal berms, minimal water bars	8231	39
Completed Dozer Line Road as Completed Line	Dozer boded road	Unknown Unknown	willilmar perms, minimar water pars	18737	40
Road as Completed Line Road as Completed Line	Div R road prep	Unknown	Slash	3216	40
Road as Completed Line Road as Completed Line	Road prep	Unknown	Slash, chipper and scatter	668	42
Road as Completed Line Road as Completed Line	Road prep	Unknown	orasii, oripper anu scatter	5726	43
Road as Completed Line Road as Completed Line	Abandoned road prep line	Unknown	Slash	2611	43
Road as Completed Line Road as Completed Line	Road prep	Unknown	Slash	5091	45
Completed Dozer Line	Dozer bladed Ross	Unknown	Short steep sections need water bars, 1 short errant steep section, minor berms	11644	5
	DOZCI DIAUCU 11033	Unknown	Short steep sections need water bars, 1 short errant steep section, minor bernis Steep, water bars, berms & slash	2806	6
Completed Linzer Line				2000	U
Completed Dozer Line Completed Dozer Line		Unknown		591	8