



Pine Hollow Fire

Repair Map

AZ-ASD-000595
Aug 7, 2020 appx. 11,405 acres

Repair Status as of August 6, 1900hr

Lat-Long Grid Ticks: 1' minute interval
Map Projection: NAD83 UTM Zone12
Grid Data: Team 6 GIS
Author: alaska
Date: 20200806 10:07:40
File: repair_2020_PineHollow_AZASD000595_Event_ArsPrs_2_5



- Repair Status Line**
- Repair Needed
 - In Progress
 - Completed - Ready for Inspection
 - Completed - Inspected
 - No Repair Needed
 - Unknown
 - Other - See Comments
- Repair Status Point**
- Repair Needed
 - In Progress
 - Completed - Ready for Inspection
 - Completed - Inspected
 - No Repair Needed
 - Unknown
 - Other - See Comments
- Fire Point**
- Drop Point
 - Dip Site
 - Fence - Cut/Damaged
 - Fire Origin
 - Helispot
 - Repeater
 - Water Source
 - Value at Risk
 - Division Break
- Fire Line**
- Contained Line
 - Completed Dozer Line
 - Road as Completed Line
 - Aerial Hazard
 - Aerial Redundant Drop
 - Repair Line

FC Line Type	Label	Repair Status	Repair Comments	Line Width Feet	Length Feet	Line Date Time	Comments
Completed Dozer Line	DL-10	Completed - Inspected		15	1254	7/29/2020 12:00:00	
Completed Dozer Line	DL-11	Completed - Inspected	10-15 ft wide, 1-2 ft berm	15	7702	7/29/2020 12:00:00	10-15 ft wide 1-2 ft berm
Completed Dozer Line	DL-12	Completed - Inspected		15	1977	7/29/2020 12:00:00	
Completed Dozer Line	DL-13	Completed - Inspected	10-15 ft wide, 1-2 ft berm	15	7331	7/29/2020 12:00:00	
Completed Dozer Line	DL-14	Completed - Inspected	10-15 ft wide, 1-2 ft berm	15	147	7/29/2020 12:00:00	
Completed Dozer Line	DL-15	Completed - Inspected		10	2593	7/30/2020 18:00:00	Single blade dtr line
Completed Dozer Line	DL-16	Completed - Inspected		25	2573	7/30/2020 12:00:00	Road widened with a dozer to 3 blades wide
Completed Dozer Line	DL-17	Completed - Inspected		65	3454	7/31/2020 12:00:00	Dozer line single blade with 50 ft mastication on fire side of line
Completed Dozer Line	DL-20	Completed - Inspected	dozer only, no mastication	15	2573	7/31/2020 12:00:00	dozer only, no mastication
Completed Dozer Line	DL-21	Completed - Inspected	Single blade line	15	3943	7/31/2020 12:00:00	Single blade line
Completed Dozer Line	DL-30	Completed - Inspected		15	8129	7/30/2020 12:00:00	
Repair Line	RP-40	No Repair Needed	pushed out area; repair is part of Mungum operation		839	7/30/2020 12:00:00	outline of pushed out area
Road as Completed Line	RD-10	No Repair Needed	Entire line is on existing roads	100	5230		saw prep complete 50 ft E of road; mastication complete 15 ft E of road; mastication complete 50 ft W of road
Road as Completed Line	RD-11	No Repair Needed	Entire line is on existing roads	100	1824		mastication complete 50 ft E of road; mastication complete 50 ft W of road
Road as Completed Line	RD-12	No Repair Needed	Entire line is on existing roads	100	1450		saw prep 50 ft E of road, mastication 15 ft E of road; mastication complete 50 ft W of road
Road as Completed Line	RD-13	No Repair Needed	Entire line is on existing roads	100	11530		mastication complete 50 ft E of road; mastication complete 50 ft W of road
Road as Completed Line	RD-14	No Repair Needed	Entire line is on existing roads	50	8625		DIV A proposed berm; open grassland east of road did not require saw or mastication prep
Road as Completed Line	RD-15	No Repair Needed		100	3621		Improved rd with 50 ft mastication cut; mastication complete 50 ft W of road
Road as Completed Line	RD-20	No Repair Needed		50	10635		Road improved with dozer; mastication 50 ft E
Road as Completed Line	RD-21	Completed - Inspected		15	6032		dozer open existing two-track
Road as Completed Line	RD-22	Unknown		15	1714		

FeatureCategory	Label	RepairStatus
Dip Site	Paria Dip	Unknown
Dip Site	Pumpkin Dip	Unknown
Dip Site	Reservoir Dip	Unknown
Drop Point	DP-11	Unknown
Drop Point	DP-15	Unknown
Drop Point	DP-25	Unknown
Drop Point	DP-27	Unknown
Drop Point	DP-34	Unknown
Drop Point	DP-35	Unknown
Drop Point	DP-36	Unknown
Drop Point	DP-41	Unknown
Drop Point	DP-45	Unknown
Fence - Cut/Damaged		No Repair Needed
Fence - Cut/Damaged		No Repair Needed
Helibase	Kanab Helibase	Unknown
Incident Command Post	Kanab City Admin ICP	Unknown
Incident Command Post	Pine Hollow ICP	Unknown
Repeater	Buckskin Repeater	Unknown
Repeater	CMD 7	Unknown
Repeater	CMD 8	Unknown
Staging Area	Crew Parking	Unknown
Value at Risk	Catchment	Unknown
Value at Risk	Catchment	Unknown
Value at Risk	Catchment	Unknown
Value at Risk	Catchment	Unknown
Value at Risk	Catchment	Unknown
Value at Risk	Catchment	Unknown
Value at Risk	Catchment	Unknown
Value at Risk	Catchment	Unknown
Value at Risk	Catchment	Unknown
Value at Risk	Coyote Springs Ranch	Unknown
Water Source	Cattle Tank	Unknown
Water Source	Fold-a-tank	Unknown

Sources: Esri, Airbus DS, USGS/NASA, CGIAR, N Robinson, NGAS, NLS, OS, NMA, Geodatasystemen, Rijksinformatie, Geobase, FEMA, Intermap and the GIS user community