



Suppression Repair Overview

Left Fork
UT-DIF-000133
7/7/2022 Day

4,239 acres at 07/05/2022 3:31



Event Point Repair

Repair Status

- In Use - Fire Management
- Needs Assessment
- Repair Needed
- In Progress
- Completed - Ready for Inspection
- Completed - Inspected
- No Repair Needed
- Other - See Comments

Event Line Repair

Repair Status

- In Use - Fire Management
- Needs Assessment
- Repair Needed
- In Progress
- Completed - Ready for Inspection
- Completed - Inspected
- No Repair Needed
- Other - See Comments

Air Operations

- Dip Site
- Heliport
- Sling Site

Assignment Breaks

- Division Break

Logistics

- Medical
- Drop Point

Repair

- Repair Point
- Dozer Push
- Culvert

Communications

- Mobile Weather Unit
- Repeater

Water

- Water Source
- Structures

Ops Completed

- Completed Dozer Line
- Completed Fuel Break
- Completed Hand Line
- Completed Mixed Construction Line
- Completed Road as Line

Reference

- Access or Improved Road
- Fence
- Other

Repair

- Repair Line
- Road Repair

Air Ops

- Retardant Drop

Perimeter Line

- Contained
- Non-MotORIZED Trail

MVUM Roads

- 1 Roads Open to All Vehicles, Yearlong
- 15 Other Public Roads
- Unknown Road
- 1 Basic Custodial Care (CLOSED)

MVUM Trail

- 5 Trails Open to All Vehicles, Yearlong
- 7 Trails Open to Vehicles 50' or Less in Width, Yearlong
- 11 Special Designation, Yearlong

HIFLD Roads

- Paved Roads
- Dirt (Not Paved)
- FireRetardantEIS_WaterBodies
- FireRetardantEIS_Streams
- FireRetardantEIS_Semidw
- Blubber Creek Watershed

NHDFlowline

- Stream/River: Artificial Path
- Stream/River: Intermittent

NHDWaterbody

- Lake / Pond
- Lake / Pond (Intermittent)

CONUS Wetlands

- Freshwater Emergent Wetland
- Freshwater Pond

Surface Ownership

- National Park Service (NPS)
- State
- US Forest Service (USFS)
- Private

Color Country Team 2/7/6/2022 1957
North American 1983 Datum. Lat/Long Grid