


Line Type	Repair Status (Miles)				TOTAL	Percent Complete
	Completed - Inspected	Completed - Ready for Inspection	Repair Needed	Unknown		
Access or Improved Road			7.98		7.98	0%
Completed Dozer Line	1.79	0.67	12.15		14.60	12%
Completed Fuel Break			4.50	2.08	6.58	0%
Completed Hand Line	0.70	0.04	3.54	0.00	4.68	15%
Completed Mixed Construction Line			2.65	0.26	2.91	0%
Completed Plow Line	0.20		0.38		0.59	33%
Completed Road as Line			12.17	0.61	12.78	0%
Fence			0.24		0.24	0%
Repair Line			0.14	0.10	0.23	0%
Road Repair			16.85		16.85	0%
<b>LINE TOTAL</b>	<b>2.59</b>	<b>0.70</b>	<b>61.09</b>	<b>3.05</b>	<b>67.43</b>	<b>4%</b>
<b>Points - 15% Complete</b>						

# SUPPRESSION REPAIR

Day 9/22/2021

**Alder Creek**  
MTBDF-006269  
Alder Creek GIS Acres 35412  
09/21/2021 21:41 MDT  
Acres from IR

**Sand Lake**  
MTBDF-006298  
Sand Lake GIS Acres 228  
09/13/2021 21:09 MDT  
Acres from IR



- Dip Site
- Staging Area
- Road Repair
- Dozer Push
- Water Source
- P - Completed Plow Line
- Helispot
- Lookout
- Resource Location
- Culvert
- R - Completed Road as Line
- Unimproved Landing Area
- Value at Risk
- Clean Up Area
- W/W Completed Dozer Line
- Drop Point
- Landing or Log Deck
- Safety Zone
- Gate
- Hazard
- H - Completed Hand Line
- Camp
- Fence - Cut/Damaged
- M - Completed Mixed Construction Line
- Repair Line
- Repair Status Line
- Repair Needed
- Unknown
- Completed - Inspected
- Completed - Ready for Inspection

