


Line Type	Repair Status (Miles)				TOTAL	Percent Complete
	Completed - Inspected	Completed - Ready for Inspect on	Repair Needed	Unknown		
Access or Improved Road			7.98		7.98	0%
Completed Dozer Line	1.79	0.67	12.15	2.08	14.60	12%
Completed Fuel Break			4.50	2.08	6.58	0%
Completed Hand Line	0.60	0.04	4.04	0.00	4.68	13%
Completed Mixed Construct on Line			2.65	0.26	2.91	0%
Completed Plow Line	0.21		0.38		0.59	35%
Completed Road as Line			12.17	0.61	12.78	0%
Fence			0.24		0.24	0%
Repair Line			0.14	0.10	0.23	0%
Road Repair			16.85		16.85	0%
LINE TOTAL	2.59	0.70	61.09	3.05	67.43	4%
Points - 8% Complete						

SUPPRESSION REPAIR

Day 9/24/2021

Alder Creek
MTBDF-006269
Alder Creek GIS Acres 35412
09/13/2021 21:41 MDT
Acres from IR

Sand Lake
MTBDF-006298
Sand Lake GIS Acres 228
09/13/2021 21:09 MDT
Acres from IR



- Dip Site
- Staging Area
- Road Repair
- Dozer Push
- Water Source
- P 2 Completed Plow Line
- Helispot
- Lookout
- Resource Location
- Clean Up Area
- R 2 Completed Road as Line
- Unimproved Landing Area
- Value at Risk
- Repair Point
- Safety Zone
- Repair Status Line
- Drop Point
- Gate
- Landing or Log Deck
- Hazard
- H 2 Completed Hand Line
- Bridge
- Fence - Cut/Damaged
- M 2 Completed Mixed Construction Line
- Repair Needed
- Unknown

