


Line Type	Repair Status (Miles)				TOTAL	Percent Complete
	Completed - Inspected	Completed - Ready for Inspection	Repair Needed	Unknown		
Access or Improved Road	0.24		3.94		4.18	6%
Completed Dozer Line	1.79	4.08	12.18	0.69	18.74	10%
Completed Fuel Break		0.77	4.04	2.32	7.13	0%
Completed Hand Line	0.74	0.28	2.10	0.13	3.25	23%
Completed Mixed Construction Line		0.26	2.51	1.62	4.38	0%
Completed Plow Line	0.20	0.44	0.38		1.01	19%
Completed Road as Line		0.20	12.15	1.89	14.23	0%
Fence			0.24		0.24	0%
Other		0.20	0.09		0.28	0%
Repair Line			0.14	0.10	0.23	0%
Road Repair			1.36	16.56	17.93	0%
LINE TOTAL	2.96	7.59	54.31	6.75	71.61	4%

SUPPRESSION REPAIR

09/28/2021

Alder Creek
MTBDF-006269
Alder Creek GIS Acres 36,169
09/25/2021 2:05 PM MDT
Acres from IR

Sand Lake
MTBDF-006298
Sand Lake GIS Acres 228
09/13/2021 2:09 PM MDT
Acres from IR



- Dip Site
- Staging Area
- Road Repair
- Dozer Push
- Water Source
- Helispot
- Lookout
- Resource Location
- Culvert
- Completed Plow Line
- Unimproved Landing Area
- Value at Risk
- Repair Point
- Clean Up Area
- Completed Dozer Line
- Drop Point
- Landing or Log Deck
- Safety Zone
- Completed Fuel Break
- Gate
- Hazard
- H - Completed Hand Line
- Bridge
- Fence - Cut/Damaged
- M - Completed Mixed Construction Line
- Fence

- P - Completed Plow Line
- R - Completed Road as Line
- Completed - Ready for Inspection
- Repair Needed
- Unknown
- Other
- Repair Line
- Access or Improved Road Repair Status Line
- Completed - Inspected

