



Line Type	Repair Status (miles)				TOTAL	Percent Complete
	Completed - Inspected	In Progress	Repair Needed	Unknown		
Access or Improved Road	1.76		7.60		9.36	19%
Completed Dozer Line	2.99		7.95		10.94	27%
Completed Fuel Break	17.32		12.08	0.09	29.49	59%
Completed Hand Line	0.78		13.73	0.12	14.63	5%
Completed Mixed Construction Line	0.35		0.53	0.55	1.43	0%
Completed Road as Line	5.90		0.06		6.32	6%
Fence	0.59		1.64		2.24	27%
Repair Line	0.36	8.39	0.43		9.18	4%
Road Repair	0.03	7.37			9.56	0%
<b>LINE TOTAL</b>	<b>24.18</b>	<b>2.15</b>	<b>65.21</b>	<b>1.26</b>	<b>92.80</b>	<b>26%</b>

# SUPPRESSION REPAIR

09/28/2021

**Trail Creek**  
**MTBDF-006272**  
 Trail Creek GIS Area 57,299  
 09/27/2021 10:11 MDJ  
 Acres from TR



0 1 Miles  
 Scale: 1:40,017  
 NAD 1983 UTM Zone 12N

- Dip Site
- Camp
- Bridge
- Landing or Log Deck
- Water Source
- Helispot
- Staging Area
- Water Development or Draft Site
- Fence - Cut/Damaged
- Completed Dozer Line
- Sling Site
- Value at Risk
- Stream Crossing
- Culvert
- Clean Up Area
- Safety Zone
- Unimproved Landing Area
- Other
- Road Repair
- Repair Point
- Gate
- Repair Status Line
- Access or Improved Road
- Completed - Inspected
- In Use - Fire Management
- In Progress
- Repair Needed
- Unknown
- Completed Hand Line
- Completed Mixed Construction Line
- Road Repair

