


Line Type	Repair Status (Miles)				TOTAL	Percent Complete
	Completed - Inspected	Completed - Ready for Inspection	Repair Needed	Unknown		
Access or Improved Road	0.48		0.63	0.05	1.15	41%
Completed Dozer Line	1.08	4.41	17.70	0.47	23.66	5%
Completed Fuel Break		1.72	5.66	0.42	7.80	0%
Completed Hand Line	6.04	2.97	12.84	6.27	28.12	21%
Completed Mixed Construction Line		0.82	1.05	4.55	6.42	0%
Completed Plow Line	0.94		0.20		1.14	82%
Completed Road as Line		0.01	2.97	4.98	7.97	0%
Fence			3.26		3.26	0%
Other		0.25	0.05		0.30	0%
Repair Line			0.35	0.03	0.38	0%
Road Repair		0.07	3.47		3.54	0%
LINE TOTAL	8.54	10.26	48.17	16.78	83.75	10%

SUPPRESSION REPAIR

09/29/2021

Alder Creek
MTBDF-006269
Alder Creek GIS Acres 36,538
09/28/2021 13:49 MDT
Acres from IR

Sand Lake
MTBDF-006298
Sand Lake GIS Acres 228
09/13/2021 21:09 MDT
Acres from IR



- Dip Site
- Staging Area
- Road Repair
- Dozer Push
- Water Source
- Helispot
- Lookout
- Resource Location
- Clean Up Area
- Completed Dozer Line
- Unimproved Landing Area
- Value at Risk
- Repair Point
- Clean Up Area
- Completed Fuel Line
- Drop Point
- Landing or Log Deck
- Safety Zone
- Completed Hand Line
- Gate
- Hazard
- H - Completed Hand Line
- Bridge
- Fence - Cut/Damaged
- P - Completed Plow Line
- R - Completed Road as Line
- Other
- Completed - Ready for Inspection
- Repair Needed
- Unknown
- Completed - Inspected

