


Line Type	Repair Status (Miles)				TOTAL	Percent Complete
	Completed - Inspected	Completed - Ready for Inspection	Repair Needed	Unknown		
Access or Improved Road	0.48		0.63	0.05	1.15	41%
Completed Dozer Line	1.08	4.41	17.70	0.47	23.66	5%
Completed Fuel Break		1.72	5.66	0.42	7.80	0%
Completed Hand Line	6.04	2.97	12.84	6.27	28.12	21%
Completed Mixed Construction Line		0.82	1.05	4.55	6.42	0%
Completed Plow Line	0.94		0.20		1.14	82%
Completed Road as Line		0.01	2.97	4.98	7.97	0%
Fence			3.26		3.26	0%
Other		0.25	0.05		0.30	0%
Repair Line			0.35	0.03	0.38	0%
Road Repair		0.07	3.47		3.54	0%
<b>LINE TOTAL</b>	<b>8.54</b>	<b>10.26</b>	<b>48.17</b>	<b>16.78</b>	<b>83.75</b>	<b>10%</b>

# SUPPRESSION REPAIR

09/29/2021

**Alder Creek**  
MTBDF-006269  
Alder Creek GIS Acres 36,538  
09/28/2021 2:09 MDT  
Acres from IR

**Sand Lake**  
MTBDF-006298  
Sand Lake GIS Acres 228  
09/13/2021 2:09 MDT  
Acres from IR



- Dip Site
- Staging Area
- Road Repair
- Dozer Push
- Water Source
- Helispot
- Lookout
- Resource Location
- Clean Up Area
- Completed Dozer Line
- Unimproved Landing Area
- Value at Risk
- Repair Point
- Completed Fuel Break
- Drop Point
- Landing or Log Deck
- Safety Zone
- Completed Hand Line
- Gate
- Hazard
- Completed Mixed Construction Line
- Bridge
- Fence - Cut/Damaged
- Fence
- Completed Plow Line
- Other
- Completed - Ready for Inspection
- Repair Needed
- Unknown
- Access or Improved Road Repair Status Line
- Completed - Inspected

