

# Alder Creek

	Repair Point Count	Percent Complete
Completed - Inspected	20	9%
Completed - Ready for Inspection	1	0%
Other - See Comments	1	0%
Repair Needed	170	72%
Unknown	43	18%
<b>Grand Total</b>	<b>235</b>	


Line Type	Repair Status (Miles)				TOTAL	Percent Complete
	Completed - Inspected	Completed - Ready for Inspection	Repair Needed	Unknown		
Access or Improved Road	0.24	0.06	3.94	0.63	4.87	5%
Completed Dozer Line	5.71	4.75	11.11	0.83	22.40	25%
Completed Fuel Break	2.45	0.77	3.57	2.32	9.10	27%
Completed Hand Line	2.08	0.31	2.74	0.28	5.41	39%
Completed Mixed Construction Line	0.26		3.11	1.94	5.30	5%
Completed Plow Line	0.20		0.38		0.58	34%
Completed Road as Line		0.44	13.26	1.89	15.58	0%
Fence			0.24		0.24	0%
Other		0.20	0.09		0.28	0%
Planned Dozer Line				0.42	0.42	0%
Repair Line			0.14	0.10	0.23	0%
Road Repair		1.36	16.56		17.93	0%
<b>Grand Total</b>	<b>10.93</b>	<b>7.89</b>	<b>55.12</b>	<b>8.40</b>	<b>82.34</b>	<b>13%</b>

## SUPPRESSION REPAIR

10/3/2021

**Alder Creek**  
 MTBDF-006269  
 Alder Creek GIS Acres 36,742  
 10/02/2021 1806 MDT  
 Acres from IR

**Sand Lake**  
 MTBDF-006298  
 Sand Lake GIS Acres 228  
 09/13/2021 2109 MDT  
 Acres from IR



- Dip Site
- Staging Area
- Bridge
- Landing or Log Deck
- Safety Zone
- Helispot
- Lookout
- Stream Crossing
- Hazard
- H - Completed Hand Line
- Unimproved Landing Area
- Value at Risk
- Road Repair
- Dozer Push
- M - Completed Mixed Construction Line
- Drop Point
- Resource Location
- Culvert
- P - Completed Plow Line
- Camp
- Gate
- Clean Up Area
- MW Completed Fuel Break
- Planned Dozer Line
- Access or Improved Road
- Repair Status Line
- Fence
- Completed - Inspected
- Completed - Ready for Inspection
- Repair Needed
- Unknown

