

# Alder Creek


	Repair Point Count	Complete
Completed - Inspected	20	9%
Completed - Ready for Inspection	1	0%
Other - See Comments	1	0%
Repair Needed	170	72%
Unknown	43	18%
<b>Grand Total</b>	<b>235</b>	

Line Type	Repair Status (Miles)				TOTAL	Percent Complete
	Completed - Inspected	Completed - Ready for Inspection	Repair Needed	Unknown		
Access or Improved Road	0.67		4.20		4.87	14%
Completed Dozer Line	7.74	2.84	10.98	0.83	22.40	35%
Completed Fuel Break	4.81		1.98	2.32	9.10	53%
Completed Hand Line	2.73	0.28	2.12	0.28	5.41	50%
Completed Mixed Construction Line	0.26		3.11	1.94	5.30	5%
Completed Plow Line	0.50		0.08		0.58	86%
Completed Road as Line	4.78	0.44	8.48	1.89	15.58	31%
Fence			0.24		0.24	0%
Other		0.20	0.09		0.28	0%
Planned Dozer Line				0.42	0.42	0%
Repair Line				0.10	0.23	0%
Road Repair		1.36	16.56		17.93	0%
<b>Grand Total</b>	<b>21.48</b>	<b>5.12</b>	<b>47.97</b>	<b>7.77</b>	<b>82.34</b>	<b>26%</b>

## SUPPRESSION REPAIR

**Alder Creek**  
 MTBDF-006269  
 Alder Creek GIS Acres 36,905  
 10/03/2021 2043 MDT  
 Acres from IR

**Sand Lake**  
 MTBDF-006298  
 Sand Lake GIS Acres 228  
 09/13/2021 2109 MDT  
 Acres from IR



- Dip Site
- Staging Area
- Bridge
- Landing or Log Deck
- Safety Zone
- H - Completed Hand Line
- Access or Improved Road
- Helispot
- Lookout
- Stream Crossing
- Hazard
- Repair Status Line
- Unimproved Landing Area
- Value at Risk
- Road Repair
- Dozer Push
- Water Source
- Completed - Inspected
- Drop Point
- Resource Location
- Culvert
- Completed Dozer Line
- Completed Road as Line
- Completed - Ready for Inspection
- Camp
- Gate
- Clean Up Area
- Completed Fuel Break
- Planned Dozer Line
- Repair Needed
- Unknown

