


Aerial Hazard	Water Development or Draft Site	<b>Event Point - Status</b>	<b>Event Line - Status</b>
Dip Site	Structure Wrap	<b>Repair Status</b>	<b>Repair Status</b>
Helispot	Stream Crossing	Completed - Inspected	Completed - Inspected
Division Break	Resource Location	Completed - Ready for Inspection	Completed - Ready for Inspection
Drop Point	Repair Point	In Progress	In Progress
Closure	Landing or Log Deck	Repair Needed	Repair Needed
Staging Area	Fence - Cut/Damaged	Unknown	Unknown
Lookout	Dozer Push	Completed Dozer Line	Wildfire Daily Fire Perimeter
Hot Spot - Spot Fire	Clean Up Area	Completed Fuel Break	<b>Ownership</b>
Value at Risk	Mobile Weather Unit	Completed Hand Line	State of Montana
Other	Internet Access	Completed Mixed Construction Line	USFS
Gate	Safety Zone	Completed Road as Line	
Fire Station	Hazard	Access or Improved Road	
Bridge	Water Source	Other	
		Repair Line	
		Retardant Drop	
		Fire Edge	
		Contained Line	

Author: jfrazier  
 Date: 9/19/2021, 10:12:14 PM  
 T:\FS\INFS\Helena\LewisClark\Program  
 5100FireMgmt\GIS\ZoneKH12021\_DivideComplex\projects



**Repair Map**  
 Balsinger (8,584 acres)  
 8/18/2021 2100 hrs  
 MT-HLF-005079  
 9/20/2021

0 0.25 0.5 Miles