



# Suppression Repair Map - Zone 5

Stateline Complex  
D-IPF-000504

11,071 acres as of  
09/09/2021 2215 MDT

09/12/2021 Day

## TUMBLEDOWN OPERATIONS

- |   |   |  |  |   |
|---|---|--|--|---|
| <ul style="list-style-type: none"> <li>● Helispot</li> <li>⓪ Unimproved Landing Area</li> <li>■ Drop Point</li> <li>ⓧ Closure</li> <li>Ⓜ Staging Area</li> <li>Ⓜ Lookout</li> <li>Ⓜ Value at Risk</li> <li>Ⓜ Other</li> <li>Ⓜ Gate</li> </ul> | <ul style="list-style-type: none"> <li>Ⓜ Bridge</li> <li>Ⓜ Water Development or Draft Site</li> <li>Ⓜ Stream Crossing</li> <li>Ⓜ Road Repair</li> <li>Ⓜ Repair Point</li> <li>Ⓜ Landing or Log Deck</li> <li>Ⓜ Dozer Push</li> <li>Ⓜ Culvert</li> <li>Ⓜ Repeater</li> </ul> | <ul style="list-style-type: none"> <li>Ⓜ Water Source</li> <li>Ⓜ Other Property</li> <li>Ⓜ Pump</li> <li>Ⓜ Water Tank</li> <li>Ⓜ Completed Dozer Line</li> <li>Ⓜ Completed Fuel Break</li> <li>Ⓜ Completed Hand Line</li> <li>Ⓜ Completed Mixed Construction Line</li> <li>Ⓜ Completed Road as Line</li> </ul> | <ul style="list-style-type: none"> <li>— Access or Improved Road</li> <li>— Other</li> <li>— Repair Line</li> <li>— Road Repair</li> <li>— Fire Edge</li> <li>— Contained Line</li> <li>— Wildfire Daily Fire Perimeter</li> <li>— Fire Zones</li> </ul> | <ul style="list-style-type: none"> <li>● Repair Status Point</li> <li>● Completed - Inspected</li> <li>● In Use - Fire Management</li> <li>● Completed - Ready for Inspection</li> <li>● In Progress</li> <li>● Repair Needed</li> <li>● No Repair Needed</li> <li>● Other - See Comments</li> <li>● Unknown</li> </ul> |
|---|---|--|--|---|

