



# Suppression Repair Map - Zone 5

Stateline Complex  
 D-IPF-000504  
 9/14/2021

11,071 acres as of  
 09/09/2021 2215 MDT

## TUMBLEDOWN OPERATIONS

- |   |   |  |  |   |
|---|---|--|--|---|
| <ul style="list-style-type: none"> <li>● Helispot</li> <li>○ Unimproved Landing Area</li> <li>■ Drop Point</li> <li>⊠ Closure</li> <li>⊡ Staging Area</li> <li>⊞ Lookout</li> <li>⊙ Value at Risk</li> <li>⊙ Other</li> <li>⊙ Gate</li> </ul> | <ul style="list-style-type: none"> <li>⊙ Bridge</li> <li>⊙ Water Development or Draft Site</li> <li>⊙ Stream Crossing</li> <li>⊙ Road Repair</li> <li>⊙ Repair Point</li> <li>⊙ Landing or Log Deck</li> <li>⊙ Dozer Push</li> <li>⊙ Culvert</li> <li>⊙ Repeater</li> </ul> | <ul style="list-style-type: none"> <li>⊙ Water Source</li> <li>⊙ Other Property</li> <li>⊙ Pump</li> <li>⊙ Water Tank</li> <li>⊙ Completed Dozer Line</li> <li>⊙ Completed Fuel Break</li> <li>⊙ Completed Hand Line</li> <li>⊙ Completed Mixed Construction Line</li> <li>⊙ Completed Road as Line</li> </ul> | <ul style="list-style-type: none"> <li>— Access or Improved Road</li> <li>— Other</li> <li>— Repair Line</li> <li>— Road Repair</li> <li>— Fire Edge</li> <li>— Contained Line</li> <li>— Wildfire Daily Fire Perimeter</li> <li>— Fire Zones</li> </ul> | <ul style="list-style-type: none"> <li>● Repair Status Point</li> <li>● Completed - Inspected</li> <li>● In Use - Fire Management</li> <li>● Completed - Ready for Inspection</li> <li>● In Progress</li> <li>● Repair Needed</li> <li>● No Repair Needed</li> <li>● Other - See Comments</li> <li>● Unknown</li> </ul> |
|---|---|--|--|---|

