


# Suppression Repair



**Colt Fire**  
**MT-SWS-200549**  
**9/5/2023**  
**7,154 Acres**  
 Fire perimeter updated  
 from GPS and IR on 8/25/2023 @ 2322hrs

- |  |   |   |  |  |  |
|--|---|---|--|--|--|
| <ul style="list-style-type: none"> <li>● Label Point</li> <li>Ⓟ Pump</li> <li>Ⓜ Helispot</li> <li>Ⓢ Unimproved Landing Area</li> <li>Ⓝ Division Break</li> <li>Ⓜ Incident Command Post</li> <li>Ⓛ Drop Point</li> <li>Ⓝ Closure</li> <li>Ⓢ Staging Area</li> </ul> | <ul style="list-style-type: none"> <li>● Other</li> <li>Ⓜ Stream Crossing</li> <li>Ⓜ Repair Point</li> <li>Ⓜ Landing or Log Deck</li> <li>Ⓜ Culvert</li> <li>Ⓜ Internet Access</li> <li>Ⓜ Repeater</li> <li>Ⓜ Completed Dozer Line</li> <li>Ⓜ Completed Fuel Break</li> </ul> | <ul style="list-style-type: none"> <li>Ⓜ Completed Hand Line</li> <li>Ⓜ Completed Mixed Construction Line</li> <li>Ⓜ Accountable Property</li> <li>Ⓜ Repair Status</li> <li>Ⓜ Access or Improved Road</li> <li>Ⓜ Highlighted Feature</li> <li>Ⓜ Other</li> <li>Ⓜ Repair Line</li> <li>Ⓜ Road Repair</li> <li>Ⓜ Contained</li> </ul> | <ul style="list-style-type: none"> <li>Ⓜ Wildfire Daily Fire Perimeter</li> <li>Ⓜ Repair Status</li> <li>Ⓜ In Use - Fire Management</li> <li>Ⓜ Event Point</li> <li>Ⓜ Repair Status</li> <li>Ⓜ In Use - Fire Management</li> <li>Ⓜ Needs Assessment</li> </ul> | <ul style="list-style-type: none"> <li>● Repair Needed</li> <li>● Completed - Ready for Inspection</li> <li>● Completed - Inspected</li> <li>● Other - See Comments</li> <li>● Event Line</li> <li>● Repair Status</li> <li>● In Use - Fire Management</li> <li>● Needs Assessment</li> <li>● Repair Needed</li> </ul> | <ul style="list-style-type: none"> <li>Ⓜ In Progress</li> <li>Ⓜ Completed - Ready for Inspection</li> <li>Ⓜ Completed - Inspected</li> <li>Ⓜ No Repair Needed</li> <li>Ⓜ ForestServiceRoads</li> </ul> |
|--|---|---|--|--|--|

