

Copper King Fire Repair Map


MT-LNF-005092
September 10, 2016
28,553 Acres



Legend

- Roads Sawn Out
- Repair Status**
- Repair Needed
- Repair Type**
- Dozer Line
- Hand Line
- Other
- Contingency Line
- Repair Status**
- Other
- Repair Complete
- Repair Needed

	USFS	DNRC	Private	Weyer	Local Gov	Totals	% of total
Repair Complete							
Dozer Line	1.59	0.78		2.06		4.43	
Hand Line	0.23			0.20		0.43	
Other	1.14	1.20	3.83	4.87	0.09	11.13	14.0%
Repair Needed							
Dozer Line	3.91	1.90	1.69	13.16		20.67	
Hand Line	2.20	0.24	0.64	2.76		5.85	
Other	16.98	7.93	1.02	23.21		49.14	66.4%
Rehab Other							
Dozer Line	0.79					0.79	
Hand Line	0.11		1.38			1.49	
Other	10.22		1.12	8.63		19.97	19.5%
Grand Totals	37.17	12.06	9.69	54.89	0.09	113.89	
% of Total	32.6%	10.6%	8.5%	48.2%	0.1%		



	USFS	DNRC	Private	Weyer	Totals	% of total
Repair Complete						
Dozer Line	2.15	1.44		7.29	10.88	
Hand Line	0.23			0.41	0.64	
Other	8.81	2.83	4.08	14.56	30.29	
					41.81	33.3%
Repair Needed						
Dozer Line	3.43	0.01	1.71	7.78	12.93	
Hand Line	2.44	0.24	0.48	2.77	5.94	
Other	14.03	7.18	2.66	17.19	41.07	
					59.93	47.7%
Rehab Other						
Dozer Line	0.90			1.57	2.47	
Hand Line			1.38		1.38	
Other	10.22		1.12	8.63	19.97	
					23.82	19.0%
Grand Totals	42.21	11.71	11.43	60.20	125.56	
% of Total	33.6%	9.3%	9.1%	47.9%		

