

STRUCTURE  
PROTECTION PLAN  
FOR ONE HORSE  
BLOCK

07/30/2017

# Structure Protection Plan

## One Horse

Location: Florence Carlton Lp. On the East side. North side is Tie Chute Rd, South side is Holloway Ln.

Description: This area is directly West of Florence and along Florence Carlton Lp. is a heavily populated urban area. The entire rest of the block is timbered with the exception of one large ranch to the South on Holloway Rd. Most of the structures that are accessed from Tie Chute Rd. on the North have defensible space and are defensible. The houses accessed off of Holloway Rd. from the South toward the East are defensible with work. The West end of Holloway Rd. has a large junkyard with one resident that will need to be evacuated. One Horse creek runs through the South end of the block – this has minimal water. The only good draftable water is on the ranch to the South.

Safety Zone: The only good safety zone is on the ranch to the South. All other be out to Hwy 93.

Timing: If the fire progresses down One Horse Creek or down the slope from the West. Some of the homes in this area will take some work so trigger early.

Plan:

Most of the structures along Tie Chute Rd. will need minimal work (most are good) this area is accessible for Type 3 engines and will need a Strike Team of Type 3 Engines for protection.

The houses accessed from Holloway Ln. are accessible by Type 6 Engines and toward the West end will need a lot of work clearing. You can pump from a few spots in the creek but there will be limited water available. The junkyard at the end of Holloway should have a dozer line cut around it and firefighters kept out due to Haz-Mat. Safety zone for this area would be the ranch to the South.

Needs:

- 1 – Strike Teams Type 3 Engines
- 1 – Strike Team Type 6 Engines
- 1 – Water Tender
- 1 - Dozer
- 10 – Mark 3 Pumps
- 20 – Sprinkler Kits
- 4 – Pumpkins
- Overhead for above

### Structure Triage Information



**Structure Number:**  
**Structure Name:** 234 B Tie Chute Lane  
**SubDivision:** One Horse  
**GPS Location, Lat.** 46 38.54892  
**GPS Location, Long.** 114 4.71174  
**Safety Zone Present:** No  
**Type of Structure:** Residential  
**Surrounding Fuels:** Grass, Shrub  
**Structure Triage Category:** Defensible, Prep and Hold  
**Roof Material:** Composite  
**Heat Traps:** Open Eaves, Wood Deck  
**Electrical Power:** Overhead  
**Hazards:**  
**Access to Site:** T1 Engine  
**Comm with ICP:** Radio, Cell Service  
**Water Source:** Faucet / Hose  
**Mitigation Time:** 1-2 Hours  
**Collected By:** E-27 Florence

**Where is Safety Zone:** 1-2 minutes to the school

**Primary Structures:**

**Outbuildings:**

**Defensible Space:** 30-50 Feet

**Siding Material:** Wood

**Gas to Structure:** Underground

**Best Access From:** Tie Chute lane

**Collected Date/Time:** 07/30/2017 10:08:52

Photo 1

Photo 2



Photo 3

Photo 4

### Structure Triage Information



**Structure Number:**  
**Structure Name:** 246 Tie Chute lane  
**SubDivision:** One Horse  
**GPS Location, Lat.** 46 38.54802  
**GPS Location, Long.** 114 4.78968  
**Safety Zone Present:** No  
**Type of Structure:** Residential  
**Surrounding Fuels:** Grass  
**Structure Triage Category:** Defensible, Prep and Hold  
**Roof Material:** Composite  
**Heat Traps:** Wood Deck  
**Electrical Power:** Overhead  
**Hazards:**  
**Access to Site:** T1 Engine  
**Comm with ICP:** Radio, Cell Service  
**Water Source:** Faucet / Hose  
**Mitigation Time:** Less Than An Hour  
**Collected By:** E-27 Florence

**Where is Safety Zone:** 1-2 minute drive to ICP

**Primary Structures:**

**Outbuildings:**

**Defensible Space:** 30-50 Feet

**Siding Material:** Masonry

**Gas to Structure:**

**Best Access From:** Tie Chute lane

**Collected Date/Time:** 07/30/2017 10:09:20

Photo 1

Photo 2



Photo 3

Photo 4

## Structure Triage Information



**Structure Number:**  
**Structure Name:** 300 Tie Chute  
**SubDivision:** One Horse  
**GPS Location, Lat.** 46 38.55414  
**GPS Location, Long.** 114 5.11776

**Safety Zone Present:** Yes  
**Type of Structure:** Residential  
**Surrounding Fuels:** Grass, Timber  
**Structure Triage Category:** Defensible, Prep and Hold  
**Roof Material:** Composite  
**Heat Traps:** Wood Deck, Rain Gutters  
**Electrical Power:** Underground  
**Hazards:**  
**Access to Site:** T3/4 Engine  
**Comm with ICP:** Radio, Cell Service  
**Water Source:** Faucet / Hose, Large Pond, Creek  
**Mitigation Time:** Less Than An Hour  
**Notes:** Pond could be used as water source, ground is soft. Creek runs through north end of property. Swimming pool on north end.

**Where is Safety Zone:** One engine, large green yard. Access to pasture on the north side of the property, possibly swampy.

**Primary Structures:** **Outbuildings:**

**Defensible Space:** 50-100 Feet

**Siding Material:** Wood

**Gas to Structure:** Underground

**Best Access From:** Tie Chute

**Collected By:** AZ-TNF 1265  
Photo 1

**Collected Date/Time:** 07/30/2017 10:10:10  
Photo 2



Photo 3



Photo 4

## Structure Triage Information



**Structure Number:**

**Structure Name:** 302 Wickiup Drive

**SubDivision:** One Horse

**GPS Location, Lat.** 46 38.27574

**GPS Location, Long.** 114 5.1129

**Safety Zone Present:** Yes

**Type of Structure:** Residential

**Surrounding Fuels:** Grass

**Structure Triage**

**Category:** Defensible, Stand Alone

**Roof Material:** Composite

**Heat Traps:** Wood Deck,Rain Gutters

**Electrical Power:** Underground

**Hazards:**

**Where is Safety Zone:** Front yard

**Primary Structures:**

**Outbuildings:**

**Defensible Space:** 30-50 Feet

**Siding Material:** Wood

**Gas to Structure:** Underground

Wickiup Drive, off of Florence Carlton Loop, off of Tie Chute Lane, off of Old

**Best Access From:** US 93

**Access to Site:** T1 Engine

**Comm with ICP:** Radio,Cell Service

**Water Source:** Faucet / Hose

**Mitigation Time:** Less Than An Hour

**Other Resources**

**Needed to Protect:** Sprinklers

**Collected By:** Engine 951

**Collected Date/Time:** 07/30/2017 10:09:51

Photo 1

Photo 2



Photo 3



Photo 4

## Structure Triage Information



**Structure Number:**  
**Structure Name:** 303 Rocky Road  
**SubDivision:** One Horse  
**GPS Location, Lat.** 46 38.06778  
**GPS Location, Long.** 114 5.13906  
**Safety Zone Present:** Yes  
**Type of Structure:** Mixed Use  
**Surrounding Fuels:** Grass, Timber  
**Structure Triage Category:** Defensible, Prep and Hold  
**Roof Material:** Metal  
**Heat Traps:** Other Receptor  
**Electrical Power:** Overhead, Underground  
**Hazards:** Fuels, Animals  
**Access to Site:** T1 Engine  
**Comm with ICP:** Radio, Cell Service  
**Water Source:** Faucet / Hose  
**Mitigation Time:** More Than 5 Hours  
**Other Resources Needed to Protect:** Removal of wood and hay from around the house, Lots of clutter. But surrounded by green grass  
**Notes:** Cows in the backyard

**Where is Safety Zone:** Down the road to park on Florence Carlton Loop  
**Primary Structures:**  
**Outbuildings:**  
**Defensible Space:** 30-50 Feet  
**Siding Material:** Wood  
**Gas to Structure:** Underground  
**Best Access From:** Rocky Road from Florence Carlton Loop

**Collected By:** Engine 951  
Photo 1

**Collected Date/Time:** 07/30/2017 10:09:43  
Photo 2



Photo 3



Photo 4



### Structure Triage Information



**Structure Number:**  
**Structure Name:** 312 Hughs Lane  
**SubDivision:** One Horse  
**GPS Location, Lat.** 46 38.0937  
**GPS Location, Long.** 114 5.2113  
**Safety Zone Present:** Yes  
**Type of Structure:** Residential  
**Surrounding Fuels:** Grass  
**Structure Triage Category:** Defensible, Stand Alone  
**Roof Material:** Composite  
**Heat Traps:** Rain Gutters  
**Electrical Power:** Overhead, Underground  
**Hazards:**  
**Access to Site:** T1 Engine  
**Comm with ICP:** Radio, Cell Service  
**Water Source:** Faucet / Hose  
**Mitigation Time:** None Needed  
**Collected By:** Engine 951

**Where is Safety Zone:** Down the road to park on Florence Carlton Loop  
**Primary Structures:**  
**Outbuildings:**

**Defensible Space:** 50-100 Feet

**Siding Material:** Wood

**Gas to Structure:** Underground

**Best Access From:** Hughs Lane off of Florence Carlton Loop

**Collected Date/Time:** 07/30/2017 10:08:55

Photo 1

Photo 2



Photo 3

Photo 4





## Structure Triage Information



**Structure Number:**  
**Structure Name:** 313 Wickiup Drive  
**SubDivision:** One Horse  
**GPS Location, Lat.** 46 38.2743  
**GPS Location, Long.** 114 5.17362  
**Safety Zone Present:** Yes  
**Type of Structure:** Residential  
**Surrounding Fuels:** Timber  
**Structure Triage Category:** Defensible, Stand Alone  
**Roof Material:** Composite  
**Heat Traps:** Wood Deck  
**Electrical Power:** Underground  
**Hazards:** Fuels  
**Access to Site:** T1 Engine  
**Comm with ICP:** Radio, Cell Service  
**Water Source:** Faucet / Hose  
**Mitigation Time:** Less Than An Hour  
**Other Resources Needed to Protect:** Wood around the house could be removed. Thinning in the backyard  
**Collected By:** Engine 951

**Where is Safety Zone:** Down the road to Florence Carlton Loop

**Primary Structures:** **Outbuildings:**

**Defensible Space:** 30-50 Feet

**Siding Material:** Wood

**Gas to Structure:** Underground

**Best Access From:** Wickiup Lane

**Collected Date/Time:** 07/30/2017 10:10:15

Photo 1

Photo 2



Photo 3

Photo 4



## Structure Triage Information



**Structure Number:**

**Structure Name:** 316 Wickiup Drive

**SubDivision:** One Horse

**GPS Location, Lat.** 46 38.27424

**GPS Location, Long.** 114 5.15712

**Safety Zone Present:** Yes

**Type of Structure:** Residential

**Surrounding Fuels:** Timber

**Structure Triage**

**Category:** Defensible, Stand Alone

**Roof Material:** Composite

**Heat Traps:** Wood Deck, Rain Gutters

**Electrical Power:** Underground

**Hazards:**

**Access to Site:** T1 Engine

**Comm with ICP:** Radio, Cell Service

**Water Source:** Faucet / Hose

**Mitigation Time:** Less Than An Hour

**Other Resources**

**Needed to Protect:**

**Notes:** Timber but no ladder fuels, green grass understory

**Where is Safety Zone:** Down the road to Florentine Carleton

**Primary Structures:**

**Outbuildings:**

**Defensible Space:** 30-50 Feet

**Siding Material:** Wood

**Gas to Structure:** Underground

**Best Access From:** Wickiup Lane

**Collected By:** Engine 951

Photo 1

**Collected Date/Time:** 07/30/2017 10:09:40

Photo 2



Photo 3



Photo 4

## Structure Triage Information



**Structure Number:**  
**Structure Name:** 317/319 Wickiup Drive  
**SubDivision:** One Horse  
**GPS Location, Lat.** 46 38.27484  
**GPS Location, Long.** 114 5.24748  
**Safety Zone Present:** Yes  
**Type of Structure:** Residential  
**Surrounding Fuels:** Timber  
**Structure Triage Category:** Defensible, Stand Alone  
**Roof Material:** Composite  
**Heat Traps:** Wood Deck,Rain Gutters  
**Electrical Power:** Underground  
**Hazards:** Fuels  
**Access to Site:** T1 Engine  
**Comm with ICP:** Radio,Cell Service  
**Water Source:** Faucet / Hose  
**Mitigation Time:** 1-2 Hours  
**Other Resources Needed to Protect:** Mowing grass in backyard  
**Collected By:** Engine 951  
Photo 1

**Where is Safety Zone:** Down Wickiup Lane to Florence Carleton

**Primary Structures:** **Outbuildings:**

**Defensible Space:** 30-50 Feet

**Siding Material:** Vinyl

**Gas to Structure:** Underground

**Best Access From:** Wickiup drive

**Collected Date/Time:** 07/30/2017 10:09:58

Photo 2



Photo 1



Photo 2



Photo 3

## Structure Triage Information



Structure Number:  
Structure Name: 318 Rocky Road  
SubDivision: One Horse

GPS Location, Lat. 46 38.06094

GPS Location, Long. 114 5.23956

Safety Zone Present: Yes

Type of Structure: Residential

Surrounding Fuels: Grass, Timber

Structure Triage

Category: Defensible, Prep and Hold

Roof Material: Wood

Heat Traps:

Electrical Power: Underground

Hazards: Fuels

Access to Site: T1 Engine

Comm with ICP: Radio, Cell Service

Water Source: Faucet / Hose

Mitigation Time: 1-2 Hours

Other Resources: Needs some mowing around back, and propane tank

Needed to Protect:  
Collected By: Engine 951

Photo 1

Where is Safety Zone: Down the road to park on Florence Carlton Loop

Primary Structures:

Outbuildings:

Defensible Space: 30-50 Feet

Siding Material: Wood

Gas to Structure: Aboveground

Best Access From: Rocky Road

Collected Date/Time: 07/30/2017 10:09:12

Photo 2



Photo 3



Photo 4

## Structure Triage Information



**Structure Number:**  
**Structure Name:** 320 Wickiup Drive  
**SubDivision:** One Horse  
**GPS Location, Lat.** 46 38.30922  
**GPS Location, Long.** 114 5.21058  
**Safety Zone Present:** Yes  
**Type of Structure:** Residential  
**Surrounding Fuels:** Timber  
**Structure Triage Category:** Defensible, Stand Alone  
**Roof Material:** Composite  
**Heat Traps:** Rain Gutters  
**Electrical Power:** Underground  
**Hazards:**  
**Access to Site:** T1 Engine  
**Comm with ICP:** Radio, Cell Service  
**Water Source:** Faucet / Hose  
**Mitigation Time:** Less Than An Hour  
**Other Resources Needed to Protect:** Tall grasses around 2 outbuildings, need Mowing or line  
**Notes:** Timber with no ladder fuels

**Where is Safety Zone:** Down the road to Florence Carleton Loop

**Primary Structures:**

**Outbuildings:**

**Defensible Space:**

**Siding Material:** Wood

**Gas to Structure:** Underground

**Best Access From:**

**Collected By:** Engine 951  
Photo 1

**Collected Date/Time:** 07/30/2017 10:10:11  
Photo 2



Photo 3



Photo 4



## Structure Triage Information



**Structure Number:**  
**Structure Name:** 321 Rocky Road  
**SubDivision:** One Horse  
**GPS Location, Lat.** 46 38.0541  
**GPS Location, Long.** 114 5.24688  
**Safety Zone Present:** Yes  
**Type of Structure:** Residential  
**Surrounding Fuels:** Timber  
**Structure Triage Category:** Defensible, Prep and Hold  
**Roof Material:** Metal  
**Heat Traps:** Open Eaves, Wood Deck, Rain Gutters, Other Receptor  
**Electrical Power:** Overhead, Underground  
**Hazards:** Fuels  
**Access to Site:** T1 Engine  
**Comm with ICP:** Radio, Cell Service  
**Water Source:** Faucet / Hose  
**Mitigation Time:** Less Than An Hour  
**Other Resources Needed to Protect:** Garage has exposed wall and open eaves. House has second story wood deck  
**Collected By:** Engine 951  
**Where is Safety Zone:** Down the road to park on Florence Carlton Loop  
**Primary Structures:**  
**Outbuildings:**  
**Defensible Space:** 30-50 Feet  
**Siding Material:** Metal  
**Gas to Structure:** Underground  
**Best Access From:** Rocky Road  
**Collected Date/Time:** 07/30/2017 10:09:06

Photo 1

Photo 2



Photo 3

Photo 4



## Structure Triage Information



Structure Number: 321 Wickiup Drive  
Structure Name: 321 Wickiup Drive  
SubDivision: One Horse  
GPS Location, Lat. 46 38.24742  
GPS Location, Long. 114 5.22738  
Safety Zone Present: Yes      Where is Safety Zone: Down the road Florence  
Type of Structure: Residential      Primary Structures:      Outbuildings:  
Surrounding Fuels: Timber      Defensible Space: 30-50 Feet  
Structure Triage Category: Defensible, Prep and Hold  
Roof Material: Composite      Siding Material: Wood  
Heat Traps: Rain Gutters  
Electrical Power: Underground      Gas to Structure: Underground  
Hazards: Fuels  
Access to Site: T1 Engine      Best Access From: Wickiup Drive  
Comm with ICP: Radio, Cell Service  
Water Source: Faucet / Hose, Porta-Tank/Pumpkin  
Mitigation Time: Less Than An Hour  
Other Resources: Clean gutters and roof, remove wood from around house, thinning along back fence  
Needed to Protect:  
Notes: Pool in the back

Collected By: Engine 951  
Photo 1

Collected Date/Time: 07/30/2017 10:10:08  
Photo 2



Photo 3



Photo 4



## Structure Triage Information



**Structure Number:**  
**Structure Name:** 322 /324 Wickiup Drive  
**SubDivision:** One Horse  
**GPS Location, Lat.** 46 38.31804  
**GPS Location, Long.** 114 5.22462  
**Safety Zone Present:** Yes  
**Type of Structure:** Residential  
**Surrounding Fuels:** Timber  
**Structure Triage Category:** Defensible, Stand Alone  
**Roof Material:** Composite  
**Heat Traps:** Rain Gutters  
**Electrical Power:** Overhead  
**Hazards:** Septic Tank  
**Access to Site:** T1 Engine  
**Comm with ICP:** Radio, Cell Service  
**Water Source:** Faucet / Hose  
**Mitigation Time:** 1-2 Hours  
**Other Resources Needed to Protect:** Clean under decks, gutters  
**Collected By:** Engine 951

**Where is Safety Zone:** Down Wickiup To Florence Carleton Loop

**Primary Structures:** **Outbuildings:**

**Defensible Space:** 30-50 Feet

**Siding Material:** Vinyl

**Gas to Structure:** Underground

**Best Access From:** Wickiup Drive

**Collected Date/Time:** 07/30/2017 10:10:03

Photo 1

Photo 2



Photo 3



Photo 4



## Structure Triage Information



**Structure Number:**  
**Structure Name:** 323 Wickiup Drive  
**SubDivision:** One Horse  
**GPS Location, Lat.** 46 38.29566  
**GPS Location, Long.** 114 5.21862  
**Safety Zone Present:** Yes  
**Type of Structure:** Residential  
**Surrounding Fuels:** Timber  
**Structure Triage Category:** Defensible, Stand Alone  
**Roof Material:** Composite  
**Heat Traps:** Wood Deck  
**Electrical Power:** Overhead  
**Hazards:** Fuels  
**Access to Site:** T1 Engine  
**Comm with ICP:** Radio, Cell Service  
**Water Source:** Faucet / Hose  
**Mitigation Time:** 2-3 Hours  
**Other Resources Needed to Protect:** Limbing and thinning behind property  
**Collected By:** Engine 951

**Where is Safety Zone:** Down wickiup drive to Florence Carleton loop

**Primary Structures:**

**Outbuildings:**

**Defensible Space:** 30-50 Feet

**Siding Material:** Wood

**Gas to Structure:** Underground

**Best Access From:** Wickiup Drive

**Collected Date/Time:** 07/30/2017 10:09:10

Photo 1

Photo 2



Photo 3

Photo 4



## Structure Triage Information



Structure Number:  
Structure Name: 327 Wickiup Drive  
SubDivision: One Horse

GPS Location, Lat. 46 38.30994

GPS Location, Long. 114 5.22612

Safety Zone Present: Yes

Type of Structure: Residential

Surrounding Fuels: Timber

Structure Triage

Category: Defensible, Prep and Hold

Roof Material: Metal

Heat Traps: Other Receptor

Electrical Power: Overhead

Hazards: Fuels

Access to Site: T1 Engine

Comm with ICP: Radio, Cell Service

Water Source: Faucet / Hose

Mitigation Time: 1-2 Hours

Other Resources Needed to Protect: Some limbing and thinning around the back of the house. And line around backside of property

Collected By: Engine 951  
Photo 1

Where is Safety Zone: Down the wickiup drive to Florence Carleton loop

Primary Structures:

Outbuildings:

Defensible Space: 30-50 Feet

Siding Material: Wood

Gas to Structure: Underground

Best Access From: Wickiup Drive

Collected Date/Time: 07/30/2017 10:09:56  
Photo 2



Photo 1



Photo 2



Photo 3

## Structure Triage Information



**Structure Number:**  
**Structure Name:** 340 Holloway Lane  
**SubDivision:** One Horse  
**GPS Location, Lat.** 46 37.93182  
**GPS Location, Long.** 114 5.24076  
**Safety Zone Present:** Yes  
**Type of Structure:** Residential  
**Surrounding Fuels:** Grass  
**Structure Triage Category:** Defensible, Stand Alone  
**Roof Material:** Composite  
**Heat Traps:** Rain Gutters  
**Electrical Power:** Overhead  
**Hazards:** HazMat  
**Access to Site:** T1 Engine  
**Comm with ICP:** Radio, Cell Service  
**Water Source:** Faucet / Hose  
**Mitigation Time:** None Needed  
**Other Resources Needed to Protect:** None  
**Notes:** Green grass all around.

**Where is Safety Zone:** Yard

**Primary Structures:**

**Outbuildings:**

**Defensible Space:** 50-100 Feet

**Siding Material:** Wood

**Gas to Structure:** Underground

**Best Access From:** 93 to Holloway

**Collected By:** Lolo 632

Photo 1

**Collected Date/Time:** 07/30/2017 10:09:49

Photo 2



Photo 3



Photo 4

## Structure Triage Information



**Structure Number:**  
**Structure Name:** 341 Holloway Lane  
**SubDivision:** One Horse  
**GPS Location, Lat.** 46 37.89972  
**GPS Location, Long.** 114 5.27922  
**Safety Zone Present:** Yes  
**Type of Structure:** Residential  
**Surrounding Fuels:** Grass, Timber  
**Structure Triage Category:** Defensible, Stand Alone  
**Roof Material:** Metal  
**Heat Traps:** Wood Deck  
**Electrical Power:** Overhead, Solar/Wind  
**Hazards:** HazMat  
**Access to Site:** T1 Engine  
**Comm with ICP:** Radio, Cell Service  
**Water Source:** Faucet / Hose  
**Mitigation Time:** Less Than An Hour  
**Other Resources Needed to Protect:** None  
**Notes:** Several out buildings.

**Where is Safety Zone:** West of structure

**Primary Structures:**

**Outbuildings:**

**Defensible Space:** 30-50 Feet

**Siding Material:** Wood

**Gas to Structure:** Underground

**Best Access From:** 93 to Holloway to

**Collected By:** Lolo 632

Photo 1

**Collected Date/Time:** 07/30/2017 10:09:48

Photo 2



Photo 3



Photo 4



## Structure Triage Information



**Structure Number:**  
**Structure Name:** 373 Tie Chute Ln  
**SubDivision:** One Horse  
**GPS Location, Lat.** 46 38.50782  
**GPS Location, Long.** 114 5.55858  
**Safety Zone Present:** No  
**Type of Structure:** Residential  
**Surrounding Fuels:** Grass,Shrub  
**Structure Triage Category:** Defensible, Stand Alone  
**Roof Material:** Composite  
**Heat Traps:** Wood Deck,Rain Gutters  
**Electrical Power:** Overhead,Underground  
**Hazards:**  
**Access to Site:** T1 Engine  
**Comm with ICP:** Radio,Cell Service  
**Water Source:** Faucet / Hose  
**Mitigation Time:** Less Than An Hour  
**Other Resources Needed to Protect:** T6 patrol

**Where is Safety Zone:** Tie Chute Lane to Old Highway 93

**Primary Structures:**

**Outbuildings:**

**Defensible Space:** 30-50 Feet

**Siding Material:** Wood

**Gas to Structure:** Underground

**Best Access From:** Tight turnaround in driveway.

**Notes:** Small well house structure at North East corner of property hundred yards away from residence

**Collected By:** COCO 482  
Photo 1

**Collected Date/Time:** 07/30/2017 10:09:59  
Photo 2



Photo 3

Photo 4

## Structure Triage Information



**Structure Number:**  
**Structure Name:** 387 Tie Chute Ln  
**SubDivision:** One Horse  
**GPS Location, Lat.** 46 38.49294  
**GPS Location, Long.** 114 5.69478  
**Safety Zone Present:** No  
**Type of Structure:** Residential  
**Surrounding Fuels:** Grass, Timber  
**Structure Triage Category:** Defensible, Prep and Hold  
**Roof Material:** Composite  
**Heat Traps:** Wood Deck, Rain Gutters  
**Electrical Power:** Overhead  
**Hazards:** Fuels  
**Access to Site:** T3/4 Engine  
**Comm with ICP:** Radio, Cell Service  
**Water Source:** Faucet / Hose  
**Mitigation Time:** 2-3 Hours  
**Other Resources Needed to Protect:** An engine crew could prep around structures to reduce fuel loading  
**Notes:** Livestock is on property.

**Where is Safety Zone:** To Tie Chute Ln then out to old highway 93 then to highway 93

**Primary Structures:**

**Outbuildings:**

**Defensible Space:** 30-50 Feet

**Siding Material:** Wood

**Gas to Structure:** Aboveground

**Best Access From:** Tie Chute Ln to old highway 93 to highway 93

**Collected By:** COCO 482

Photo 1

**Collected Date/Time:** 07/30/2017 10:09:28

Photo 2



Photo 3

Photo 4

## Structure Triage Information



**Structure Number:**  
**Structure Name:** 390 Scheffler LN  
**SubDivision:** One Horse  
**GPS Location, Lat.** 46 37.99578  
**GPS Location, Long.** 114 5.19504

**Safety Zone Present:** No  
**Type of Structure:** Residential  
**Surrounding Fuels:** Grass, Timber  
**Structure Triage Category:** Defensible, Stand Alone  
**Roof Material:** Composite  
**Heat Traps:**  
**Electrical Power:** Underground  
**Hazards:**  
**Access to Site:** T1 Engine  
**Comm with ICP:** Radio, Cell Service  
**Water Source:**  
**Mitigation Time:** None Needed  
**Notes:** Heavy equipment onsite.

**Where is Safety Zone:** Scheffler LN to Florence Carlton Loop to Tie Chute LN to Old Hwy 93 to designated safety zone.

**Primary Structures:** **Outbuildings:**

**Defensible Space:** 30-50 Feet

**Siding Material:** Wood

**Gas to Structure:** Underground

**Best Access From:** Old Hwy 93 to Tie Chute LN to Florence Carlton Loop to Scheffler LN.

**Collected By:** Prescott 951  
Photo 1

**Collected Date/Time:** 07/30/2017 10:09:22  
Photo 2



Photo 3



Photo 4

## Structure Triage Information



**Structure Number:**  
**Structure Name:** 395 Tie Chute Ln  
**SubDivision:** One Horse  
**GPS Location, Lat.** 46 38.39562  
**GPS Location, Long.** 114 5.7141  
**Safety Zone Present:** No  
**Type of Structure:** Residential  
**Surrounding Fuels:** Timber  
**Structure Triage Category:** Defensible, Prep and Hold  
**Roof Material:** Composite  
**Heat Traps:** Wood Deck, Rain Gutters  
**Electrical Power:** Underground  
**Hazards:**  
**Access to Site:** T3/4 Engine  
**Comm with ICP:** Radio, Cell Service  
**Water Source:** Faucet / Hose  
**Mitigation Time:** Less Than An Hour  
**Other Resources Needed to Protect:** One engine crew to do minimal prep and hold the property  
**Notes:** 2 wells on property

**Where is Safety Zone:** Back down Tie Shoot Rd to old highway 93 to highway 93  
**Primary Structures:**  
**Outbuildings:**  
**Defensible Space:** 30-50 Feet  
**Siding Material:** Wood  
**Gas to Structure:** None  
**Best Access From:** Highway 93 to old highway 93 to Tie Shoot Rd

**Collected By:** COCO 482

Photo 1

**Collected Date/Time:** 07/30/2017 10:09:42

Photo 2



Photo 3



Photo 4





## Structure Triage Information



Structure Number:  
Structure Name: 400 Scheffler LN  
SubDivision: One Horse  
GPS Location, Lat. 46 38.00094  
GPS Location, Long. 114 5.25618

Safety Zone Present: No  
Type of Structure: Residential  
Surrounding Fuels: Grass, Timber  
Structure Triage Category: Defensible, Prep and Hold  
Roof Material: Composite  
Heat Traps: Rain Gutters  
Electrical Power: Overhead  
Hazards: Septic Tank  
Access to Site: T1 Engine  
Comm with ICP: Radio, Cell Service  
Water Source: Faucet / Hose  
Mitigation Time: None Needed  
Collected By: Prescott 951

Where is Safety Zone: Scheffler LN to Florence Carlton Loop to Tie Chute LN to Old Hwy 93 to designated safety zone.

Primary Structures: **Defensible Space:** 30-50 Feet

**Siding Material:** Wood

**Gas to Structure:** Underground

**Best Access From:** Old Hwy 93 to Tie Chute LN to Florence Carlton Loop to Scheffler LN.

**Collected Date/Time:** 07/30/2017 10:09:29

Photo 1

Photo 2



Photo 3



Photo 4



## Structure Triage Information



**Structure Number:**  
**Structure Name:** 415 Tie Chute Rd  
**SubDivision:** One Horse  
**GPS Location, Lat.** 46 38.43732  
**GPS Location, Long.** 114 5.81622  
**Safety Zone Present:** No **Where is Safety Zone:** Out Tie Chute Rd to old highway 93.  
**Type of Structure:** Residential **Primary Structures:** **Outbuildings:**  
**Surrounding Fuels:** Grass, Timber **Defensible Space:** 30-50 Feet  
**Structure Triage Category:** Defensible, Prep and Hold  
**Roof Material:** Composite **Siding Material:** Wood  
**Heat Traps:** Wood Deck, Rain Gutters  
**Electrical Power:** Underground **Gas to Structure:** None  
**Hazards:** Fuels  
**Access to Site:** T1 Engine **Best Access From:** Old highway 93 to Tie Chute to  
**Comm with ICP:** Radio, Cell Service  
**Water Source:** Faucet / Hose  
**Mitigation Time:** 2-3 Hours  
**Other Resources Needed to Protect:** When Engine, one sprinkler kit, portable Pump kit, portable water source, some line put in around structures.  
**Notes:** Owner states that if door is not answered right away proceed into the house due to medical problems he cannot reach the door quickly. Secondary garage located north of main structures.

**Collected By:** COCO 482

Photo 1

**Collected Date/Time:** 07/30/2017 10:08:50

Photo 2



Photo 3



Photo 4



## Structure Triage Information



**Structure Number:**  
**Structure Name:** 419 Tie Chute Ln  
**SubDivision:** One Horse  
**GPS Location, Lat.** 46 38.50992  
**GPS Location, Long.** 114 6.55008  
**Safety Zone Present:** No **Where is Safety Zone:** Down Tie shoots back to old highway 93 to highway 93  
**Type of Structure:** Residential **Primary Structures:** **Outbuildings:**  
**Surrounding Fuels:** Timber **Defensible Space:** 30-50 Feet  
**Structure Triage Category:** Defensible, Prep and Hold  
**Roof Material:** Composite **Siding Material:** Wood  
**Heat Traps:** Open Eaves, Wood Deck, Rain Gutters  
**Electrical Power:** Underground **Gas to Structure:** Aboveground  
**Hazards:** Fuels, Septic Tank  
**Access to Site:** T3/4 Engine **Best Access From:** Old highway 93 to Tie Shoots Rd  
**Comm with ICP:** Radio, Cell Service  
**Water Source:** Faucet / Hose  
**Mitigation Time:** 1-2 Hours  
**Other Resources Needed to Protect:** One engine crew to prep and hold property some fuel reduction and to place sprinklers  
**Collected By:** COCO 482 **Collected Date/Time:** 07/30/2017 10:10:04

Photo 1

Photo 2



Photo 3

Photo 4



## Structure Triage Information



**Structure Number:**  
**Structure Name:** 428 Holloway Lane  
**SubDivision:** One Horse  
**GPS Location, Lat.** 46 38.09634  
**GPS Location, Long.** 114 5.63394  
**Safety Zone Present:** Yes  
**Type of Structure:** Residential  
**Surrounding Fuels:** Grass, Timber  
**Structure Triage Category:** Defensible, Stand Alone  
**Roof Material:** Composite  
**Heat Traps:** Wood Deck, Rain Gutters, Other Receptor  
**Electrical Power:** Underground  
**Hazards:** Animals, HazMat  
**Access to Site:** T3/4 Engine  
**Comm with ICP:** Radio, Cell Service  
**Water Source:** Faucet / Hose  
**Mitigation Time:** Less Than An Hour  
**Other Resources Needed to Protect:** None  
**Notes:** Attic vents beneath eaves.

**Where is Safety Zone:** East on Holloway Lane to Hwy 93

**Primary Structures:**

**Outbuildings:**

**Defensible Space:** 50-100 Feet

**Siding Material:** Wood

**Gas to Structure:**

**Best Access From:** Off Hwy 93, west Holloway Lane

**Collected By:** Lolo 632  
Photo 1

**Collected Date/Time:** 07/30/2017 10:09:54  
Photo 2



Photo 3



Photo 4



## Structure Triage Information



**Structure Number:**  
**Structure Name:** 437 Holloway Lane  
**SubDivision:** One Horse  
**GPS Location, Lat.** 46 38.07282  
**GPS Location, Long.** 114 6.82386  
**Safety Zone Present:** Yes  
**Type of Structure:** Residential  
**Surrounding Fuels:** Grass  
**Structure Triage Category:** Defensible, Stand Alone  
**Roof Material:** Composite  
**Heat Traps:** Rain Gutters  
**Electrical Power:** Underground  
**Hazards:** HazMat  
**Access to Site:** T1 Engine  
**Comm with ICP:** Radio, Cell Service  
**Water Source:** Faucet / Hose, Large Pond, Creek  
**Mitigation Time:** None Needed  
**Other Resources Needed to Protect:** None

**Where is Safety Zone:** East of main structure

**Primary Structures:**

**Outbuildings:**

**Defensible Space:** >100 Feet

**Siding Material:** Masonry

**Gas to Structure:** Underground

**Best Access From:** 93 to Holloway

**Notes:** Well maintained ranch with large green meadows, thinned timber, and irrigated throughout. Huge meadow to the south can be used for personnel and possible helicopters.

**Collected By:** Lolo 632  
Photo 1

**Collected Date/Time:** 07/30/2017 10:10:17  
Photo 2



Photo 3



Photo 4



## Structure Triage Information



**Structure Number:**  
**Structure Name:** 441 Tie Chute rd  
**SubDivision:** One Horse  
**GPS Location, Lat.** 46 38.46966  
**GPS Location, Long.** 114 6.15156  
**Safety Zone Present:** No  
**Type of Structure:** Residential  
**Surrounding Fuels:** Grass, Timber

**Where is Safety Zone:** Escape route- Tie Chute Rd to old highway 93.

**Primary Structures:** **Outbuildings:**  
**Defensible Space:** 30-50 Feet

**Structure Triage Category:** Defensible, Prep and Hold  
**Roof Material:** Metal  
**Heat Traps:** Wood Deck  
**Electrical Power:** Underground  
**Hazards:** Fuels  
**Access to Site:** T3/4 Engine  
**Comm with ICP:** Radio  
**Water Source:** Faucet / Hose  
**Mitigation Time:** 4-5 Hours  
**Other Resources Needed to Protect:** One engine crew, sprinkler kit and portable water source. 4 to 5 hours worth of work. line structures, set up sprinklers.

**Siding Material:** Wood

**Gas to Structure:** Aboveground

**Best Access From:** Old highway 93 to Tie Chute

**Notes:** 100 to 200 ft space around the structures has been thinned. Layer of pine litter remains. The driveway is tight for a Type 3 with a good turn around near the house. No other water source other than the on-site well was found. Corral and Barn North of the

**Collected By:** COCO 482  
Photo 1

**Collected Date/Time:** 07/30/2017 10:10:06  
Photo 2



Photo 3

Photo 4



## Structure Triage Information



**Structure Number:**  
**Structure Name:** 448 Holloway Lane  
**SubDivision:** One Horse  
**GPS Location, Lat.** 46 38.02782  
**GPS Location, Long.** 114 5.78496  
**Safety Zone Present:** No  
**Type of Structure:** Residential  
**Surrounding Fuels:** Grass,Shrub,Timber  
**Structure Triage Category:** Defensible, Stand Alone  
**Roof Material:** Metal  
**Heat Traps:** Wood Deck,Rain Gutters  
**Electrical Power:** Overhead  
**Hazards:** HazMat  
**Access to Site:** T3/4 Engine  
**Comm with ICP:** Radio,Cell Service  
**Water Source:** Faucet / Hose  
**Mitigation Time:** None Needed  
**Other Resources Needed to Protect:** None

**Where is Safety Zone:** East on Holloway Lane to Hwy 93

**Primary Structures:**

**Outbuildings:**

**Defensible Space:** 50-100 Feet

**Siding Material:** Wood

**Gas to Structure:**

**Best Access From:** Hwy 93 to Holloway Lane

**Notes:** Structure has Creek on south side of property. Riparian area runs along the side of the house. Good landscaping and clearance around property.

**Collected By:** Lolo 632  
Photo 1

**Collected Date/Time:** 07/30/2017 10:09:15  
Photo 2



Photo 3



Photo 4



## Structure Triage Information



**Structure Number:**  
**Structure Name:** 454 Holloway Ln  
**SubDivision:** One Horse  
**GPS Location, Lat.** 46 38.11584  
**GPS Location, Long.** 114 5.79084  
**Safety Zone Present:** Yes **Where is Safety Zone:** East on Holloway Lane to Hwy 93  
**Type of Structure:** Residential **Primary Structures:** **Outbuildings:**  
**Surrounding Fuels:** Grass,Shrub,Timber **Defensible Space:** 50-100 Feet  
**Structure Triage Category:** Defensible, Stand Alone  
**Roof Material:** Metal **Siding Material:** Vinyl  
**Heat Traps:** Open Eaves,Other Receptor **Gas to Structure:**  
**Electrical Power:** **Best Access From:** Hwy 93 to Holloway  
**Hazards:** Fuels,Animals,HazMat  
**Access to Site:** T3/4 Engine  
**Comm with ICP:** Radio,Cell Service  
**Water Source:** Faucet / Hose  
**Mitigation Time:** 3-4 Hours  
**Other Resources Needed to Protect:** 1 hand crew to prep north side of house. 3-4 hours  
**Notes:** Multiple debris piles in close to proximity to structure.  
Resident is currently residing guest house. 30% of structure is with out siding but covered with tyvek.

**Collected By:** Lolo 632  
Photo 1

**Collected Date/Time:** 07/30/2017 10:09:36  
Photo 2



Photo 3



Photo 4





## Structure Triage Information



**Structure Number:**  
**Structure Name:** 459 Holloway Lane  
**SubDivision:** One Horse  
**GPS Location, Lat.** 46 38.03514  
**GPS Location, Long.** 114 5.7873  
**Safety Zone Present:** Yes **Where is Safety Zone:** East on Holloway Lane to Hwy 93  
**Type of Structure:** Residential **Primary Structures:** **Outbuildings:**  
**Surrounding Fuels:** Grass,Shrub,Timber **Defensible Space:** None  
**Structure Triage Category:** Non-Defensible, Prep and Leave  
**Roof Material:** Metal **Siding Material:** Wood  
**Heat Traps:** Open Eaves,Rain Gutters,Other Receptor  
**Electrical Power:** Overhead **Gas to Structure:**  
**Hazards:** Fuels,HazMat  
**Access to Site:** T3/4 Engine **Best Access From:** Hwy 93 to Holloway Lane  
**Comm with ICP:** Radio,Cell Service  
**Water Source:** Faucet / Hose  
**Mitigation Time:** More Than 5 Hours  
**Other Resources Needed to Protect:** Sprinklers, hand crew with about 5 hours of work  
**Notes:** Multiple areas around main residence and out buildings are open and damaged.

**Collected By:** Lolo 632

**Collected Date/Time:** 07/30/2017 10:08:59

Photo 1

Photo 2



Photo 3

Photo 4



## Structure Triage Information



Structure Number:  
Structure Name: 467 Holloway Lane  
SubDivision: One Horse  
GPS Location, Lat. 46 38.06784  
GPS Location, Long. 114 5.8935  
Safety Zone Present: No  
Type of Structure: Residential  
Surrounding Fuels: Grass, Shrub, Timber

Where is Safety Zone: East on Holloway Lane to Hwy 93

Primary Structures:

Defensible Space: None

Outbuildings:

Structure Triage Category: Non-Defensible, Prep and Leave

Roof Material: Metal Siding Material: Wood

Heat Traps: Wood Deck

Electrical Power: Underground Gas to Structure:

Hazards: HazMat

Access to Site: T3/4 Engine Best Access From: Hwy 93 to Holloway Lane

Comm with ICP: Radio, Cell Service

Water Source: Faucet / Hose

Mitigation Time: More Than 5 Hours

Other Resources: One half days worth of work for a 20 man crew.

Needed to Protect:

Notes: Access to Creek from multiple trails behind house. Riparian area behind house. Brush backs up to house. Ladder fuels into timber present around the structure. Multiple mailboxes could be an additional residence on site. Second mailbox address signed as 4

Collected By: Lolo 632  
Photo 1

Collected Date/Time: 07/30/2017 10:08:54  
Photo 2



Photo 1



Photo 2



Photo 3



Photo 4

### Structure Triage Information



**Structure Number:**  
**Structure Name:** 483 Tie Chute Ln  
**SubDivision:** One Horse  
**GPS Location, Lat.** 46 38.51406  
**GPS Location, Long.** 114 6.3462  
**Safety Zone Present:** No  
**Type of Structure:** Residential  
**Surrounding Fuels:** Grass, Timber  
**Structure Triage Category:** Defensible, Prep and Hold  
**Roof Material:** Composite  
**Heat Traps:** Wood Deck, Rain Gutters  
**Electrical Power:** Underground  
**Hazards:** Fuels, Septic Tank  
**Access to Site:** T3/4 Engine  
**Comm with ICP:** Radio, Cell Service  
**Water Source:** Faucet / Hose  
**Mitigation Time:** 1-2 Hours  
**Other Resources Needed to Protect:** An engine crew can do a little prep around structure  
**Collected By:** COCO 482

**Where is Safety Zone:** Out to Tie Chute to old highway 93 then to highway 93

**Primary Structures:** **Outbuildings:**

**Defensible Space:** 30-50 Feet

**Siding Material:** Wood

**Gas to Structure:** Underground

**Best Access From:** Tie Chute to old highway 93 to highway 93

**Collected Date/Time:** 07/30/2017 10:09:29

Photo 1

Photo 2



Photo 3

Photo 4

## Structure Triage Information



**Structure Number:**  
**Structure Name:** 510 Trenk way  
**SubDivision:** One Horse  
**GPS Location, Lat.** 46 38.24298  
**GPS Location, Long.** 114 6.0096  
**Safety Zone Present:** Yes **Where is Safety Zone:** Field 100 yds south of structures  
**Type of Structure:** Residential **Primary Structures:** **Outbuildings:**  
**Surrounding Fuels:** Grass, Timber **Defensible Space:** None  
**Structure Triage Category:** Defensible, Prep and Hold  
**Roof Material:** Metal **Siding Material:** Metal  
**Heat Traps:** Rain Gutters, Other Receptor  
**Electrical Power:** Underground **Gas to Structure:** Aboveground  
**Hazards:** Septic Tank, HazMat  
**Access to Site:** T1 Engine **Best Access From:** 93 to Holloway to Trenk way  
**Comm with ICP:** Radio, Cell Service  
**Water Source:** Faucet / Hose  
**Mitigation Time:** 2-3 Hours  
**Other Resources Needed to Protect:** Brush hog  
**Collected By:** Lolo 632 **Collected Date/Time:** 07/30/2017 10:08:49

Photo 1



Photo 3



Photo 2



Photo 4

### Structure Triage Information



Structure Number:  
Structure Name: 520 Trenk Way  
SubDivision: One Horse  
GPS Location, Lat. 46 38.1246  
GPS Location, Long. 114 6.16716  
Safety Zone Present: Yes  
Type of Structure: Residential  
Surrounding Fuels: Grass,Shrub,Timber  
Structure Triage Category: Non-Defensible, Rescue, Drive By  
Roof Material:  
Heat Traps:  
Electrical Power:  
Hazards:  
Access to Site:  
Comm with ICP: Radio,Cell Service  
Water Source:  
Mitigation Time:  
Notes: Home owner not home, Division said owner wasn't very friendly.

Where is Safety Zone: Out Holloway Ln back to Hwy 93

Primary Structures:

Outbuildings:

Defensible Space:

Siding Material:

Gas to Structure:

Best Access From:

Collected By: Lolo 632

Photo 1

Collected Date/Time: 07/30/2017 10:09:17

Photo 2



Photo 3



Photo 4

## Structure Triage Information



**Structure Number:**

**Structure Name:** 595 Tie Chute Ln

**SubDivision:** One Horse

**GPS Location, Lat.** 46 38.52282

**GPS Location, Long.** 114 6.93036

**Safety Zone Present:** No

**Type of Structure:** Residential

**Surrounding Fuels:** Timber, None

**Structure Triage**

**Category:** Defensible, Prep and Hold

**Roof Material:** Composite

**Heat Traps:** Open Eaves

**Electrical Power:** Overhead, Underground

**Hazards:**

**Access to Site:** T1 Engine

**Comm with ICP:** Radio, Cell Service

**Water Source:** Faucet / Hose

**Mitigation Time:** Less Than An Hour

**Notes:** New construction, half built... update in future

**Where is Safety Zone:** Tie Chute lane to Old Highway 93, to designated safety zone

**Primary Structures:**

**Outbuildings:**

**Defensible Space:** 30-50 Feet

**Siding Material:** Wood

**Gas to Structure:** None

**Best Access From:** Old Highway 93 to Tie Chute Lane

Son owns property to the west and uphill

**Collected By:** COCO 482

Photo 1

**Collected Date/Time:** 07/30/2017 10:10:08

Photo 2



Photo 3

Photo 4

## Structure Triage Information



**Structure Number:**  
**Structure Name:** 609 Tie Chute Ln  
**SubDivision:** One Horse  
**GPS Location, Lat.** 46 38.5242  
**GPS Location, Long.** 114 7.01808  
**Safety Zone Present:** No  
**Type of Structure:** Residential  
**Surrounding Fuels:** Grass, Timber  
**Structure Triage Category:** Defensible, Prep and Hold  
**Roof Material:** Metal  
**Heat Traps:** Other Receptor  
**Electrical Power:** Underground  
**Hazards:** Terrain, Fuels  
**Access to Site:** T3/4 Engine  
**Comm with ICP:** Radio, Cell Service  
**Water Source:** Faucet / Hose, Creek  
**Mitigation Time:** 1-2 Hours  
**Other Resources Needed to Protect:** One Engine, sprinkler kit portable water source, portable pump, there's a nearby stream that may be used as a water source.  
**Notes:** Secondary structure under construction, defensible spaces 15 - 20 ft Timber round structures has been thinned but area does have potential to carry ground fire, there's a nearby large Creek that could be used as a potential water source. Creek is 7 chai

**Where is Safety Zone:** ESCAPE ROUTE- out Tie Chute to old highway 93  
**Primary Structures:**  
**Defensible Space:** 30-50 Feet  
**Outbuildings:**  
**Siding Material:** Metal  
**Gas to Structure:** None  
**Best Access From:** Old highway 93 to Tie Chute Rd

**Collected By:** COCO 482  
Photo 1

**Collected Date/Time:** 07/30/2017 10:09:18  
Photo 2



Photo 1



Photo 2



Photo 3



Photo 4

### Structure Triage Information



**Structure Number:**  
**Structure Name:** 620 Trenk way  
**SubDivision:** One Horse  
**GPS Location, Lat.** 46 38.15292  
**GPS Location, Long.** 114 5.92956  
**Safety Zone Present:** Yes  
**Type of Structure:** Residential  
**Surrounding Fuels:** Grass, Timber  
**Structure Triage Category:** Defensible, Prep and Hold  
**Roof Material:** Metal  
**Heat Traps:** Wood Deck, Rain Gutters  
**Electrical Power:** Underground  
**Hazards:** HazMat  
**Access to Site:** T1 Engine  
**Comm with ICP:** Radio, Cell Service  
**Water Source:** Faucet / Hose  
**Mitigation Time:** Less Than An Hour  
**Other Resources Needed to Protect:** None  
**Notes:** Fuel in gutters. Two wood decks.

**Where is Safety Zone:** 50 yards west

**Primary Structures:**

**Outbuildings:**

**Defensible Space:** 50-100 Feet

**Siding Material:** Wood

**Gas to Structure:** Underground

**Best Access From:** 93 to Holloway to Trenk way

**Collected By:** Lolo 632

Photo 1

**Collected Date/Time:** 07/30/2017 10:09:39

Photo 2



Photo 3



Photo 4





## Structure Triage Information



**Structure Number:**  
**Structure Name:** 625 Tie Chute Lane  
**SubDivision:** One Horse  
**GPS Location, Lat.** 46 38.47602  
**GPS Location, Long.** 114 5.89572  
**Safety Zone Present:** No  
**Type of Structure:** Residential  
**Surrounding Fuels:** Grass, Timber  
**Structure Triage Category:** Defensible, Prep and Hold  
**Roof Material:** Composite  
**Heat Traps:** Wood Deck, Rain Gutters  
**Electrical Power:** Overhead, Underground  
**Hazards:** Fuels  
**Access to Site:** T1 Engine  
**Comm with ICP:** Radio, Cell Service  
**Water Source:** Faucet / Hose  
**Mitigation Time:** 1-2 Hours  
**Other Resources Needed to Protect:** One sprinkler kit  
**Notes:** Metal roof garage is first building you come to on property... to the north of the main residence

**Where is Safety Zone:** Tie Chute Lane to Old Highway 93

**Primary Structures:**

**Outbuildings:**

**Defensible Space:** 30-50 Feet

**Siding Material:** Wood

**Gas to Structure:** Underground

**Best Access From:** Old Highway 93 to Tie Shoot Lane

**Collected By:** COCO 482  
Photo 1

**Collected Date/Time:** 07/30/2017 10:09:27  
Photo 2



Photo 3



Photo 4



## Structure Triage Information



Structure Number:  
Structure Name: 627 Tie Chute Ln  
SubDivision: One Horse  
GPS Location, Lat. 46 38.52486  
GPS Location, Long. 114 7.17606

Tie Chute out Old Hwy 93. 2 Type 6 Engines could fit in yard next to main house.

Safety Zone Present: No  
Type of Structure: Residential  
Surrounding Fuels: Grass, Timber

Where is Safety Zone: house.  
Primary Structures:

Outbuildings:

Defensible Space: 30-50 Feet

### Structure Triage

Category: Defensible, Prep and Hold  
Roof Material: Metal  
Heat Traps: Open Eaves, Wood Deck, Rain Gutters  
Electrical Power: Underground  
Hazards: Animals  
Access to Site: T3/4 Engine  
Comm with ICP: Radio, Cell Service  
Water Source: Faucet / Hose, Porta-Tank/Pumpkin, Creek  
Mitigation Time: 1-2 Hours  
Other Resources Needed to Protect: Type 3 Engine  
Notes: Water tank next door.

Siding Material: Metal

Gas to Structure: Aboveground

Best Access From: Old Hwy 93 to Tie Chute

Collected By: AZ-TNF 1265  
Photo 1

Collected Date/Time: 07/30/2017 10:09:26  
Photo 2



Photo 3



Photo 4



## Structure Triage Information



**Structure Number:**  
**Structure Name:** ? Hughs Lane  
**SubDivision:** One Horse  
**GPS Location, Lat.** 46 38.06784  
**GPS Location, Long.** 114 5.26632  
**Safety Zone Present:** Yes  
**Type of Structure:** Residential  
**Surrounding Fuels:** Grass, Timber  
**Structure Triage Category:** Defensible, Prep and Hold  
**Roof Material:** Metal  
**Heat Traps:** Other Receptor  
**Electrical Power:** Underground  
**Hazards:** Fuels  
**Access to Site:** T1 Engine  
**Comm with ICP:** Radio, Cell Service  
**Water Source:** Faucet / Hose  
**Mitigation Time:** More Than 5 Hours  
**Other Resources Needed to Protect:** Heavy pile, needs to be covered. lots of weedwacking in the back, continuous fuels to the house.  
**Notes:** Could not find property number

**Where is Safety Zone:** Down the road to park on Florence Carlton Loop

**Primary Structures:** **Outbuildings:**

**Defensible Space:** 30-50 Feet

**Siding Material:** Metal

**Gas to Structure:** Underground

**Best Access From:** Hugh's Lane from Florence Carlton

**Collected By:** Engine 951  
Photo 1

**Collected Date/Time:** 07/30/2017 10:09:47  
Photo 2



Photo 3

Photo 4



