



STHERN 4

Structure Number:	169		FED TEAM
Structure Name:	FS #2		2 1-17-10-2
SubDivision:	<b>Cottonwood Guard Station</b>		S. LL VE
GPS Location, Lat.	48 1.25178		
GPS Location, Long.	120 38.45526		ANAGE
Safety Zone Present:	No	Where is Safety Zone: No safety zone present.	
Type of Structure:	Other	Primary Structures: 1	Outbuildings: 4
Other Type of	Government Building		
Surrounding Fuels:	Shrub,Timber,Slash	Defensible Space	e: 50-100 Feet
Structure Triage			
Category:	Non-Defensible, Prep and Le	ave	
Roof Material:	Metal	Siding Materia	I: Wood
Heat Traps:	Wood Deck, Other Receptor		
Electrical Power:	Solar/Wind	Gas to Structure	e: Aboveground
Hazards:	Terrain, Fuels, Haz Mat		
Hazard Notes:	500 gal LPG tank on site, no	safety zone.	
Access to Site:	T3/4 Engine	Best Access From: Located at the end of E	ntiat River Road MP 37.5 on left.
Comm with ICP:	Radio		
Water Source:	Faucet / Hose,Creek		
Mitigation Time:	1-2 Hours		
Other Resources			
Needed to Protect:	Hose lay with sprinkler kits, s	scratch line around all structures, use structure	e wrap where needed.
Notes:	debris and all heat traps have bee buildings have hand line scratched	n covered with structure wrap. There is also a large ba I around them and have been structure wrapped wher	with a clean metal roof and wood siding. Roof is clear of rn and tac shop on site with three other misc outbuildings. All re necessary. All structures in the compound have been
	nroximity to established safety zo		prep and leave due to lack of safety zones and distance in
Collected By:	Jay Walter Photo 1	Collected Date/Time:	08/03/2014 07:03:47 GMT-07:00 Photo 2









Structure Number:	144		FED TLAN
Structure Name:	PH #4-2		2 000000
SubDivision:	Pope Summer Homes		S. LL P
GPS Location, Lat.	47 58.56648		
GPS Location, Long.	120 33.70884		24NAGE
Safety Zone Present:	No	Where is Safety Zone: Safety zone is located 7	miles south on Entiat River Road.
Type of Structure:	Residential	Primary Structures: 1	Outbuildings: 3
Other Type of			
Surrounding Fuels:	Shrub, Timber, Slash	Defensible Space	e: 50-100 Feet
Structure Triage			
Category:	Non-Defensible, Prep and Le	ave	
Roof Material:	Wood	Siding Materia	I: Wood
Heat Traps:	Open Eaves, Wood Deck, Oth	er Receptor	
Electrical Power:	Generator	Gas to Structure	e: Aboveground
Hazards:	Fuels		
Hazard Notes:	250 gal LPG tank on site.		
Access to Site:	T3/4 Engine	Best Access From: West on unnamed drive	eway marked #4 west of Entiat River Road.
Comm with ICP:	Radio		
Water Source:	Creek		
Mitigation Time:	1-2 Hours		
Other Resources			
Needed to Protect:	Hose lay with sprinkler kits,	scratch line around structure, use structure wr	ap where needed .
Notes:	comprised wood siding with a dire	ty wood roof. Heat traps and decks are present but clear able driveway located off of main roadway in a small gro	Summer Homes. Structure's primary building construction is ar of debris and combustible materials. Access to the oup of structures. Structure 4-2 is non-defendable prep and
Collected By:	Jay Walter Photo 1	Collected Date/Time:	08/03/2014 08:18:07 GMT-07:00 Photo 2



Photo 3

Photo 4

STHERN 2



Structure Number:	161	FED TLAN . 2
Structure Name:	PH #5-1	2 Dorthoga
SubDivision:	Pope Summer Homes	ST. EL VE
GPS Location, Lat.	47 58.60398	
GPS Location, Long.	120 33.7347	**ANAGE***
Safety Zone Present:	No	Where is Safety Zone: Safety zone is located 7 miles south on Entiat River Road.
Type of Structure:	Residential	Primary Structures: 1 Outbuildings: 1
Other Type of		
Surrounding Fuels:	Shrub,Timber,Slash	Defensible Space: 50-100 Feet
Structure Triage		
Category:	Non-Defensible, Prep and Le	ave
Roof Material:	Metal	Siding Material: Wood
Heat Traps:	Open Eaves, Other Receptor	
Electrical Power:	Generator	Gas to Structure: Aboveground
Hazards:	Fuels, Haz Mat	
Hazard Notes:	25 gal LPG tank on site.	
Access to Site:	T3/4 Engine	Best Access From: West on unnamed driveway marked #5 west of Entiat River Road.
Comm with ICP:	Radio	
Water Source:	Creek	
Mitigation Time:	1-2 Hours	
Other Resources		
Needed to Protect:	His lay with sprinkler kits, scr	atch line around structure, use structure wrap where needed.
Notes:	wood siding with a clean metal ro	e located along the Entiat River in the Pope Summer Homes. Structure's primary building construction is comprised of. Heat traps and decks are present but clear of debris and combustible materials. Access to the structure is by a ated off of main roadway in a small group of structures. Structure 5-1 is non-defendable prep and leave due to lack
Collected By:	Jay Walter	Collected Date/Time: 08/03/2014 07:06:40 GMT-07:00
	Photo 1	Photo 2
AN OWNER STREET		



Photo 3

Photo 4

THERN &



Structure Number:	142		FED TIAN
Structure Name:	PH #6-1		a Contrata
SubDivision:	Pope Summer Homes		St. B-LE
GPS Location, Lat.	47 58.64838		
GPS Location, Long.	120 33.79032		24NAG2
Safety Zone Present:	No	Where is Safety Zone: Safety zone is located 7	miles south on Entiat River Road.
Type of Structure:	Residential	Primary Structures: 1	Outbuildings: 2
Other Type of			
Surrounding Fuels:	Shrub, Timber, Slash	Defensible Space	e: 30-50 Feet
Structure Triage			
Category:	Non-Defensible, Prep and Le	ave	
Roof Material:	Metal	Siding Materia	I: Wood
Heat Traps:	Open Eaves, Other Receptor		
Electrical Power:	Generator	Gas to Structure	e: Aboveground
Hazards:	Fuels, Haz Mat		
Hazard Notes:	250 gal LPG tank on site.		
Access to Site:	T3/4 Engine	Best Access From: West on unnamed drive	eway marked #6 west of Entiat River Road.
Comm with ICP:	Radio		
Water Source:	Creek		
Mitigation Time:	1-2 Hours		
Other Resources			
Needed to Protect:	Hose lay with sprinkler kit, se	cratch line around structure, use structure wra	p where needed.
Notes:	wood siding with a clean metal ro	of. Heat traps and decks are present but clear of debris	omes. Structure's primary building construction is comprised and combustible materials. Access to the structure is by a s. Structure 4-1 is non-defendable prep and leave due to lack
Collected By:	Jay Walter Photo 1	Collected Date/Time:	08/03/2014 08:18:51 GMT-07:00 Photo 2



Photo 3

Photo 4

THERN &



STHERN 4

Structure Number:	141		FED TLAN	
Structure Name:	PH #7-1		2 000000	
SubDivision:	Pope Summer Homes		ST. EP. S	
GPS Location, Lat.	47 58.64994			
GPS Location, Long.	120 33.8577		**ANAGE**	
Safety Zone Present:	No	Where is Safety Zone: Safety zone is located 7	miles south on the Entiat River Road.	
Type of Structure:	Residential	Primary Structures: 1	Outbuildings: 1	
Other Type of				
Surrounding Fuels:	Shrub, Timber, Slash	Defensible Space	e: 30-50 Feet	
Structure Triage				
Category:	Non-Defensible, Prep and	Leave		
Roof Material:	Metal	Siding Materia	I: Wood	
Heat Traps:	Open Eaves,Wood Deck,O	Open Eaves,Wood Deck,Other Receptor		
Electrical Power:	Generator	Gas to Structure	e: Aboveground	
Hazards:	Fuels, Haz Mat			
Hazard Notes:	250 gal LPG tank on site.			
Access to Site:	T3/4 Engine	Best Access From: West on unnamed drive	eway marked #7 west of Entiat River Road.	
Comm with ICP:	Radio			
Water Source:	Creek			
Mitigation Time:	1-2 Hours			
Other Resources				
Needed to Protect:	Hose lay with sprinkler kit	s, scratch line around structure, use structure wr	ap where needed.	
Notes:	wood siding with a clean wood	roof. Heat traps and decks are present but clear of debris	omes. Structure's primary building construction is comprised and combustible materials. Access to the structure is by a s. Structure 7-1 is non-defendable prep and leave due to lack	
Collected By:	Jay Walter	Collected Date/Time:	08/03/2014 08:19:10 GMT-07:00	
	Photo 1		Photo 2	
	201			



Phota Phota

STHERN 2

Structure Number:	164		FED TLAN
Structure Name:	PH #7-2		S I COME
SubDivision:	Pope Summer Homes		S. BHAR
GPS Location, Lat.	47 5.86668		
GPS Location, Long.	120 33.92604		TANAGE
Safety Zone Present:	No	Where is Safety Zone: Safety zone is located 7	miles south on Entiat River Road.
Type of Structure:	Residential	Primary Structures: 1	Outbuildings: 2
Other Type of			
Surrounding Fuels:	Shrub, Timber, Slash	Defensible Space	: 30-50 Feet
Structure Triage			
Category:	Non-Defensible, Prep and Le	ave	
Roof Material:	Metal	Siding Material	: Wood
Heat Traps:	Wood Deck, Other Receptor		
Electrical Power:	Generator	Gas to Structure	: Aboveground
Hazards:	Fuels, Haz Mat		
Hazard Notes:	500 gal LPG tank on site.		
Access to Site:	T3/4 Engine	Best Access From: West on unnamed drive	way marked with #7 west of Entiat River Road.
Comm with ICP:	Radio		
Water Source:	Creek		
Mitigation Time:	1-2 Hours		
Other Resources			
Needed to Protect:	Hose lay with sprinkler kits, s	cratch line around structure, use structure wra	ap where needed.
Notes:	comprised wood siding with a clea	in metal roof. Heat traps and decks are present but clea ble driveway located off of main roadway in a small gro	Immer Homes. Structure's primary building construction is ar of debris and combustible materials. Access to the pup of structures. Structure 7-2 is non-defendable prep and
Collected By:	Jay Walter	Collected Date/Time:	08/03/2014 07:05:45 GMT-07:00






THERN &

Structure Number:	139		FED TLAN
Structure Name:	PH #7-3		2 0000003
SubDivision:	Pope Summer Homes		S. EL S
GPS Location, Lat.	47 58.66398		
GPS Location, Long.	120 33.94302		24NAGE
Safety Zone Present:	No	Where is Safety Zone: Safety zone is located 7	miles south on entiate River Road.
Type of Structure:	Residential	Primary Structures: 1	Outbuildings: 2
Other Type of			
Surrounding Fuels:	Shrub, Timber, Slash	Defensible Space	:: 30-50 Feet
Structure Triage			
Category:	Non-Defensible, Prep and Le	ave	
Roof Material:	Metal	Siding Material	l: Wood
Heat Traps:	Open Eaves, Other Receptor		
Electrical Power:	Generator	Gas to Structure	e: Aboveground
Hazards:	Fuels, Haz Mat		
Hazard Notes:	25 gal LPG tank on site.		
Access to Site:	T3/4 Engine	Best Access From: West on unnamed drive	way marked #7 west of Entiat River Road.
Comm with ICP:	Radio		
Water Source:	Creek		
Mitigation Time:	1-2 Hours		
Other Resources			
Needed to Protect: Notes:	Structure is a single story structure wood siding with a clean metal room	of. Heat traps and decks are present but clear of debris	ap where needed. omes. Structure's primary building construction is comprised and combustible materials. Access to the structure is by a . Structure 7-3 is non-defendable prep and leave due to lack
Collected By:	Jay Walter Photo 1	Collected Date/Time:	08/03/2014 08:19:50 GMT-07:00 Photo 2



<image>







Structure Name:       PH #7-5         SubDivision:       Pope Summer Homes         GPS Location, Lat.       47 58.67772         GPS Location, Long.       120 34.01034         Safety Zone Present:       No       Where is Safety Zone: Safety zone is located 7 miles south on Entiat River Road.         Type of Structure:       Residential       Primary Structures: 1       Outbuildings: 0         Other Type of       Structure Triage       Structure Triage       Structure Triage         Category:       Non-Defensible, Prep and Leave       Siding Material: Wood       Heat Traps:       Open Eaves,Wood Deck,Other Receptor         Electrical Power:       Generator       Gas to Structure: Aboveground       Hazard Structure: Safety Zone Structure: Aboveground         Hazard Store:       Tj4 Engine       Best Access From: West on unnamed driveway marked #7 west of Entiat River Road.         Comm with ICP:       Radio         Water Source:       Creek         Mitigation Time:       1 - 2 Hours         Wither Source:       Structure is a single story structure located along the Entiat River in the Pope Summer Homes. Structure's primary building construction is comprised wood siding with a clean asphalt shingle roof. Heat traps and decks are present but clear of debris and combustible materials. Access to the structure is by a narrow but passable driveway located off of main roadway in a small group of structure's 5 is non-defendable prep and l	Structure Number:	137		FED TLAN
GPS Location, Lat.       47 58.67772         GPS Location, Long.       120 34.01034         Safety Zone Present:       No       Where is Safety Zone: Safety Zone is located 7 miles south on Entiat River Road.         Type of Structure:       Residential       Primary Structures: 1       Outbuildings: 0         Other Type of       Surrounding Fuels:       Shrub, Timber, Slash       Defensible Space: 30-50 Feet         Structure Triage       Category:       Non-Defensible, Prep and Leave       Soding Material: Wood         Heat Traps:       Open Eaves, Wood Deck, Other Receptor       Electrical Power:       Generator       Gas to Structure: Aboveground         Hazard Notes:       5 gal LPG tank on site.       Access to Site:       T3/4 Engine       Best Access From: West on unnamed driveway marked #7 west of Entiat River Road.         Comm with ICP:       Radio       Water Source:       Creek       Mitigation Time:       1-2 Hours         Where source:       Creek       Hose lay with sprinkler kits, scratch line around structure, use structure wrap where needed.       Notes:       Structure is a single story structure located along the Entiat River in the Pope Summer Homes. Structure's primary building construction is comprised wood siding with a clean asphalt shingle roof. Heat traps and decks are present but clear of debris and combustible materials. Access to the structure is by a arrow but passable driveway located off of main roadway in a small group of structures. Structure 7-5 is n	Structure Name:	PH #7-5		2 CONTRACT
GPS Location, Long.       120 34.01034         Safety Zone Present:       No       Where is Safety Zone: Safety zone is located 7 miles south on Entiat River Road.         Type of Structure:       Residential       Primary Structures: 1       Outbuildings: 0         Other Type of       Surrounding Fuels:       Shrub,Timber,Slash       Defensible Space: 30-50 Feet         Structure Triage       Category:       Non-Defensible, Prep and Leave       Siding Material: Wood         Roof Material:       Composite       Siding Material: Wood       Heat Traps:         Open Eaves,Wood Deck,Other Receptor       Electrical Power:       Generator       Gas to Structure: Aboveground         Hazards:       Fuels,HazMat       Hazards:       S gal LPG tank on site.       Access to Site:       T3/4 Engine       Best Access From: West on unnamed driveway marked #7 west of Entiat River Road.       Comm with ICP:       Radio         Water Source:       Creek	SubDivision:	Pope Summer Homes		ST. EL E
Safety Zone Present:       No       Where is Safety Zone: Safety zone is located 7 miles south on Entiat River Road.         Type of Structure:       Residential       Primary Structures: 1       Outbuildings: 0         Other Type of       Surrounding Fuels:       Shrub,Timber,Slash       Defensible Space: 30-50 Feet         Structure Triage       Category:       Non-Defensible, Prep and Leave       Siding Material: Wood         Roof Material:       Composite       Siding Material: Wood       Heat Traps:         Open Eaves,Wood Deck,Other Receptor       Electrical Power:       Generator       Gas to Structure: Aboveground         HazardS:       Fuels,HazMat       HazardS:       S gal LPG tank on site.       Access to Site:       T3/4 Engine       Best Access From: West on unnamed driveway marked #7 west of Entiat River Road.       Comm with ICP:       Radio         Water Source:       Creek       Integration Time:       1-2 Hours       I-2 Hours       Integration Structure is a single story structure located along the Entiat River in the Pope Summer Homes. Structure's primary building construction is comprised wood siding with a clean asphalt shingle roof. Heat traps and decks are present but clear of debris and combustible materials. Access to the structure is by a narrow but passable driveway located off of main roadway in a small group of structure. Structure 7.5 is non-defendable prep and leave due to lack of safety zone present on site.         Collected By:       Jay Walter       Collecte	GPS Location, Lat.	47 58.67772		
Type of Structure:       Residential       Primary Structures: 1       Outbuildings: 0         Other Type of       Surrounding Fuels:       Shrub, Timber, Slash       Defensible Space: 30-50 Feet         Structure Triage       Structure Triage       Category:       Non-Defensible, Prep and Leave         Roof Material:       Composite       Siding Material: Wood         Heat Traps:       Open Eaves,Wood Deck,Other Receptor         Electrical Power:       Generator       Gas to Structure: Aboveground         HazardS:       Fuels,HazMat         Hazard Notes:       Sigl LPG tank on site.         Access to Site:       T3/4 Engine       Best Access From: West on unnamed driveway marked #7 west of Entiat River Road.         Comm with ICP:       Radio       Structure is a single story structure located along the Entiat River, use structure way where needed.         Notes:       Structure is a single story structure located along the Entiat River in the Pope Summer Homes. Structure's primary building construction is comprised wood siding with a clean asphalt shingle roof. Heat traps and decks are present but clear of debris and combustible materials. Access to the structure is by a narrow but passable driveway located off of main roadway in a small group of structures. Structure 7-5 is non-defendable prep and leave due to lack of safety zone present on site.         Collected By:       Jay Walter       Collected Date/Time:       08/03/2014 08:20:27 GMT-07:00	GPS Location, Long.	120 34.01034		***ANAGE**
Other Type of       Defensible Space: 30-50 Feet         Surrounding Fuels:       Shrub, Timber, Slash       Defensible Space: 30-50 Feet         Structure Triage       Category:       Non-Defensible, Prep and Leave         Roof Material:       Composite       Siding Material: Wood         Heat Traps:       Open Eaves, Wood Deck, Other Receptor       Electrical Power:         Electrical Power:       Generator       Gas to Structure: Aboveground         Hazards:       Fuels, HazMat       Access to Site:       T3/4 Engine         Hazard Notes:       5 gal LPG tank on site.       Access to Site:       T3/4 Engine       Best Access From: West on unnamed driveway marked #7 west of Entiat River Road.         Comm with ICP:       Radio       Vater Source:       Creek         Mitigation Time:       1-2 Hours       I-2 Hours       Structure is a single story structure located along the Entiat River in the Pope Summer Homes. Structure's primary building construction is comprised wood stifue with a sprinkler kits, scratch line around structure, use structure strue's primary building construction is comprised wood stifue word but passable driveway located of of main roadway in a small group of structure? 5 is non-defendable prep and leave due to lack of safety zone present on site.         Collected By:       Jay Walter       Collected Date/Time:       08/03/2014 08:20:27 GMT-07:00	Safety Zone Present:	No	Where is Safety Zone: Safety zone is located 7	miles south on Entiat River Road.
Surrounding Fuels:Shrub, Timber, SlashDefensible Space: 30-50 FeetStructure TriageCompositeSiding Material: WoodCategory:Non-Defensible, Prep and LeaveRoof Material:CompositeSiding Material: WoodHeat Traps:Open Eaves, Wood Deck, Other ReceptorElectrical Power:GeneratorGas to Structure: AbovegroundHazardS:Fuels, HazMatHazard Notes:5 gal LPG tank on site.Access to Site:T3/4 EngineBest Access From: West on unnamed driveway marked #7 west of Entiat River Road.Comm with ICP:RadioWater Source:CreekMitigation Time:1-2 HoursOther ResourcesStructure is a single story structure located along the Entiat River in the Pope Summer Homes. Structure's primary building construction is comprised wood siding with a clean asphalt shingle roof. Heat traps and decks are present but clear of debris and combustible materials. Access to the structure is by a narrow but passable driveway located off of main roadway in a small group of structure 7-5 is non-defendable prep and leave due to lack of safety zone present on site.Collected By:Jay WalterCollected Date/Time: 08/03/2014 08:20:27 GMT-07:00	Type of Structure:	Residential	Primary Structures: 1	Outbuildings: 0
Structure Triage         Category:       Non-Defensible, Prep and Leave         Roof Material:       Composite         Roof Material:       Composite         Stiding Material:       Wood         Heat Traps:       Open Eaves, Wood Deck, Other Receptor         Electrical Power:       Generator         Generator       Gas to Structure: Aboveground         Hazards:       Fuels, HazMat         Hazards:       S gal LPG tank on site.         Access to Site:       T3/4 Engine         Best Access From:       West on unnamed driveway marked #7 west of Entiat River Road.         Comm with ICP:       Radio         Water Source:       Creek         Mitigation Time:       1-2 Hours         Other Resources       Hose lay with sprinkler kits, scratch line around structure, use structure wrap where needed.         Notes:       Structure is a single story structure located along the Entiat River in the Pope Summer Homes. Structure's primary building construction is comprised wood siding with a clean asphalt shingle roof. Heat traps and decks are present but clear of debris and combustible materials. Access to the structure is by a narrow but passable driveway located off of main roadway in a small group of structures. Structure 7-5 is non-defendable prep and leave due to lack of safety zone present on site.         Collected By:       Jay Walter       Collected Date/Time: 08/03/2014 08:20:27 GMT-07:00	Other Type of			
Category:Non-Defensible, Prep and LeaveRoof Material:CompositeSiding Material: WoodHeat Traps:Open Eaves,Wood Deck,Other ReceptorElectrical Power:GeneratorGas to Structure: AbovegroundHazards:Fuels,HazMatHazard Notes:5 gal LPG tank on site.Access to Site:T3/4 EngineBest Access From: West on unnamed driveway marked #7 west of Entiat River Road.Comm with ICP:RadioWater Source:CreekMitigation Time:1-2 HoursOther ResourcesHose lay with sprinkler kits, scratch line around structure, use structure wrap where needed.Notes:Structure is a single story structure located along the Entiat River in the Pope Summer Homes. Structure 's primary building construction is comprised wood siding with a clean asphalt shingle roof. Heat traps and decks are present but clear of debris and combustible materials. Access to the structure is by a narrow but passable driveway located off of main roadway in a small group of structure 7-5 is non-defendable prep and leave due to lack of safety zone present on site.Collected By:Jay WalterCollected Date/Time: 08/03/2014 08:20:27 GMT-07:00	Surrounding Fuels:	Shrub, Timber, Slash	Defensible Space	:: 30-50 Feet
Roof Material:CompositeSiding Material: WoodHeat Traps:Open Eaves,Wood Deck,Other ReceptorElectrical Power:GeneratorGas to Structure: AbovegroundHazards:Fuels,HazMatHazard Notes:5 gal LPG tank on site.Access to Site:T3/4 EngineBest Access From: West on unnamed driveway marked #7 west of Entiat River Road.Comm with ICP:RadioWater Source:CreekMitigation Time:1-2 HoursOther ResourcesFoelaw with sprinkler kits, scratch line around structure, use structure wrap where needed.Notes:Structure is a single story structure located along the Entiat River in the Pope Summer Homes. Structure's primary building construction is comprised wood siding with a clean asphalt shingle roof. Heat traps and decks are present but clear of debris and combustible materials. Access to the structure is by a narrow but passable driveway located off of main roadway in a small group of structure. Structure 7-5 is non-defendable prep and leave due to lack of safety zone present on site.Collected By:Jay WalterCollected Date/Time:08/03/2014 08:20:27 GMT-07:00	Structure Triage			
Heat Traps:       Open Eaves, Wood Deck, Other Receptor         Electrical Power:       Generator         Generator:       Gas to Structure: Aboveground         Hazards:       Fuels, HazMat         Hazard Notes:       5 gal LPG tank on site.         Access to Site:       T3/4 Engine         Best Access From: West on unnamed driveway marked #7 west of Entiat River Road.         Comm with ICP:       Radio         Water Source:       Creek         Mitigation Time:       1-2 Hours         Other Resources       Fuelay with sprinkler kits, scratch line around structure, use structure wrap where needed.         Notes:       Structure is a single story structure located along the Entiat River in the Pope Summer Homes. Structure's primary building construction is comprised wood siding with a clean asphalt shingle roof. Heat traps and decks are present but clear of debris and combustible materials. Access to the structure is by a narrow but passable driveway located off of main roadway in a small group of structures. Structure 7-5 is non-defendable prep and leave due to lack of safety zone present on site.         Collected By:       Jay Walter       Collected Date/Time: 08/03/2014 08:20:27 GMT-07:00	Category:	Non-Defensible, Prep and	Leave	
Electrical Power:       Generator       Gas to Structure: Aboveground         Hazards:       Fuels,HazMat         Hazards:       Fuels,HazMat         Hazard Notes:       5 gal LPG tank on site.         Access to Site:       T3/4 Engine         Best Access From: West on unnamed driveway marked #7 west of Entiat River Road.         Comm with ICP:       Radio         Water Source:       Creek         Mitigation Time:       1-2 Hours         Other Resources       Hose lay with sprinkler kits, scratch line around structure, use structure wrap where needed.         Notes:       Structure is a single story structure located along the Entiat River in the Pope Summer Homes. Structure's primary building construction is comprised wood siding with a clean asphalt shingle roof. Heat traps and decks are present but clear of debris and combustible materials. Access to the structure to lack of safety zone present on site.         Collected By:       Jay Walter	Roof Material:	Composite	Siding Material	l: Wood
Hazards:       Fuels,HazMat         Hazard Notes:       5 gal LPG tank on site.         Access to Site:       T3/4 Engine         Best Access From:       West on unnamed driveway marked #7 west of Entiat River Road.         Comm with ICP:       Radio         Water Source:       Creek         Mitigation Time:       1-2 Hours         Other Resources       Hose lay with sprinkler kits, scratch line around structure, use structure wrap where needed.         Notes:       Structure is a single story structure located along the Entiat River in the Pope Summer Homes. Structure's primary building construction is comprised wood siding with a clean asphalt shingle roof. Heat traps and decks are present but clear of debris and combustible materials. Access to the structure is by a narrow but passable driveway located off of main roadway in a small group of structure. Structure 7-5 is non-defendable prep and leave due to lack of safety zone present on site.         Collected By:       Jay Walter       Collected Date/Time: 08/03/2014 08:20:27 GMT-07:00	Heat Traps:	Open Eaves,Wood Deck,Other Receptor		
Hazard Notes:       5 gal LPG tank on site.         Access to Site:       T3/4 Engine         Best Access From: West on unnamed driveway marked #7 west of Entiat River Road.         Comm with ICP:       Radio         Water Source:       Creek         Mitigation Time:       1-2 Hours         Other Resources       Vater Structure is a single story structure located along the Entiat River in the Pope Summer Homes. Structure's primary building construction is comprised wood siding with a clean asphalt shingle roof. Heat traps and decks are present but clear of debris and combustible materials. Access to the structure is by a narrow but passable driveway located off of main roadway in a small group of structures. Structure 7-5 is non-defendable prep and leave due to lack of safety zone present on site.         Collected By:       Jay Walter	Electrical Power:	Generator	Gas to Structure	: Aboveground
Access to Site:T3/4 EngineBest Access From: West on unnamed driveway marked #7 west of Entiat River Road.Comm with ICP:RadioWater Source:CreekMitigation Time:1-2 HoursOther ResourcesVater Source:Needed to Protect:Hose lay with sprinkler kits, scratch line around structure, use structure wrap where needed.Notes:Structure is a single story structure located along the Entiat River in the Pope Summer Homes. Structure's primary building construction is comprised wood siding with a clean asphalt shingle roof. Heat traps and decks are present but clear of debris and combustible materials. Access to the structure is by a narrow but passable driveway located off of main roadway in a small group of structures. Structure 7-5 is non-defendable prep and leave due to lack of safety zone present on site.Collected By:Jay WalterCollected Date/Time: 08/03/2014 08:20:27 GMT-07:00	Hazards:	Fuels, Haz Mat		
Comm with ICP:RadioWater Source:CreekMitigation Time:1-2 HoursOther ResourcesHose lay with sprinkler kits, scratch line around structure, use structure wrap where needed.Needed to Protect:Hose lay with sprinkler kits, scratch line around structure, use structure wrap where needed.Notes:Structure is a single story structure located along the Entiat River in the Pope Summer Homes. Structure's primary building construction is comprised wood siding with a clean asphalt shingle roof. Heat traps and decks are present but clear of debris and combustible materials. Access to the structure is by a narrow but passable driveway located off of main roadway in a small group of structures. Structure 7-5 is non-defendable prep and leave due to lack of safety zone present on site.Collected By:Jay WalterCollected Date/Time:08/03/2014 08:20:27 GMT-07:00	Hazard Notes:	5 gal LPG tank on site.		
Water Source:       Creek         Mitigation Time:       1-2 Hours         Other Resources       Hose lay with sprinkler kits, scratch line around structure, use structure wrap where needed.         Needed to Protect:       Hose lay with sprinkler kits, scratch line around structure, use structure wrap where needed.         Notes:       Structure is a single story structure located along the Entiat River in the Pope Summer Homes. Structure's primary building construction is comprised wood siding with a clean asphalt shingle roof. Heat traps and decks are present but clear of debris and combustible materials. Access to the structure is by a narrow but passable driveway located off of main roadway in a small group of structures. Structure 7-5 is non-defendable prep and leave due to lack of safety zone present on site.         Collected By:       Jay Walter       Collected Date/Time:       08/03/2014 08:20:27 GMT-07:00	Access to Site:	T3/4 Engine	Best Access From: West on unnamed drive	way marked #7 west of Entiat River Road.
Mitigation Time:       1-2 Hours         Other Resources       I-2 Hours         Needed to Protect:       Hose lay with sprinkler kits, scratch line around structure, use structure wrap where needed.         Notes:       Structure is a single story structure located along the Entiat River in the Pope Summer Homes. Structure's primary building construction is comprised wood siding with a clean asphalt shingle roof. Heat traps and decks are present but clear of debris and combustible materials. Access to the structure is by a narrow but passable driveway located off of main roadway in a small group of structures. Structure 7-5 is non-defendable prep and leave due to lack of safety zone present on site.         Collected By:       Jay Walter       Collected Date/Time: 08/03/2014 08:20:27 GMT-07:00	Comm with ICP:	Radio		
Other Resources         Needed to Protect:       Hose lay with sprinkler kits, scratch line around structure, use structure wrap where needed.         Notes:       Structure is a single story structure located along the Entiat River in the Pope Summer Homes. Structure's primary building construction is comprised wood siding with a clean asphalt shingle roof. Heat traps and decks are present but clear of debris and combustible materials. Access to the structure is by a narrow but passable driveway located off of main roadway in a small group of structures. Structure 7-5 is non-defendable prep and leave due to lack of safety zone present on site.         Collected By:       Jay Walter       Collected Date/Time: 08/03/2014 08:20:27 GMT-07:00	Water Source:	Creek		
Needed to Protect:       Hose lay with sprinkler kits, scratch line around structure, use structure wrap where needed.         Notes:       Structure is a single story structure located along the Entiat River in the Pope Summer Homes. Structure's primary building construction is comprised wood siding with a clean asphalt shingle roof. Heat traps and decks are present but clear of debris and combustible materials. Access to the structure is by a narrow but passable driveway located off of main roadway in a small group of structures. Structure 7-5 is non-defendable prep and leave due to lack of safety zone present on site.         Collected By:       Jay Walter       Collected Date/Time:       08/03/2014 08:20:27 GMT-07:00	Mitigation Time:	1-2 Hours		
Notes:Structure is a single story structure located along the Entiat River in the Pope Summer Homes. Structure's primary building construction is comprised wood siding with a clean asphalt shingle roof. Heat traps and decks are present but clear of debris and combustible materials. Access to the structure is by a narrow but passable driveway located off of main roadway in a small group of structure. Structure 7-5 is non-defendable prep and leave due to lack of safety zone present on site.Collected By:Jay WalterCollected Date/Time:08/03/2014 08:20:27 GMT-07:00	Other Resources			
<ul> <li>wood siding with a clean asphalt shingle roof. Heat traps and decks are present but clear of debris and combustible materials. Access to the structure is by a narrow but passable driveway located off of main roadway in a small group of structures. Structure 7-5 is non-defendable prep and leave due to lack of safety zone present on site.</li> <li>Collected By: Jay Walter Collected Date/Time: 08/03/2014 08:20:27 GMT-07:00</li> </ul>	Needed to Protect:	Hose lay with sprinkler kits	s, scratch line around structure, use structure wra	ap where needed.
	Notes:	wood siding with a clean aspha is by a narrow but passable driv	It shingle roof. Heat traps and decks are present but clear reway located off of main roadway in a small group of stru	of debris and combustible materials. Access to the structure
Photo 1 Photo 2	Collected By:	Jay Walter	Collected Date/Time:	08/03/2014 08:20:27 GMT-07:00
		Photo 1		Photo 2







Photo 4

STHERN 2











CHERN 2

Structure Number:	153		FED TLAW
Structure Name:	RH #1-2		a Donations
SubDivision:	<b>Riverside Summer Homes</b>		ST. ELLAS
GPS Location, Lat.	47 5.81442		
GPS Location, Long.	120 33.18258		ANAGE
Safety Zone Present:	No	Where is Safety Zone: Down Entiat River Road	approx 8 miles
Type of Structure:	Residential	Primary Structures: 1	Outbuildings: 2
Other Type of			
Surrounding Fuels:	Shrub,Timber,Slash	Defensible Space	e: 30-50 Feet
Structure Triage			
Category:	Non-Defensible, Prep and Le	ave	
Roof Material:	Metal	Siding Materia	I: Wood
Heat Traps:	Wood Deck,Other Receptor		
Electrical Power:	Generator	Gas to Structure	e: Aboveground
Hazards:	Fuels, Haz Mat		
Hazard Notes:	LPG tank on site		
Access to Site:	T3/4 Engine	Best Access From: Entiat River Road & stru	icture group road 1
Comm with ICP:	Radio		
Water Source:	Creek		
Mitigation Time:	1-2 Hours		
Other Resources			
Needed to Protect:	Sprinkler kits set up with pur	np and hose lay in place. Scratch line around s	tructures and light fuels removal.
Notes:	comprised of a metal roof with we by a passable driveway located of	ood siding. Heat traps and decks are present but clear o	Summer Homes. Structure's primary building construction is of debris and combustible materials. Access to the structure is ructure 1-2 is non-defendable prep and leave due to lack of
	safety zone present on site.		
Collected By:	Jay Walter	Collected Date/Time:	08/03/2014 08:14:20 GMT-07:00

Collected By

Walter





STHERN AN

Structure Number:	151	PED TLAN
Structure Name:	RH #1-3	E THE
SubDivision:	<b>Riverside Summer Homes</b>	St. LL VE
GPS Location, Lat.	47 58.12854	
GPS Location, Long.	120 0.03318	A HAGE AND
Safety Zone Present:	No	Where is Safety Zone: Down Entiat River Road approx 8 miles.
Type of Structure:	Residential	Primary Structures: 1 Outbuildings: 2
Other Type of		
Surrounding Fuels:	Shrub, Timber, Slash	Defensible Space: 30-50 Feet
Structure Triage		
Category:	Non-Defensible, Prep and Le	ave
Roof Material:	Metal	Siding Material: Wood
Heat Traps:	Wood Deck,Other Receptor	
Electrical Power:	Generator	Gas to Structure: Aboveground
Hazards:	Fuels, Haz Mat	
Hazard Notes:	250 gal LPG tank on site	
Access to Site:	T3/4 Engine	Best Access From: Entiat River Road & Riverside Structure road 1
Comm with ICP:	Radio	
Water Source:	Creek	
Mitigation Time:	2-3 Hours	
Other Resources	Pump with hose lay and spri	nklers will need to be present on site. Scratch line will need to line the exterior perimeter of the
Needed to Protect:	structure.	
Notes:	construction is comprised wood s	e with a loft located along the Entiat River in the Riverside Summer Homes. Structure's primary building iding with a clean metal roof. Heat traps and decks are present but clear of debris and combustible materials. Access t passable driveway located off of main roadway in a group of three structures. Structure 1-3 is non-defendable prep ne present on site.
Collected By:	Jay Walter	Collected Date/Time: 08/03/2014 08:15:11 GMT-07:00

Jay Walter





Structure Number:	150		FED TEAM
Structure Name:	RH #2-1		a Contracta
SubDivision:	<b>Riverside Summer Homes</b>		EL CE
GPS Location, Lat.	47 58.15704		
GPS Location, Long.	120 33.16716		24NAGE
Safety Zone Present:	No	Where is Safety Zone: Safety zone is located 6	miles south on Entiat River Road.
Type of Structure:	Residential	Primary Structures: 1	Outbuildings: 4
Other Type of			
Surrounding Fuels:	Shrub, Timber, Slash	Defensible Space	e: 30-50 Feet
Structure Triage			
Category:	Non-Defensible, Prep and Le	ave	
Roof Material:	Metal	Siding Materia	I: Wood
Heat Traps:	Open Eaves,Wood Deck,Oth	er Receptor	
Electrical Power:	Generator	Gas to Structure	e: Aboveground
Hazards:	Fuels, Haz Mat		
Hazard Notes:	500 gal. LPG tank on site.		
Access to Site:	T3/4 Engine	Best Access From: Unnamed but marked d	riveway 2 west of Entiat River Road.
Comm with ICP:	Radio		
Water Source:	Creek		
Mitigation Time:	1-2 Hours		
Other Resources			
Needed to Protect:	One type 6 or larger engine of	on site.	
Notes:	construction is comprised wood s	t passable driveway located off of main roadway in a g	ide Summer Homes. Structure's primary building present but clear of debris and combustible materials. Access roup of structures. Structure 2-1 is non-defendable prep and
Collected By:	Jay Walter	Collected Date/Time:	08/03/2014 08:15:37 GMT-07:00

Collected By:

Jay Walter





Photo 4

STHERN AL



STHERN &


Structure Number:	149	FED TLAN	
Structure Name:	RH #3-1	= TIFE	
SubDivision:	<b>Riverside Summer Homes</b>	St. EH. P.	
GPS Location, Lat.	47 58.15146		
GPS Location, Long.	120 33.16518	24NAGE***	
Safety Zone Present:	No	Vhere is Safety Zone: Safety zone is located 6 miles south on Entiat River Road.	
Type of Structure:	Residential	Primary Structures: 1 Outbuildings: 1	
Other Type of			
Surrounding Fuels:	Shrub, Timber, Slash	Defensible Space: 30-50 Feet	
Structure Triage			
Category:	Non-Defensible, Prep and Lea	ave	
Roof Material:	Metal	Siding Material: Wood	
Heat Traps:	Open Eaves,Wood Deck,Other Receptor		
Electrical Power:	Generator	Gas to Structure: Aboveground	
Hazards:	Fuels,HazMat		
Hazard Notes:	25 LPG tank on site.		
Access to Site:	T3/4 Engine	Best Access From: Unnamed driveway but marked #3 west of Entiat River Road.	
Comm with ICP:	Radio		
Water Source:	Creek		
Mitigation Time:	1-2 Hours		
Other Resources			
Needed to Protect:	Type 6 or larger engine on sit	e.	
Notes:	comprised wood siding with a clea	e located along the Entiat River in the Riverside Summer Homes. Structure's primary building construction is n metal roof. Heat traps and decks are present but clear of debris and combustible materials. Access to the ble driveway located off of main roadway in a group of three structures. Structure 3-1 is non-defendable prep and esent on site.	
Collected By:	lav Walter	Collected Date/Time: 08/03/2014 08:15:57 GMT-07:00	

ected B

Jay Walter













STHERN A

Structure Number:	147	FED TTAN A
Structure Name:	RH #3-3	a Dortana
SubDivision:	<b>Riverside Summer Homes</b>	S. LL S
GPS Location, Lat.	47 0.58188	
GPS Location, Long.	120 33.19068	47ANA GEN
Safety Zone Present:	No	Where is Safety Zone: Safety zone is located 6 miles south down Entiat River Road.
Type of Structure:	Residential	Primary Structures: 1 Outbuildings: 2
Other Type of		
Surrounding Fuels:	Shrub, Timber, Slash	Defensible Space: 50-100 Feet
Structure Triage		
Category:	Non-Defensible, Prep and L	eave
Roof Material:	Metal	Siding Material: Wood
Heat Traps:	Open Eaves,Wood Deck,Oth	ner Receptor
Electrical Power:	Generator	Gas to Structure: Aboveground
Hazards:	Fuels, Haz Mat	
Hazard Notes:	250 LPG tank on site.	
Access to Site:	T3/4 Engine	Best Access From: West on unnamed driveway marked #3 west of Entiat River Road.
Comm with ICP:	Radio	
Water Source:	Creek	
Mitigation Time:	1-2 Hours	
Other Resources		
Needed to Protect:	Hose lay with sprinkler kits,	scatch line around wrap on structure.
Notes:	comprised wood siding with a clo	are located along the Entiat River in the Riverside Summer Homes. Structure's primary building construction is ean metal roof. Heat traps and decks are present but clear of debris and combustible materials. Access to the able driveway located off of main roadway in a group of three structures. Structure 3-3 is non-defendable prep and present on site.
Collected By:	Jay Walter	Collected Date/Time: 08/03/2014 08:16:35 GMT-07:00







Structure Number:	158		FED TLAN
Structure Name:	RH #3-4		2 Donates
SubDivision:	<b>Riverside Summer Homes</b>		ST. LL E
GPS Location, Lat.	47 58.21704		
GPS Location, Long.	120 33.19182		**ANAGE**
Safety Zone Present:	No	Where is Safety Zone: Safety zone is located 6	miles south on the Entiat River Road.
Type of Structure:	Residential	Primary Structures: 1	Outbuildings: 2
Other Type of			
Surrounding Fuels:	Shrub, Timber, Slash	Defensible Space	: 50-100 Feet
Structure Triage			
Category:	Non-Defensible, Prep and Lo	eave	
Roof Material:	Wood	Siding Material	: Wood
Heat Traps:	Open Eaves,Wood Deck,Oth	ner Receptor	
Electrical Power:	Solar/Wind,Generator	Gas to Structure	: Aboveground
Hazards:	Fuels, Haz Mat		
Hazard Notes:	250 gal LPG tank on site.		
Access to Site:	T3/4 Engine	Best Access From: West on unnamed drive	way marked #3 west of Entiat River Road.
Comm with ICP:	Radio		
Water Source:	Creek		
Mitigation Time:	1-2 Hours		
Other Resources			
Needed to Protect:	Hose lay with sprinkler kits,	scratch line around and wrap structure.	
Notes:	comprised wood siding with a cle	, , , , ,	
Collected By:	Jay walter	Collected Date/Time:	08/03/2014 07:07:46 GMT-07:00





Photo 4

STHERN A



Structure Number:	373		
Structure Name:	1-1 5100 RD		
SubDivision:	Entiat		
GPS Location, Lat.	47 58.11306		
GPS Location, Long.	120 3.31512		
Safety Zone Present:	No	Where is Safety Zone: Silver Falls parking	
Type of Structure:	Residential	Primary Structures: 1	Outbuildings: 2
Other Type of			
Surrounding Fuels:	Shrub, Timber, Slash	Defensible Space: None	
Structure Triage			
Category:	Non-Defensible, Prep a	nd Leave	
Roof Material:	Metal	Siding Material: Wood	
Heat Traps:	Open Eaves, Wood Deck	k,Other Receptor	
Electrical Power:	None	Gas to Structure: None	
Hazards:	Terrain, Fuels		
Hazard Notes:	One way in, one way ou	ut. Interconnected crown.	
Access to Site:	T6 Engine	Best Access From: 5100 rd	
Comm with ICP:	Radio		
Water Source:	Creek		
Mitigation Time:	1-2 Hours		
Other Resources			
Needed to Protect:	Sprinklers, pump, foil		
Notes:	Summer cabin with a good	water source, significant fuel issue	



Early Winters Photo 1 Collected Date/Time: 08

08/17/2014 18:51 Photo 2



Photo 3



Structure Number: Structure Name:	374 1-1 structure 5100 rd		
SubDivision:	Entiat		
GPS Location, Lat.	47 58.11516		
GPS Location, Long.	120 33.1575		
Safety Zone Present:	No	Where is Safety Zone: Silver Falls parking	
Type of Structure:	Residential	Primary Structures: 1	Outbuildings: 2
Other Type of		-	U
Surrounding Fuels:	Shrub, Timber, Slash	Defensible Space: None	2
Structure Triage			
Category:	Non-Defensible, Prep and	Leave	
Roof Material:	Wood	Siding Material: Woo	d
Heat Traps:	Wood Deck,Other Recepto	or	
Electrical Power:	None	Gas to Structure: Abov	veground
Hazards:	Terrain, Fuels, No Turn Aro	und	
Hazard Notes:	Snags, interconnected cro	wn	
Access to Site:	Handcrew	Best Access From: Access on foot from structure	1-2
Comm with ICP:	Radio		
Water Source:	Creek		
Mitigation Time:	1-2 Hours		
Other Resources			
Needed to Protect:	Sprinkles, pump, foil		
Notes:	Summer cabin with good water	r source, must access by foot from structure 1-2's driveway.	

Collected By:

Early Winters

Collected Date/Time: 08/17/2014 18:50

Photo 2



Photo 3

		Structure Triage Information	NATION
Structure Number:	375		
Structure Name:	1-3 structure 5100 rd		
SubDivision:	Entiat		TEAM
GPS Location, Lat.	47 58.09122		Contract of the second s
GPS Location, Long.	120 33.16032		CNI
Safety Zone Present:	No	Where is Safety Zone: Silver falls parking	
Type of Structure:	Residential	Primary Structures: 1	Outbuildings: 2
Other Type of			
Surrounding Fuels:	Shrub, Timber, Slash	Defensible Spac	e: None
Structure Triage			
Category:	Non-Defensible, Prep ar	nd Leave	
Roof Material:	Metal	Siding Materia	al: Wood
Heat Traps:	Open Eaves,Wood Deck	,Other Receptor	
Electrical Power:	Underground	Gas to Structur	<b>'e:</b> Aboveground
Hazards:	Terrain, Fuels		-
Hazard Notes:	Multiple large wood pile	es less than 30 ft from structure, interconnected ci	rown, propane tank, snags
Access to Site:	T6 Engine	Best Access From: 5100 rd	
Comm with ICP:	None		
Water Source:	Creek		
Mitigation Time:	1-2 Hours		
Other Resources			
Needed to Protect:	Sprinklers, pump, foil		
Notes:	Summer cabin with good wa	ater course, multiple wood piles surrounding home	

Collected By:

Early winters Photo 1

Collected Date/Time:

08/17/2014 18:50 Photo 2



Photo 3

Structure Number: Structure Name: SubDivision:	377 3-1 structure 5100 road Entiat		- 24
GPS Location, Lat.	47 5.81454		CIDE
GPS Location, Long.	120 33.1749		
Safety Zone Present:	No	Where is Safety Zone: Sliver falls parking	
Type of Structure:	Residential	Primary Structures: 1	Outbuildings: 1
Other Type of			
Surrounding Fuels:	Shrub, Timber, Slash	Defensible Spac	e: None
Structure Triage			
Category:	Non-Defensible, Prep and	Leave	
Roof Material:	Metal	Siding Materia	al: Wood
Heat Traps:	Open Eaves		
Electrical Power:	None	Gas to Structur	e: Aboveground
Hazards:	Terrain, Fuels		
Hazard Notes:	Interconnected crown		
Access to Site:	T6 Engine	Best Access From: Driveway 2 from 5100	road
Comm with ICP:	Radio		
Water Source:	Creek		
Mitigation Time:	1-2 Hours		
Other Resources			
Needed to Protect:	Sprinklers, pump, foil		
Notes:	Summer cabin with good wate	r source, inner connected crown	

Collected By:

Early winters Photo 1 Collected Date/Time: 08

08/17/2014 18:50 Photo 2 JATIO/



Photo 3

		Structure Triage Information	NATIONA
Structure Number:	378		
Structure Name:	3-2 structure 5100 rd		
SubDivision:	Entiat		
GPS Location, Lat.	47 58.18248		Comments.
GPS Location, Long.	120 33.16128		ENT
Safety Zone Present:	No	Where is Safety Zone: Silver falls parking	
Type of Structure:	Residential	Primary Structures: 1	Outbuildings: 2
Other Type of			
Surrounding Fuels:	Shrub, Timber, Slash	Defensible Spa	ace: None
Structure Triage			
Category:	Non-Defensible, Prep ar	nd Leave	
Roof Material:	Wood	Siding Mate	rial: Wood
Heat Traps:	Open Eaves, Rain Gutter		
Electrical Power:	None	Gas to Struct	ure: Aboveground
Hazards:	Terrain, Fuels		-
Hazard Notes:	Inner connected crown,	, wood pile less than 30 ft away	
Access to Site:	T6 Engine	Best Access From: Driveway 3 from 510	0 road
Comm with ICP:	Radio		
Water Source:	Creek		
Mitigation Time:	1-2 Hours		
Other Resources			
Needed to Protect:	Sprinklers, pump, foil		
Notes:	Summer cabin with good wa	ater source	

Collected By:

Early winters Photo 1

Collected Date/Time: 08/17/2014 18:49

Photo 2



Photo 3

		Structure Triage Information	NATION
Structure Number:	379		
Structure Name:	3-3 structure 5100 road		
SubDivision:	Entiat		TEAM
GPS Location, Lat.	47 58.20318		Ven-
GPS Location, Long.	120 33.17712		ENT
Safety Zone Present:	No	Where is Safety Zone: Silver falls parking	
Type of Structure:	Residential	Primary Structures: 1	Outbuildings: 2
Other Type of			
Surrounding Fuels:	Shrub, Timber, Slash	Defensible Sp	oace: 30-50 Feet
Structure Triage			
Category:	Non-Defensible, Prep and	Leave	
Roof Material:	Metal	Siding Mate	erial: Wood
Heat Traps:	Open Eaves, Other Recept	or	
Electrical Power:	None	Gas to Struct	ture: Aboveground
Hazards:	Terrain, Fuels		
Hazard Notes:	Inner connected crown, w	vood pile less than 30 ft away, snags	
Access to Site:	T6 Engine	Best Access From: Driveway 3 from 510	00 rd
Comm with ICP:	Radio		
Water Source:	Creek		
Mitigation Time:	1-2 Hours		
Other Resources			
Needed to Protect:	Sprinklers, pump, foil		
Notes:	Summer cabin with good wate	r source	

Collected By:

Early winters Photo 1 Collected Date/Time: 08/17/2014 18:49

Photo 2

Photo 3

		Structure Triage Information	NATION.
Structure Number:	380		
Structure Name:	3-4 structure 5100 rd		
SubDivision:	Entiat		
GPS Location, Lat.	47 58.20252		Contraction of the second seco
GPS Location, Long.	120 33.17244		ENI
Safety Zone Present:	No	Where is Safety Zone: Silver falls parking	
Type of Structure:	Residential	Primary Structures: 1	Outbuildings: 2
Other Type of			
Surrounding Fuels:	Shrub, Timber, Slash	Defensible Space	ce: None
Structure Triage			
Category:	Non-Defensible, Prep ar	nd Leave	
Roof Material:	Wood	Siding Materia	al: Wood
Heat Traps:	Open Eaves, Other Rece	ptor	
Electrical Power:	None	Gas to Structur	re: Aboveground
Hazards:	Terrain, Fuels, No Turn A	round	
Hazard Notes:	Wood pile less than 30 f	ft from structure, snags, inner connected crown	
Access to Site:	T6 Engine	Best Access From: Driveway 3 from 5100	rd
Comm with ICP:	Radio		
Water Source:	Creek		
Mitigation Time:	1-2 Hours		
Other Resources			
Needed to Protect:	Sprinklers, pump, foil		
Notes:	Summer cabin with good wa	ater source, massive wood piles, snags	

Collected By:

Early winters Photo 1 Collected Date/Time: 08/17/2014 18:49

Photo 2



Photo 3

Structure Number: Structure Name: SubDivision:	376 Structure 2-1 rd 5100 Entiat		
GPS Location, Lat.	47 58.13922		8
GPS Location, Long.	120 33.18114		
Safety Zone Present:	No	Where is Safety Zone: Silver falls parking	
Type of Structure:	Residential	Primary Structures: 1	Outbuildings: 3
Other Type of			
Surrounding Fuels:	Shrub, Timber, Slash	Defensible Space	e: None
Structure Triage			
Category:	Non-Defensible, Prep an	id Leave	
Roof Material:	Metal	Siding Materia	I: Wood
Heat Traps:	Open Eaves,Wood Deck,	Other Receptor	
Electrical Power:	None	Gas to Structure	e: Aboveground
Hazards:	Terrain, Fuels		-
Hazard Notes:	Interconnected crown, m	nultiple wood piles around structure, propane tank	< c
Access to Site:	T6 Engine	Best Access From: Driveway 2 from 5100 r	ď
Comm with ICP:	None	·	
Water Source:	Creek		
Mitigation Time:	1-2 Hours		
Other Resources			
Needed to Protect:	Sprinklers, pump, foil		
Notes:		ter source, propane tank, interconnected crown	

Collected By:

Early winters


Collected Date/Time: 08/1

08/17/2014 18:50 Photo 2



Photo 3





Structure Number: Structure Name: SubDivision: GPS Location, Lat.	279 P9W Preston / Fox 47 54.13236		+ TODENT TEAM
GPS Location, Long.	120 28.2537		
Safety Zone Present:		Where is Safety Zone: .5 miles south on Entiat River Ro	
Type of Structure:	Residential	Primary Structures: 1	Outbuildings: 5
Other Type of			
Surrounding Fuels:	Grass,Shrub,Timber,Slash	Defensible Space: 30-50	Feet
Structure Triage			
Category:	Defensible, Prep and Hold		
Roof Material:	Metal	Siding Material: Wood	
Heat Traps:	Wood Deck, Other Receptor		
Electrical Power:	Overhead	Gas to Structure: Above	ground
Hazards:			
Hazard Notes:	Overhead power lines over t	op of driveway.	
Access to Site:	T3/4 Engine	Best Access From: Entiat River Road	
Comm with ICP:	Radio		
Water Source:	Faucet / Hose,Creek		
Mitigation Time:	1-2 Hours		
Other Resources			
Needed to Protect:	Hose lay with sprinkler kits,	vegetation removal from immediate proximity to struc	tures. Scratch line around all structures.
Notes:	under a constructed cover. Struct	story structure with a metal roof and wood siding. There are 5 ac ure has a roof clear of debris and vegetation has been brushed b Structures are in close proximity to safety zones and are uninhal	ack from the structures. Scratch line has been

Collected By:

Collected Date/Time:

Jay Walter Photo 1 08/12/2014 12:02 Photo 2 Photo 3 Photo 4





ATIONA

		Structure Triage Informa	tion
Structure Number:	275		
Structure Name:	P10E		
SubDivision:	Preston / Fox		
GPS Location, Lat.	47 5.40858		
GPS Location, Long.	120 27.81768		ENT
Safety Zone Present:	Yes	Where is Safety Zone: .2 miles sout	n on Entiat River Road.
Type of Structure:	Residential	Primary Structures: 1	Outbuildings: 1
Other Type of			
Surrounding Fuels:	Grass, Shrub, Timber	Defen	sible Space: 30-50 Feet
Structure Triage			
Category:	Defensible, Prep and Hold		
Roof Material:	Metal	Sidir	g Material: Metal
Heat Traps:	Open Eaves,Wood Deck,Ra	in Gutters, Other Receptor	
Electrical Power:	Generator	Gas t	o Structure: Aboveground
Hazards:	Terrain, Fuels		
Hazard Notes:	10 gal LPG tank on site.		
Access to Site:	T3/4 Engine	Best Access From: Entiat River F	oad
Comm with ICP:	Radio		
Water Source:	Faucet / Hose,Creek		
Mitigation Time:	1-2 Hours		
Other Resources			
Needed to Protect:	Hose lay with sprinkler kits	, light removal of vegetation from arc	und structures. Scratch hand line around all structures.
Notes:	Structure is a large fifth wheel th	avel trailer under a wood frame constructed	awning with a clean metal roof. Open eves are present with other
	ignition receptive sources under	neath the awning. Sprinkler and fuels reduc	tion in place.

Collected By:

Jay Walter

08/12/2014 13:40 Collected Date/Time:





Structure Number: Structure Name: SubDivision:	278 P10W Preston / Fox			
GPS Location, Lat.	47 5.40972		TEAM 2	
GPS Location, Long.	120 28.2435		OENT TE	
Safety Zone Present:		Where is Safety Zone: .5 miles south on Entiat River	Road.	
Type of Structure:	Residential	Primary Structures: 1	Outbuildings: 1	
Other Type of			C C	
Surrounding Fuels:	Grass,Shrub,Timber	Defensible Space: 30-50 Feet		
Structure Triage				
Category:	Defensible, Prep and Hold			
Roof Material:	Metal	Siding Material: Woo	bc	
Heat Traps:	Wood Deck,Other Receptor			
Electrical Power:	Underground	Gas to Structure: Abo	veground	
Hazards:	Terrain, Fuels			
Hazard Notes:	500 gal LPG tank on site.			
Access to Site:	T3/4 Engine	Best Access From: Entiat a River Road.		
Comm with ICP:	Radio			
Water Source:	Faucet / Hose,Creek			
Mitigation Time:	1-2 Hours			
Other Resources	Hose lay with sprinkler kits,	scratch line around all structures and remove any ve	getation that is in direct proximity to the	
Needed to Protect:	structure.			
Notes:		story structure with a metal roof and wood siding. Structure h s. Structures are in close proximity to safety zones and are unir	•	

Collected By:

Jay Walter

Collected Date/Time: 08/12/2014 12:13 Photo 2 NATIONA











ATIONA


Structure Number: Structure Name: SubDivision: GPS Location, Lat.	276 P11W Preston / Fox 47 54.11754 120 28.20108			+ TODENT TEN
GPS Location, Long.		Where is Safety 7ana, E miles south	on Entiat Divor Doad	
Safety Zone Present:		Where is Safety Zone: .5 miles south of		Outhuildings 1
Type of Structure:	Residential	Primary Structures: 1		Outbuildings: 1
Other Type of		Defensil	hla <b>C</b> urana, 20 E0 Eant	
Surrounding Fuels:	Grass,Shrub,Timber	Defensio	ble Space: 30-50 Feet	
Structure Triage				
Category:	Defensible, Prep and Hold		<b>NA</b> - <b>N</b> -	
Roof Material:	Metal	•	Material: Wood	
Heat Traps:	Open Eaves, Wood Deck, Rair			
Electrical Power:	Overhead, Generator	Gas to S	Structure: Abovegrou	nd
Hazards:	Terrain, Fuels			
Hazard Notes:	250 gal LPG tank on site.			
Access to Site:	T3/4 Engine	Best Access From: Entiat River Roa	ad	
Comm with ICP:	Radio			
Water Source:	Faucet / Hose,Creek			
Mitigation Time:	1-2 Hours			
Other Resources				
Needed to Protect: Notes:	Structure is a single family single	scratch line around all structures and n story structure with a metal roof and wood si k from the structures and scratch line has be time.	iding. Structure has a roof	with large amounts of debris on top of it.

Collected By:

Jay Walter







**Collected By:** 

Jay Walter

**Collected Date/Time:** 08/12/2014 13:56



Photo 3



ALERN

Structure Number: Structure Name: SubDivision: GPS Location, Lat. GPS Location, Long. Safety Zone Present: Type of Structure: Other Type of	170 FS #1 Silver Falls Guard Station 47 57.48888 120 32.13216 No Other Government building	Where is Safety Zone: Safety zones are located Primary Structures: 1	I south of guard station location approx 4 miles. Outbuildings: 3
Surrounding Fuels: Structure Triage	Timber,Slash	Defensible Space	: 30-50 Feet
Category:	Non-Defensible, Prep and L	_eave	
Roof Material:	Wood	Siding Material	: Wood
Heat Traps:	Open Eaves, Wood Deck, Ot	her Receptor	
Electrical Power:	Solar/Wind	Gas to Structure	: Aboveground
Hazards:	Fuels,HazMat		
Hazard Notes:		n site. Bulk fuel storage in outbuilding.	
Access to Site: Comm with ICP:	T1 Engine	Best Access From: Silver Falls Guard Station	n is located at the Silver Falls Trail along Entiat River
Water Source:	Radio Faucet / Hose,Porta-Tank/F	Pumpkin Crook	
Mitigation Time:	1-2 Hours	unphil, cleek	
Other Resources	1 1 100.0		
Needed to Protect:	Hose lay with sprinkler kits,	, scratch line around structure, use structure wra	ap as needed on structure.
Notes:	clean shake shingle roof with wo compound have had hand line so	bod siding. there is one medium size garage on site and tw	buildings. Primary structure is a single level structure with a wo smaller misc outbuildings. All buildings in the Silver Falls lay and sprinkler system. Structure wrap was used where n established safety zones.
Collected By:	Jay Walter Photo 1	Collected Date/Time:	08/03/2014 07:03:22 GMT-07:00 Photo 2
Contraction of the second second	Photo 3		Photo 4



		Structure Triage	Information		ATHERN AD
Structure Number:	136				FED TEAM
Structure Name:	Weather Station				SUPERIORS.
SubDivision:	Weather Station				an the P
GPS Location, Lat.	47 59.46012				Var 19
GPS Location, Long.	120 33.98082				MANAGE
Safety Zone Present:	No	Where is Safety Zone: Sa	afety zone is located 11	miles south on Entiat Ri	ver Road.
Type of Structure:	Other	Primary Structures: 2		Outbuilding	<b>s:</b> 3
Other Type of	Government Weather Statio	on			
Surrounding Fuels:	Grass,Shrub,Timber,Slash		Defensible Space:	: 30-50 Feet	
Structure Triage					
Category:	Non-Defensible, Prep and L	eave			
Roof Material:	Metal		Siding Material:	Wood	
Heat Traps:	Other Receptor				
Electrical Power:	Solar/Wind		Gas to Structure:	: None	
Hazards:	Terrain, Fuels, Haz Mat				
Hazard Notes:	Structures are located down				
Access to Site:	T6 Engine	Best Access From: Ta	ake marked spur road f	rom 5606 RD .	
Comm with ICP:	Radio				
Water Source:	None				
Mitigation Time:	1-2 Hours				
Other Resources					
Needed to Protect:	Heavy thinning along with s	•			
Notes:	Site is made up of 4 small structures now pact and levels. Both prima		-		
	shake shingle roof, while the oth		• • •		•
	constructed of metal and stand a				
				00/02/2014 00 20 46 0	NAT 07 00
Collected By:	Jay Walter Photo 1		ollected Date/Time:	08/03/2014 08:20:46 G Photo 2	IVI1-07:00
	Photo 3			Photo 4	
	The				