

# Repair Plan Map

Repair Area: Div O

Operational Period 09/12/2015

Note: Repair Items subject to modifications. Point table represents only relevant repair items.



| Pt ID | Feature Type        | Latitude  | Longitude   | Comments/Rehab Needs    |
|-------|---------------------|-----------|-------------|-------------------------|
| 158   | Landing             | 47 53.139 | -120 44.654 |                         |
| 159   | Landing             | 47 53.109 | -120 44.377 |                         |
| 160   | Landing             | 47 52.742 | -120 43.692 | Full rehab needed       |
| 161   | Landing             | 47 52.676 | -120 43.449 | Full rehab needed       |
| 162   | Landing             | 47 52.17  | -120 41.127 |                         |
| 163   | Landing             | 47 52.063 | -120 41.031 |                         |
| 164   | Landing             | 47 51.573 | -120 41.085 |                         |
| 165   | Landing             | 47 51.413 | -120 41.006 |                         |
| 166   | Landing             | 47 51.338 | -120 40.69  |                         |
| 167   | Landing             | 47 51.276 | -120 40.428 |                         |
| 168   | Landing             | 47 51.408 | -120 40.389 |                         |
| 169   | Landing             | 47 51.958 | -120 40.345 |                         |
| 170   | Landing             | 47 51.099 | -120 40.074 |                         |
| 171   | Landing             | 47 50.983 | -120 39.688 |                         |
| 172   | Landing             | 47 51.405 | -120 38.995 |                         |
| 173   | Landing             | 47 51.688 | -120 39.662 |                         |
| 175   | Landing             | 47 53.009 | -120 47.033 | 30' buf riparian        |
| 176   | Landing             | 47 53.029 | -120 46.907 | Full rehab needed       |
| 177   | Landing             | 47 53.074 | -120 46.618 | Full rehab needed       |
| 178   | Landing             | 47 53.051 | -120 46.328 | Full rehab needed       |
| 179   | Landing             | 47 52.903 | -120 45.683 | 30' buf riparian        |
| 180   | Landing             | 47 52.925 | -120 45.467 | Full rehab needed       |
| 183   | Landing             | 47 52.906 | -120 45.605 | Georgia?                |
| 174   | Culvert Damage      | 47 52.931 | -120 43.995 | Filled with debris      |
| 184   | Culvert Damage      | 47 53.038 | -120 46.868 | Minor, North side       |
| 186   | Invasive Species    | 47 52.293 | -120 41.796 | Centaurea diffusa patch |
| 181   | General Disturbance | 47 52.987 | -120 47.151 | 100' dozer lane         |
| 182   | General Disturbance | 47 53.03  | -120 45.26  | Pullout                 |
| 185   | General Disturbance | 47 53.018 | -120 44.068 | Pullout                 |

## Notes:

## Fire Points Reference

- Helispot
- Drop Point
- Ⓜ Water Source
- Ⓢ Camp
- Ⓡ Repeater
- ★ Other



| Repair Legend |                           | Ownership                 |                           | Oka/Wen NF Data |                     |
|---------------|---------------------------|---------------------------|---------------------------|-----------------|---------------------|
| ● Approved    | MMMM Road Prep/Line Break | MMMM Road Prep/Line Break | MMMM Road Prep/Line Break | WA DNR          | ● Riparian Reserves |
| ● Completed   | XXXXXX Dozer Line         | XXXXXX Dozer Line         | XXXXXX Dozer Line         | USFS            |                     |
| ● Needed      | HHHH Hand Line            | HHHH Hand Line            | HHHH Hand Line            |                 |                     |
|               | ●●●● P-Line               | ●●●● P-Line               | ●●●● P-Line               |                 |                     |