

Repair Plan Map

Repair Area: Wolverine Fire

Div O/L

Operational Period 9/21/2015

Note: Repair items subject to modifications



Div O

Div L

- Division O:**
- Oscar Temp Road
 - Oscar Gate Draft Site
 - Oscar Temp Road
 - Oscar Sky Line
 - Oscar Engine Draft
- Division L:**
- Lima Bike Trail
 - Lima Skyline
 - Lima Dozer Line
 - Alder Draft
- Other:**
- Meadow Pit Deck
 - Sooper Pit Deck
 - Mulch Landing
 - Fish Lake Spike
 - Fish Lake Draft
- Not represented on the map:**
- Oscar Landings (Repair Points)
 - Oscar Contingency Line (Repair Lines)
 - Lima Cut Bank
 - Lima Landings (Repair Points)
 - Lima Contingency Line (Repair Lines)

PT#	Feature Type	Latitude	Longitude	Notes/Rehab Needs
158	Landing	47 53.139	-120 44.654	
159	Landing	47 53.109	-120 44.377	
160	Landing	47 52.742	-120 43.692	Full rehab needed
161	Landing	47 52.676	-120 43.49	Full rehab needed
162	Landing	47 52.17	-120 41.127	
163	Landing	47 52.063	-120 41.031	
164	Landing	47 51.573	-120 41.085	
165	Landing	47 51.413	-120 41.006	
166	Landing	47 51.338	-120 40.69	
167	Landing	47 51.276	-120 40.428	
168	Landing	47 51.408	-120 40.389	
169	Landing	47 51.558	-120 40.345	
170	Landing	47 51.099	-120 40.074	
171	Landing	47 50.983	-120 39.688	
172	Landing	47 51.405	-120 38.995	
173	Landing	47 51.688	-120 39.662	
174	Culvert Damage	47 52.931	-120 43.995	Filled with debris
175	Landing	47 53.009	-120 47.033	Chipped biomass 30' buffer
176	Landing	47 53.029	-120 46.907	Full rehab needed
177	Landing	47 53.074	-120 46.618	Full rehab needed
178	Landing	47 53.051	-120 46.328	Full rehab needed
179	Landing	47 52.903	-120 45.683	Chip biomass 30' buf
180	Landing	47 52.925	-120 45.467	Full rehab needed
181	General Disturbance	47 52.987	-120 47.151	100' dozer lane
182	General Disturbance	47 53.03	-120 45.26	Pullout
183	Landing	47 52.906	-120 45.605	Georgia?
184	Culvert Damage	47 53.038	-120 46.868	Minor, North side
185	General Disturbance	47 53.018	-120 44.068	Pullout
186	Invasive Plant Species	47 52.293	-120 41.796	Snapweed patch
187	Landing	47 53.477	-120 48.635	
189	Landing	47 50.3	-120 40.221	
190	Landing	47 50.585	-120 37.33	
191	Culvert Damage	47 53.002	-120 47.091	Minor, squished
192	Landing	47 52.972	-120 47.621	Turn around
193	Landing	47 50.835	-120 38.324	
194	Riparian Damage	47 51.763	-120 41.14	wet area
195	General Disturbance	47 52.198	-120 41.046	Skyline area
196	Landing	47 52.672	-120 43.028	
197	Landing	47 52.22	-120 42.102	
198	Landing	47 51.941	-120 41.046	
199	Landing	47 52.571	-120 42.877	
200	Landing	47 52.485	-120 42.856	
201	Culvert Damage	47 52.713	-120 43.587	Full rehab needed
202	Landing	47 52.884	-120 43.926	
203	Landing	47 53.092	-120 44.837	

Repair Areas	Repair Firelines	Repair Skid Trails	Ownership	Harvest Units	Decommissioned Roads
Needed	Needed	Needed	WA DNR	Harvest Units	Decommissioned Roads
In Progress	In Progress	In Progress	USFS	Completed Dozer Line	Existing Roads
Completed	Completed	Completed	WA State Parks and Rec	Riparian Reserves	Temp Roads
Agency Approved	Approved	Approved		Culvert Locations	Trails

