



- Dip Site
- Drop Point
- Helispot
- Landmark
- Pump
- Division Break
- Completed - Inspected
- Completed - Ready for Inspection
- In Progress
- Repair Needed
- No Repair Needed
- Other - See Comments
- Unknown If Repair Needed
- Uncontrolled Fire Edge
- Completed Line
- Completed Dozer Line
- H - Completed Hand Line
- R - Road as Completed Line
- Brushed Road
- Completed - Inspected
- Completed - Ready for Inspection
- In Progress
- Repair Needed
- No Repair Needed
- Other - See Comments
- Unknown If Repair Needed
- potential increase erosion

Copyright:© 2013 National Geographic Society, Inc.