




















**Miller Complex
Rehab Map Packet
OR-RSF-000647
Rogue River Siskiyou
National Forest
October 24, 2017**



- ★ Towns
- Fire Area























-  Division Break
-  Helispot
-  Drop Point
-  Water Source
-  Hazard Road Impassable
-  Pump
-  Completed - Inspected
-  Completed - Ready for Inspection
-  In Progress
-  Repair Needed
-  Seeding Needed
-  Seeding Complete
-  Completed - Inspected
-  Completed - Ready for Inspection
-  In Progress
-  Repair Needed
-  Chipping Needed




Page 2


















Page 1




Page 3
























-  Division Break
-  Helispot
-  Drop Point
-  Water Source
-  Hazard Road Impassable
-  Pump
-  Completed - Inspected
-  Completed - Ready for Inspection
-  In Progress
-  Repair Needed
-  Seeding Needed
-  Seeding Complete
-  Completed - Inspected
-  Completed - Ready for Inspection
-  In Progress
-  Repair Needed
-  Chipping Needed























-  Division Break
-  Helispot
-  Drop Point
-  Water Source
-  Hazard Road Impassable
-  Pump
-  Completed - Inspected
-  Completed - Ready for Inspection
-  In Progress
-  Repair Needed
-  Seeding Needed
-  Seeding Complete
-  Completed - Inspected
-  Completed - Ready for Inspection
-  In Progress
-  Repair Needed
-  Chipping Needed




















-  Division Break
-  Helispot
-  Drop Point
-  Water Source
-  Hazard Road Impassable
-  Pump
-  Completed - Inspected
-  Completed - Ready for Inspection
-  In Progress
-  Repair Needed
-  Seeding Needed
-  Seeding Complete
-  Completed - Inspected
-  Completed - Ready for Inspection
-  In Progress
-  Repair Needed
-  Chipping Needed























-  Division Break
-  Helispot
-  Drop Point
-  Water Source
-  Hazard Road Impassible
-  Pump
-  Completed - Inspected
-  Completed - Ready for Inspection
-  In Progress
-  Repair Needed
-  Seeding Needed
-  Seeding Complete
-  Completed - Inspected
-  Completed - Ready for Inspection
-  In Progress
-  Repair Needed
-  Chipping Needed























DIV D




-  Division Break
-  Helispot
-  Drop Point
-  Water Source
-  Hazard Road Impassible
-  Pump
-  Completed - Inspected
-  Completed - Ready for Inspection
-  In Progress
-  Repair Needed
-  Seeding Needed
-  Seeding Complete
-  Completed - Inspected
-  Completed - Ready for Inspection
-  In Progress
-  Repair Needed
-  Chipping Needed



-  Division Break
-  Helispot
-  Drop Point
-  Water Source
-  Hazard Road Impassable
-  Pump
-  Completed - Inspected
-  Completed - Ready for Inspection
-  In Progress
-  Repair Needed
-  Seeding Needed
-  Seeding Complete
-  Completed - Inspected
-  Completed - Ready for Inspection
-  In Progress
-  Repair Needed
-  Chipping Needed



-  Division Break
 -  Helispot
 -  Drop Point
 -  Water Source
 -  Hazard Road Impassable
 -  Pump
 -  Completed - Inspected
 -  Completed - Ready for Inspection
 -  In Progress
 -  Repair Needed
 -  Seeding Needed
 -  Seeding Complete
-
-  Completed - Inspected
 -  Completed - Ready for Inspection
 -  In Progress
 -  Repair Needed
 -  Chipping Needed



Page 4

Page 5

Page 7

Page 8

Page 9


















Page 12



Page 13


Page 4


















Page 3



Page 8


















-  Division Break
-  Helispot
-  Drop Point
-  Water Source
-  Hazard Road Impassable
-  Pump
-  Completed - Inspected
-  Completed - Ready for Inspection
-  In Progress
-  Repair Needed
-  Seeding Needed
-  Seeding Complete
-  Completed - Inspected
-  Completed - Ready for Inspection
-  In Progress
-  Repair Needed
-  Chipping Needed








-  Division Break
-  Helispot
-  Drop Point
-  Water Source
-  Hazard Road Impassable
-  Pump
-  Completed - Inspected
-  Completed - Ready for Inspection
-  In Progress
-  Repair Needed
-  Seeding Needed
-  Seeding Complete
-  Completed - Inspected
-  Completed - Ready for Inspection
-  In Progress
-  Repair Needed
-  Chipping Needed





















-  Division Break
-  Helispot
-  Drop Point
-  Water Source
-  Hazard Road Impassable
-  Pump
-  Completed - Inspected
-  Completed - Ready for Inspection
-  In Progress
-  Repair Needed
-  Seeding Needed
-  Seeding Complete
-  Completed - Inspected
-  Completed - Ready for Inspection
-  In Progress
-  Repair Needed
-  Chipping Needed






















Page 11

T40S R5W



-  Division Break
-  Helispot
-  Drop Point
-  Water Source
-  Hazard Road Impassable
-  Pump
-  Completed - Inspected
-  Completed - Ready for Inspection
-  In Progress
-  Repair Needed
-  Seeding Needed
-  Seeding Complete
-  Completed - Inspected
-  Completed - Ready for Inspection
-  In Progress
-  Repair Needed
-  Chipping Needed



-  Division Break
-  Helispot
-  Drop Point
-  Water Source
-  Hazard Road Impassable
-  Pump
-  Completed - Inspected
-  Completed - Ready for Inspection
-  In Progress
-  Repair Needed
-  Seeding Needed
-  Seeding Complete
-  Completed - Inspected
-  Completed - Ready for Inspection
-  In Progress
-  Repair Needed
-  Chipping Needed

