


Light Repair Lines	
	Completed - Inspected
	Completed - Ready for Inspection
	In Progress
	Repair Needed
	No Repair Needed
	Other - See Comments
	Structures
	Trail
	Unknown
	Completed Hand Line
	Uncontrolled Fire Edge
	Road as Completed Line
	Completed Dozer Line
Repair Status Point	
	Completed - Inspected
	Completed - Ready for Inspection
	In Progress
	Repair Needed
	No Repair Needed
	Other - See Comments
	Unknown
Repair Status Line	
	Completed - Inspected
	Completed - Pending Engineer Inspection

Cougar Creek

WA-OWF-000419



200' Contour Interval

