


# Archie Creek OR-UPF-000436 10/6/2020

## Suppression Repair Map 131,542 Acres

- Airstrip or Airport
- Camp
- Clean Up Area
- Closure
- Culvert
- Dip Site
- Drop Point
- Dozer Push
- Fence - Cut/Damaged
- Fire Origin
- Hazard
- Hazard Tree
- Helispot
- Hot Spot
- Incident Command Post
- Internet Access
- Landmark
- Landing or Log Deck
- Lookout
- Mobile Weather Unit
- Repair Point
- Repeater
- Resource Location
- Road Repair
- Safety Zone
- Staging Area
- Stream Crossing
- Water Source
- Restricted Water Source
- Potential Draft Site
- Value at Risk
- Unknown
- Division Break
- Uncontrolled Fire Edge
- Contained Line
- Completed Dozer Line
- Completed Hand Line
- Road as Completed Line
- Access or Improved Road
- Line Break Completed
- Completed Burnout
- Proposed Dozer Line
- Planned Fire Line
- Planned Secondary Line
- Temporary Flight Restriction
- Road Repair
- Management Action Point
- Unknown

- ### Repair Status
- Completed - Inspected
  - In Progress
  - Repair Needed
  - No Repair Needed
  - Other - See Comments
  - Unknown
- 
- █ Completed - Inspected
  - █ In Use - Fire Management
  - █ Completed - Ready for Inspection
  - █ In Progress
  - █ Repair Needed
  - █ No Repair Needed
  - █ Unknown

FeatureCat	Label	Repair Stat	RepairComm	LatWGS84	LongWGS84
Spot Fire	1	Unknown	Hose lay with hand line	43° 21' 120"	122° 43' 756"
Spot Fire	2	Repair Needed	Bottom of spot fire with hose and hand line	43° 18' 099"	122° 43' 671"
Hazard	3	Unknown	Handout with valve seat	43° 18' 355"	122° 43' 687"
Water Development	4	Unknown	Draft Site	43° 15' 918"	122° 49' 732"
Dozer Push	5	Repair Needed	Dozer push out with small log deck	43° 22' 701"	122° 45' 752"
Spot Fire	6	Unknown	Hand line with hose lay	43° 24' 857"	122° 46' 957"
Road Repair	8	Repair Needed	Slide area	43° 14' 983"	122° 46' 014"
Road Repair	9	Repair Needed	Road Shoulder Damage	43° 15' 958"	122° 45' 503"
Dozer Push	10	Repair Needed	Handout with hose lay	43° 17' 747"	122° 45' 957"
Repair Point	11	Repair Needed	hand line to river needs waffles/water bars	43° 20' 559"	122° 44' 096"
Culvert	12	Repair Needed	Clear Culvert Crossing	43° 16' 508"	122° 43' 470"
Hazard	14	Repair Needed	will need to be decompressed, seeded, and mulched	43° 18' 096"	122° 46' 096"
Repair Point	15	Repair Needed	super steep dozer pitch, may need hand crew repair	43° 18' 678"	122° 46' 776"
Landing or Log Deck	16	Repair Needed	chipper maybe	43° 16' 960"	122° 43' 670"
Staging Area	17	Repair Needed	may be flow up and reseed against knapweed	43° 18' 242"	122° 43' 954"
Repair Point	18	Repair Needed	clean out roadside ditches	43° 18' 937"	122° 43' 324"
Dozer Push	19	Repair Needed	burnaround area	43° 16' 973"	122° 43' 319"
Landing or Log Deck	20	Repair Needed	deck	43° 17' 247"	122° 44' 324"
Repair Point	23	Repair Needed	Needs Machine Piled	43° 26' 088"	122° 47' 868"
Dozer Push	24	Repair Needed	Big Push In Old Thinning	43° 23' 498"	122° 46' 690"
Landing or Log Deck	25	Repair Needed	Decayed LOG	43° 23' 534"	122° 46' 690"
Stream Crossing	26	Repair Needed	Dozer Stuck In Wet Area Push Out	43° 22' 628"	122° 47' 051"
Staging Area	27	Repair Needed	Log Deck	43° 21' 663"	122° 45' 762"
Landing or Log Deck	29	Repair Needed	Log Deck	43° 21' 663"	122° 45' 762"
Landing or Log Deck	30	Repair Needed	Log Deck	43° 25' 048"	122° 46' 791"
Culvert	31	Repair Needed	Culvert crossing may need to be cleared out	43° 18' 508"	122° 43' 470"
Road Repair	32	Repair Needed	Investigate if from operations	43° 15' 958"	122° 45' 503"
Dozer Push	33	Repair Needed	30 x 15 area	43° 17' 794"	122° 42' 957"
Culvert	34	Repair Needed	burn culvert, exposed hole in road to culvert	43° 17' 247"	122° 43' 954"
Dozer Push	35	Repair Needed	staging area dozer opened a bit, reseed against knapweed	43° 18' 489"	122° 44' 121"
Culvert	36	Repair Needed	pipe segments unclear if burned	43° 20' 530"	122° 44' 434"
Repair Point	37	Repair Needed	Chip small brush pile	43° 24' 857"	122° 46' 102"
Repair Point	38	Repair Needed	tree on roadside may need chipper	43° 18' 994"	122° 44' 352"
Repair Point	39	Repair Needed	some roadside debris/wood	43° 18' 718"	122° 44' 630"
Dozer Push	40	Repair Needed	push-out	43° 18' 824"	122° 44' 135"
Clean Up Area	41	Repair Needed	Hydraulic Spill	43° 20' 510"	122° 43' 534"
Repair Point	42	Repair Needed	dozerline waterbars here	43° 18' 499"	122° 46' 290"
Dozer Push	43	Repair Needed	dozer push-out	43° 18' 859"	122° 42' 110"
Dozer Push	44	Repair Needed	dozer push-out	43° 18' 859"	122° 42' 110"
Dozer Push	45	Repair Needed	dozer push-out	43° 15' 762"	122° 45' 542"
Repair Point	46	Repair Needed	bars soil coming downhill	43° 15' 672"	122° 44' 923"
Stream Crossing	47	Repair Needed	crossing	43° 15' 810"	122° 41' 883"
Culvert	48	Repair Needed	Culvert crossing may need to be cleared out	43° 16' 508"	122° 43' 470"
Landing or Log Deck	49	Repair Needed	decks	43° 18' 402"	122° 46' 474"
Resource Location	50	Repair Needed	slumpy spot in road	43° 18' 402"	122° 44' 072"
Repair Point	51	Repair Needed	start of 083 roped road	43° 14' 094"	122° 54' 247"
Repair Point	52	Repair Needed	small trees roadside chip or ring into black	43° 18' 547"	122° 44' 523"
Repair Point	53	Repair Needed	scratch line around equipment	43° 20' 528"	122° 44' 385"
Resource Location	54	Repair Needed	gravel raveling from filling bed	43° 20' 498"	122° 43' 513"
Road Repair	55	Repair Needed	dozer widened road	43° 14' 990"	122° 41' 910"
Road Repair	56	Repair Needed	dozer widened shoulder	43° 17' 138"	122° 41' 976"
Staging Area	57	Repair Needed	equipment staging turn-around 40 ft wide	43° 17' 676"	122° 41' 262"
Unknown	58	Repair Needed	turnout	43° 18' 824"	122° 42' 135"
Staging Area	59	Repair Needed	burn-out dozer staging possible	43° 17' 002"	122° 42' 036"
Road Repair	60	Repair Needed	dip in road	43° 18' 201"	122° 41' 301"
Landing or Log Deck	61	No Repair Needed	dip in road	43° 18' 924"	122° 49' 791"
Staging Area	63	Repair Needed	proposed clearing for transports	43° 11' 183"	122° 43' 681"
Dozer Push	64	Repair Needed	fat dozer back and pump, needs beam pulled back, reroaded	43° 18' 668"	122° 48' 538"
Repair Point	65	Repair Needed	main travel route, need rock to repair 6' x 6' mud hole	43° 14' 800"	122° 48' 570"
Road Repair	66	Repair Needed	road push, need engineer to look at potential drainage issues	43° 18' 350"	122° 46' 666"
Repair Point	67	Repair Needed	road push, need engineer to look at potential drainage issues	43° 18' 350"	122° 46' 666"
Staging Area	68	Repair Needed	might need to clean up road after heavy eqpt	43° 14' 907"	122° 48' 362"
Repair Point	69	Repair Needed	deck	43° 18' 556"	122° 44' 750"
Dozer Push	70	Repair Needed	push-out needs to be covered	43° 18' 488"	122° 42' 496"
Landing or Log Deck	71	Repair Needed	sub soiling outside road prism, seed and slash/straw	43° 15' 924"	122° 42' 503"
Dozer Push	72	Repair Needed	Push	43° 16' 547"	122° 47' 314"
Road Repair	73	Repair Needed	Debris, burning under road bed	43° 22' 699"	122° 43' 382"
Road Repair	74	Repair Needed	Trub grinder, may need loader	43° 21' 244"	122° 44' 036"
Repair Point	75	Repair Needed	water tower burned during back burn	43° 20' 471"	122° 44' 301"
Dozer Push	76	Repair Needed	Dozer cut into bank to widen road	43° 18' 828"	122° 43' 114"
Culvert	77	Repair Needed	Culvert burned away, Water turning under road	43° 17' 222"	122° 53' 771"
Repair Point	78	Repair Needed	damage to water tower during back burn	43° 17' 910"	122° 53' 956"
Dozer Push	79	Repair Needed	Dip in road, may need repair to access log deck on 4714-704	43° 18' 857"	122° 42' 757"



10/5/2020 @ 2119  
NAD 1983 UTM Zone 10N  
GIS  
Latest Intel:  
20201002 @ 2027 hrs

