

## Repair points (located on BLM & USFWS) only

	I ( -			- / - /		
Incident Name	FC Point Type	Label	Comments	Repair Status	Repair Comments	LND_MGR
Beachie Creek	Lookout		Cut p-line and flagged 2/10 of mile to lookout point.	Repair Needed		USFS
Beachie Creek	Culvert		Culvert filling up from erosion on bank above.	Repair Needed		USFS
Beachie Creek	Other		Retaining log burnt out on road. Road failing and cracking.	Repair Needed		USFS
Beachie Creek	Other		Culvert and ditch full of debris road washing out.	Repair Needed	Excavator?	USFS
Beachie Creek	Other		Ditch below culvert full -entire mile.	Repair Needed		USFS
Beachie Creek	Hazard		Rick face crumbling into road large rocks falling	Repair Needed	Scaling? Excavator?	USFS
Beachie Creek	Culvert		Melted plastic culvert	Repair Needed	BAER ALERT - FSR 2223-520, MP 10.79 (from hwy 22), remove and replace with 32' x 24" culvert.	USFS
Beachie Creek	Culvert		Melted plastic Culvert	Repair Needed	BAER ALERT - FSR 2223-520, MP 11.21 (from hwy 22), remove and replace with 32' x 24" culvert.	USFS

## Repair lines (located on BLM & USFWS) only

Incident Name	FC Line Type	Comments	Repair Status	Repair Comments	LND_MGR	Length Feet
Beachie Creek	Other	P-line to lookout point. Cut brush/small trees and flagged line. Vegetation loss to 18" wide tread.	Repair Needed	Cover with brush. Pull flagging	USFS	1046
Beachie Creek	Completed Dozer Line	BLM and state lands, repair per local unit specs. width varies	Repair Needed	water bars as needed, obliterate berms and dozer pushes; 10/15 Theve and Garcia confirms needs work, possibly block roads, seed stream crossing	BLM	5431
Beachie Creek	Completed Dozer Line	CPI road bull dozed open. Road seems to be on existing road.	Repair Needed	Waterbar as appropriate and seed roads, cut banks and entrances off of Hwy 22. Approximately 15 water bars will be needed. Recommend mini or medium sized excavator. Trash left behind by CPI including old telephone poles, insulators, wire, beverage bottles, food wrappers, etc.	USFS	1747
Beachie Creek	Road as Completed Line	Recieved via Shapefile from Joseph Doerr WMNF	Repair Needed	Road as Line Needed to be Added and Repaired	USFS	21283
Beachie Creek	Road as Completed Line	Recieved via Shapefile from Joseph Doerr WMNF	Repair Needed	Road as Line Needed to be Added and Repaired	USFS	20946
Beachie Creek	Road as Completed Line	Recieved via Shapefile from Joseph Doerr WMNF	Repair Needed	Road as Line Needed to be Added and Repaired	USFS	19098
Beachie Creek	Road as Completed Line	Recieved via Shapefile from Joseph Doerr WMNF	Repair Needed	Road as Line Needed to be Added and Repaired	USFS	1861
Beachie Creek	Road as Completed Line	Recieved via Shapefile from Joseph Doerr WMNF	Repair Needed	Road as Line Needed to be Added and Repaired	USFS	983
Beachie Creek	Road as Completed Line	Recieved via Shapefile from Joseph Doerr WMNF	Repair Needed	Road as Line Needed to be Added and Repaired	USFS	73045
Beachie Creek	Road as Completed Line	Recieved via Shapefile from Joseph Doerr WMNF	Repair Needed	Road as Line Needed to be Added and Repaired	USFS	10982
Beachie Creek	Road as Completed Line	Recieved via Shapefile from Joseph Doerr WMNF	Repair Needed	Road as Line Needed to be Added and Repaired	USFS	28811
Beachie Creek	Road as Completed Line	Recieved via Shapefile from Joseph Doerr WMNF	Repair Needed	Road as Line Needed to be Added and Repaired	USFS	9750
Beachie Creek	Road as Completed Line	Recieved via Shapefile from Joseph Doerr WMNF	Repair Needed	Road as Line Needed to be Added and Repaired	USFS	2621
Beachie Creek	Road as Completed Line	Recieved via Shapefile from Joseph Doerr WMNF	Repair Needed	Road as Line Needed to be Added and Repaired	USFS	2621
Beachie Creek	Road as Completed	Recieved via Shapefile from	Repair Needed	Road as Line Needed to be Added and Repaired	USFS	1861







