

Summary of Div K			
Repair Status	Percent	Length (mi)	Length (ft)
Completed - Ready for Inspection	5.26%	2.10	11087
In Progress	30.18%	12.04	63558
Repair Needed	61.58%	24.56	129693
Div K		39.89	210593
Access or Improved Road		2.11	11147
Repair Needed		2.11	11147
Completed Dozer Line		2.18	11488
Completed - Ready for Inspection		0.17	875
In Use - Fire Management		0.37	1967
Repair Needed		1.64	8646
Completed Hand Line		2.64	13935
Completed - Ready for Inspection		1.67	8794
In Use - Fire Management		0.05	238
Repair Needed		0.93	4903
Completed Road as Line		25.71	135735
Completed - Ready for Inspection		0.27	1418
In Progress		11.87	62689
In Use - Fire Management		0.58	3087
Repair Needed		12.98	68541
Other		0.18	963
Unknown		0.18	963
Repair Line		6.94	36651
In Progress		0.16	869
Repair Needed		6.78	35782
Road Repair		0.13	674
Repair Needed		0.13	674