

Summary of Div A

Repair Status	Percent	Length (mi)	Length (ft)
Completed - Inspected	12.49%	5.20	27438
Completed - Ready for Inspection	37.85%	15.75	83183
In Progress	34.59%	14.40	76018
Repair Needed	15.06%	6.27	33099
Div A		41.62	219749
Access or Improved Road		11.34	59856
Completed - Ready for Inspection		0.23	1199
In Progress		6.26	33073
Repair Needed		4.85	25584
Completed Dozer Line		5.78	30506
Completed - Inspected		0.29	1543
Completed - Ready for Inspection		0.81	4259
In Progress		3.98	20989
Repair Needed		0.70	3715
Completed Fuel Break		0.90	4742
Completed - Inspected		0.90	4742
Completed Hand Line		0.28	1481
Completed - Inspected		0.17	906
In Progress		0.11	575
Completed Mixed Construction Line		0.04	186
Repair Needed		0.04	186
Completed Road as Line		20.67	109146
Completed - Inspected		2.48	13070
Completed - Ready for Inspection		14.58	77004
In Progress		3.53	18664
Repair Needed		0.08	408
Other		0.00	11
Unknown		0.00	11
Repair Line		2.62	13821
Completed - Inspected		1.36	7177
Completed - Ready for Inspection		0.14	721
In Progress		0.51	2717
Repair Needed		0.61	3206