




SUPPRESSION REPAIR
BULL COMPLEX
 OR-MHF-000753
 9/29/2021 DAY
 24,894 ACRES ON 9/25/2021 @ 2004



Summary of Total Fire *does not include NF46

Repair Status	Length (mi)	Percent
Completed - Inspected	16.97	10.99%
Completed - Ready for Inspection	48.07	31.14%
In Progress	41.44	26.84%
Repair Needed	46.42	30.07%
Total Line	154.39	

Summary of Div G

Repair Status	Percent	Length (mi)	Length (ft)
Completed - Ready for Inspection	26.60%	3.52	18563
In Progress	23.89%	5.25	27725
Repair Needed	60.12%	13.21	69775
Div G		21.98	116063
Access or Improved Road		1.87	9881
Repair Needed		1.87	9881
Completed Dozer Line		2.27	11999
Completed - Ready for Inspection		0.24	1261
In Progress		1.30	6853
Repair Needed		0.74	3885
Completed Hand Line		0.63	3344
Repair Needed		0.63	3344
Completed Road as Line		16.13	85153
Completed - Ready for Inspection		3.28	17302
In Progress		3.95	20872
Repair Needed		8.90	46979
Repair Line		1.08	5686
Repair Needed		1.08	5686

Div G

Repair Status Point

- Completed - Inspected
- In Use - Fire Management
- Repair Needed
- No Repair Needed
- Other - See Comments
- Unknown

Repair Status Line

- In Use - Fire Management
- Completed - Ready for Inspection
- In Progress
- Repair Needed

Legend

- Dip Site
- Helispot
- Division Break
- Drop Point
- Staging Area
- Lookout
- Water Development or Draft Site
- Structure Wrap
- Stream Crossing
- Resource Location
- Repair Point
- Landing or Log Deck
- Fence - Cut/Damaged
- Dozer Push
- Culvert
- Clean Up Area
- Mobile Weather Unit
- Water Source
- Completed Dozer Line
- Completed Hand Line
- Completed Road as Line
- Access or Improved Road
- Repair Line
- Wildfire Daily Fire Perimeter
- Basic Custodial Care: 1 (CLOSED)
- High Clearance Vehicles: 2
- Wilderness
- USFS Admin Boundary
- Historic Fire Perimeter
- US Forest Service (USFS)
- County Boundary

Grading in progress, planning to finish after dozer line to North is repaired

Active Rock Pit

