


Suppression Repair Rough Patch Complex South

September 19, 2021
Jack Fire: 24,165 ac
Rough Patch Complex: 50,172 ac



© 2021 NIMS
North American 1983 Edition, Cartography Data

| | | | | | | | |
|--|--|--|---|--|---|--|---|
| <ul style="list-style-type: none"> Structures Check Point (RB) Dip Site Camp Helibase Sling Site Unimproved Landing Area Division Break Branch Break Zone Break Medical | <ul style="list-style-type: none"> Incident Command Post Drop Point Closure Retardant in Avoidance Area Resource Location Repair Point Landing or Log Deck Hazard Tree Dozer Push Culvert Mobile Weather Unit | <ul style="list-style-type: none"> Structure Wrap Stream Crossing Road Repair Retardant in Avoidance Area Resource Location Repair Point Landing or Log Deck Hazard Tree Dozer Push Culvert Mobile Weather Unit | <ul style="list-style-type: none"> Internet Access Repeater Hazard Water Source Restricted Water Source Completed Burnout Completed Dozer Line Completed Fuel Break Completed Hand Line Completed Mixed Construction Line Completed Road as Line | <ul style="list-style-type: none"> Access or Improved Road Other Repair Line Road Repair Escape Route Foam Drop Retardant Drop Contained Line Wildfire Daily Fire Perimeter Timber Sales | <ul style="list-style-type: none"> Forest Service Roads Paved Road Gravel Road Dirt Roads Unimproved Roads Sensitive Areas Forest Service Land Wilderness BLM Private | <ul style="list-style-type: none"> Repair Point Completed - Inspected In Use - Fire Management Completed - Ready for Inspection In Progress Repair Needed No Repair Needed Other - See Comments Unknown | <ul style="list-style-type: none"> Repair Line Completed - Inspected In Use - Fire Management Completed - Ready for Inspection In Progress Repair Needed No Repair Needed Other - See Comments Unknown |
|--|--|--|---|--|---|--|---|