Label FC Point Type	Repair Status	Repair Comments
	•	•
47353 Landing or Log Dec	k Repair Needed	Logs will not be processed, designated for fish habitat material.
53622 Landing or Log Dec	k Unknown	
56509 Safety Zone	Repair Needed	Safety zone dozed to bare mineral soil. Will need to be reseeded PardueREAF 8/31/21
57532 Landing or Log Dec	k Repair Needed	Logs will not be processed, designated for fish habitat material.
58000 Landing or Log Dec	k Repair Needed	Logs will not be processed, designated for fish habitat material.
58552 Landing or Log Dec	k Repair Needed	Logs will not be processed, designated for fish habitat material.
58664 Repair Point	Repair Needed	Pile to be burned. Standard repair for old deck. Lots of bare mineral soil from skidding PardueREAF 8/31/21
59121 Repair Point	Repair Needed	Pile to be burned. Standard repair for old deck. Lots of bare mineral soil from skidding PardueREAF 8/31/21
60277 Landing or Log Dec	k Repair Needed	Logs will not be processed, designated for fish habitat material.
61599 Repair Point	Repair Needed	Pile to be burned. Standard repair for old deck. Lots of bare mineral soil from skidding PardueREAF 8/31/21
61651 Landing or Log Dec	k Repair Needed	Move logs for project on Little Naches. Process trees larger than 11" dbh, buck to 35 to 41 feet. Under 11" leave unprocessed
61657 Landing or Log Dec	k Repair Needed	Logs will not be processed, designated for fish habitat material.
65946 Landing or Log Dec	k Repair Needed	Logs will not be processed, designated for fish habitat material.
66345 Repair Point	Completed - Ready for Inspection	1
67323 Safety Zone	Repair Needed	Safety zone dozed to bare mineral soil. Will need to be reseeded PardueREAF 8/31/21
69403 Drop Point	Completed - Ready for Inspection	DP and surrounding repaired area seeded with about 28 pounds of seed 9/29/21.
70138 Landing or Log Dec	k Repair Needed	Standard repair
75233 Other	Unknown	
75814 Helispot	Unknown	
75929 Value at Risk	Unknown	NA

lengthen tank trap to include bypass

76498 Landing or Log Deck Unknown

77861 Landing or Log Deck Repair Needed

Repair Needed

76903 Landing or Log Deck Completed - Ready for Inspection

Unknown

Unknown

76691 Repair Point

76904 Repair Point

76905 Repair Point

Repair Point Table Schneider Springs WA-OWF-000453 Page 2 of 7

Label FC Point Type	Repair Status	Repair Comments
59486 Helispot	Completed - Ready for Inspection	Repair completed 29 September 21
62536 Helispot	Unknown	
68534 Dozer Push	Repair Needed	Block line with fill. I100 feet in length
75160 Repair Point	Completed - Ready for Inspection	Decomm spur road. Repair completed 29 September 21
75370 Repair Point	Repair Needed	Cut and pile or remove material
75664 Landing or Log Deck	c In Progress	
75877 Repair Point	Repair Needed	
76960 Landing or Log Deck	Completed - Ready for Inspection	Repair completed 29 September 21

Completed - Ready for Inspection Repair completed 29 September 21

76961 Repair Point

Road side slash along 1613 road. Needs to be chipped or piled

Label FC Point Type	Repair Status	Repair Comments
47926 Landing or Log Deck	Repair Needed	
53593 Landing or Log Deck	Unknown	Deck moved to the main landing site on 1603
59030 Other	Repair Needed	200 feet of hose left in woods. Needs to be picked up
60686 Dozer Push	Unknown	
60737 Drop Point	Unknown	
60868 Dozer Push	Completed - Ready for Inspection	Rip heavily compacted portions, spread pushed berms, seed. Repair completed 09/29/21
64682 Culvert	Repair Needed	Standard
65655 Drop Point	Unknown	
66738 Dozer Push	Unknown	
67407 Landing or Log Deck	Unknown	Deck moved to main landing site on 1603
71442 Repair Point	Repair Needed	
71863 Drop Point	Unknown	

76743 Repair Point

Repair Needed

Label FC Point Type Repair Status Repair Comments

Repair Point Table Schneider Springs WA-OWF-000453 Page 5 of 7

Label FC Point Type	Repair Status	Repair Comments
47498 Repair Point	Kepan Status	Repair comments
52097 Dozer Push	Repair Needed	Seed
52220 Landing or Log Deck	Repair Needed	Deck present 9/11/21. Slash pile needs to be re-piled without soil. Recontour and seed
54343 Landing or Log Deck	Repair Needed	Standard
56216 Staging Area	Completed - Ready for Inspection	Seeded 9/28/21 .5 lbs
56844 Landing or Log Deck	Repair Needed	
58235 Landing or Log Deck	Repair Needed	Seeded 9/28/21 REAF Miner 10lbs
58848 Landing or Log Deck	Repair Needed	Pull berms, seed and slash N and S sides of road
58982 Repair Point	Repair Needed	Recontour, slash
59741 Drop Point	Repair Needed	
61407 Dozer Push	Repair Needed	Large open landing area, rip (decompact) and spread slash pile. Seeded 9/28/21 17lbs REAF Miner
61560 Repair Point	Repair Needed	Seeding
61611 Repair Point	Repair Needed	Material needs to be repiled, seeding, slash, berm against Jeep trail
63464 Landing or Log Deck	Unknown	
63474 Landing or Log Deck	Repair Needed	Recontour, berm and slash
64043 Dozer Push	Repair Needed	Standard
64669 Landing or Log Deck	Unknown	
66533 Landing or Log Deck	Repair Needed	
66567 Landing or Log Deck	Repair Needed	Clean up slash
67146 Landing or Log Deck	Repair Needed	Decompact, spread slash pile out. Seeded 6lbs 9/28/21 REAF Miner
67275 Landing or Log Deck	Repair Needed	Needs to be seeded
70130 Safety Zone	Unknown	
75663 Repair Point	Unknown	Standard repair
75963 Landing or Log Deck	Unknown	Standard repair

Needs berm pulled back, recontour, slash. Seeded 9/28/21 REAF Miner .5lbs

77713 Dozer Push

Repair Needed

Label FC Point Type	Repair Status Repair Comments		
46652 Stream Crossing	Repair Needed Pull back berm, armor creek bank with logs and rocks.		
48590 Landing or Log De	Repair Needed pre-existing, seed as needed. Skid trails around outer perimeter need slash		
52952 Drop Point	Repair Needed		
53472 Stream Crossing	Repair Needed Pull back berm, pull sediment from creek, contour road, armor creek bank w. logs, rocks. seed, put in cottonwood poles. Avoid knapweed on east bank.		
54673 Landing or Log Deck Repair Needed			
54870 Landing or Log De	Repair Needed clear slash out of dispersed camping site, seed as needed		

59927 Resource Location Unknown

61431 Landing or Log Deck Unknown clear slash, seed as needed

63834 Landing or Log Deck Unknown 67059 Helispot Unknown

68049 Repair Point Repair Needed UA on far right needs contouring or berm; extend existing berm to tree on N side, berm s.b. be built up utilizing slash at adjacent landing

72963 Culvert Repair Needed Down slope culvert needs to be cleaned out

55170 Landing or Log Deck Repair Needed Narrow back to original width, decompact margins, seed

73539 Repair Point Repair Needed Standard repair needed. Establish edge of road. Heavy slash and rocks Repair Needed Remove rocks and debris. pipe may need replaced or end repaired.

74066 Landing or Log Deck Unknown

75221 Repair Point Repair Needed Standard repair needed. Establish edge of road. Heavy slash and rocks

Label FC Point Type Repair Status Repair Comments

47863 Landing or Log Deck Repair Needed Piles remain will need to be picked up. 8/31/21 PardueREAF

48230 Landing or Log Deck Repair Needed 8/31/21. PardueREAF Processed timber still in pile. Needs to be removed.

60111 Helispot Unknown 69884 Helispot Unknown

75665 Landing or Log Deck Repair Needed Standard repair