

Label	FC Point Type	Repair Status	Repair Comments
59486	Helispot	Completed - Ready for Inspection	Repair completed 29 September 21
62536	Helispot	Unknown	
68534	Dozer Push	Repair Needed	Block line with fill. I100 feet in length
75160	Repair Point	Completed - Ready for Inspection	Decomm spur road. Repair completed 29 September 21
75370	Repair Point	Repair Needed	Cut and pile or remove material
75664	Landing or Log Deck	In Progress	
75877	Repair Point	Repair Needed	
76960	Landing or Log Deck	Completed - Ready for Inspection	Repair completed 29 September 21
76961	Repair Point	Completed - Ready for Inspection	Repair completed 29 September 21