

| Label | FC Point Type | Repair Status | Repair Comments |
|--------------|----------------------|----------------------------------|--|
| 47926 | Landing or Log Deck | Repair Needed | |
| 53593 | Landing or Log Deck | Unknown | Deck moved to the main landing site on 1603 |
| 59030 | Other | Repair Needed | 200 feet of hose left in woods. Needs to be picked up |
| 60686 | Dozer Push | Unknown | |
| 60737 | Drop Point | Unknown | |
| 60868 | Dozer Push | Completed - Ready for Inspection | Rip heavily compacted portions, spread pushed berms, seed. Repair completed 09/29/21 |
| 64682 | Culvert | Repair Needed | Standard |
| 65655 | Drop Point | Unknown | |
| 66738 | Dozer Push | Unknown | |
| 67407 | Landing or Log Deck | Unknown | Deck moved to main landing site on 1603 |
| 71442 | Repair Point | Repair Needed | |
| 71863 | Drop Point | Unknown | |
| 76743 | Repair Point | Repair Needed | Road side slash along 1613 road. Needs to be chipped or piled |