

Label	FC Point Type	Repair Status	Repair Comments
46652	Stream Crossing	Repair Needed	Pull back berm, armor creek bank with logs and rocks.
48590	Landing or Log Deck	Repair Needed	pre-existing, seed as needed. Skid trails around outer perimeter need slash
52952	Drop Point	Repair Needed	
53472	Stream Crossing	Repair Needed	Pull back berm, pull sediment from creek, contour road, armor creek bank w. logs, rocks. seed, put in cottonwood poles. Avoid knapweed on east bank.
54673	Landing or Log Deck	Repair Needed	
54870	Landing or Log Deck	Repair Needed	clear slash out of dispersed camping site, seed as needed
55170	Landing or Log Deck	Repair Needed	Narrow back to original width, decompact margins, seed
59927	Resource Location	Unknown	
61431	Landing or Log Deck	Unknown	clear slash, seed as needed
63834	Landing or Log Deck	Unknown	
67059	Helispot	Unknown	
68049	Repair Point	Repair Needed	UA on far right needs contouring or berm; extend existing berm to tree on N side, berm s.b. be built up utilizing slash at adjacent landing
72963	Culvert	Repair Needed	Down slope culvert needs to be cleaned out
73539	Repair Point	Repair Needed	Standard repair needed. Establish edge of road. Heavy slash and rocks
73815	Culvert	Repair Needed	Remove rocks and debris. pipe may need replaced or end repaired.
74066	Landing or Log Deck	Unknown	
75221	Repair Point	Repair Needed	Standard repair needed. Establish edge of road. Heavy slash and rocks