			Waiter Creek WA-NLS-002243 03/00/2021
	FC Line Type	•	Repair Comments
	Access or Improved Road	•	·
54699	Access or Improved Road	Repair Needed	Standard class 2
54701	Access or Improved Road	Repair Needed	Standard, powder special
54705	Access or Improved Road	Repair Needed	Standard
54714	Access or Improved Road	Repair Needed	Standard check with lighting timber sale
54715	Access or Improved Road	Repair Needed	Standard
32870	Completed Dozer Line	Repair Needed	Standard repair
42965	Completed Dozer Line	Repair Needed	176
42967	Completed Dozer Line	Repair Needed	177
42968	Completed Dozer Line	Repair Needed	Standard, lots of spurs, circles
42970	Completed Dozer Line	Repair Needed	
42971	Completed Dozer Line	Repair Needed	
42972	Completed Dozer Line	Repair Needed	
42973	Completed Dozer Line	Repair Needed	
	Completed Dozer Line	•	Standard repair.
	Completed Dozer Line	•	Standard repair. Connects two roads.
	Completed Dozer Line	Repair Needed	·
	Completed Dozer Line	Repair Needed	
	Completed Dozer Line	Repair Needed	
	Completed Dozer Line	•	Standard repair. Check with district fuels/ timber
	Completed Dozer Line	•	Standard repair
	Completed Dozer Line		Standard repair. CHECK ROAD LAYER AND LIGHT SALE
	Completed Dozer Line		Standard repair. Dozer walked approx. 15 ft beyond line.
	Completed Dozer Line		Standard 75' section do 20' wide line
	Completed Dozer Line	Repair Needed	
	Completed Dozer Line	•	Standard, moderate, the road that shows on the layer underneath does not exist
	Completed Dozer Line	Repair Needed	·
	Completed Dozer Line	Repair Needed	
	Completed Dozer Line	•	Standard, low for machine high for seed two blades wide, around slash piles
	Completed Dozer Line	Repair Needed	
	Completed Dozer Line	-	Standard repair
	Completed Dozer Line	•	Standard repair Standard repair
	Completed Dozer Line  Completed Dozer Line	•	Standard repair
	Completed Dozer Line	•	Standard repair Standard repair
	•		
	Completed Dozer Line	Repair Needed	
	Completed Dozer Line	Repair Needed	
	Completed Dozer Line	•	Standard repair. See suppression repair plan.
	Completed Dozer Line	•	Standard, moderate need
	Completed Dozer Line	Repair Needed	
	Completed Dozer Line	Repair Needed	
	Completed Dozer Line	Repair Needed	
	Completed Dozer Line		Standard repair
	Completed Fuel Break	Repair Needed	
	Completed Fuel Break	•	Standard. Machine cut fuel break. Logs not yet decked
	Completed Fuel Break		Standard ; many decks need chipped or other solution.
	Completed Hand Line	•	This is the fire edge. No fire to the south of the line on the east side of the road. Very light in riparian, waterbar only where line was scratchedh
	Completed Road as Line		Outboard side cast
	•	•	Standard repair. Completed fuel break. Standard repair. Chipping, scattering, pile and burn option on hand slash. Grade road.
58542	Completed Road as Line	Repair Needed	

OBJECTID	FC Line Type	Repair Status	Repair Comments
29730	Access or Improved Road	Repair Needed	Standard Repair
50115	Access or Improved Road	Repair Needed	Standard
52061	Access or Improved Road	Repair Needed	Boulders need to put back to close road, standard
48692	Completed Dozer Line	In Progress	
49822	Completed Dozer Line	In Progress	Seed?
49850	Completed Dozer Line	In Progress	standard. water bars in place, berm pushed back and brushed.
52688	Completed Dozer Line	In Progress	Standard, equipment done needs seeding
52689	Completed Dozer Line	In Progress	Standard, needs seeding
55029	Completed Dozer Line	In Progress	Standard, Seeding?
55030	Completed Dozer Line	In Progress	Standard, heavy slash will be hard to seed
26824	Completed Dozer Line		Standard low priority
26825	•	Repair Needed	
26826	Completed Dozer Line	Repair Needed	Standard Repair, Some sections are on non system roads
26827	Completed Dozer Line	Repair Needed	Standard Repair
26828	Completed Dozer Line	Repair Needed	Standard
26829	Completed Dozer Line	Repair Needed	113 Standard Repair
26830	Completed Dozer Line	Repair Needed	Standard Repair
26831	Completed Dozer Line	Repair Needed	116 Standard Repair
26832	Completed Dozer Line	Repair Needed	Standard Repair
	Completed Dozer Line	•	114 Standard Repair
	•	Repair Needed	·
	·	•	Standard Repair
	Completed Dozer Line	•	Standard Low priority, seeding needed
	Completed Dozer Line	Repair Needed	· · · · ·
29738	Completed Dozer Line	Repair Needed	Standard
29740	Completed Dozer Line	Repair Needed	Standard
29742	Completed Dozer Line	Repair Needed	Standard Repair
30115	Completed Dozer Line	Repair Needed	Hazard trees everywhere , lots of downfall and other debris no mechanical repair needed
30116	Completed Dozer Line	Repair Needed	Standard
48682	Completed Dozer Line	Repair Needed	Standard. GPS track of previously represented dozer line
48690	Completed Dozer Line	Repair Needed	
48693	Completed Dozer Line	Repair Needed	Standard
49824	Completed Dozer Line	Repair Needed	
49825	Completed Dozer Line	Repair Needed	
49826	Completed Dozer Line	Repair Needed	Standard
49851	Completed Dozer Line	Repair Needed	Standard
49852	Completed Dozer Line	Repair Needed	Standard
49853	Completed Dozer Line	Repair Needed	
50346	Completed Dozer Line	Repair Needed	Standard,
52058	Completed Dozer Line	Repair Needed	DI around slash pile
52063	Completed Dozer Line	Repair Needed	Standard or seed only
52124	Completed Dozer Line	Repair Needed	Standard
52125	Completed Dozer Line	Repair Needed	Standard
52126	Completed Dozer Line	Repair Needed	Standard
52439	Completed Dozer Line	Repair Needed	Standard Low priority
53618	Completed Dozer Line	Repair Needed	Standard
58540	Completed Dozer Line	Repair Needed	Standard Repair
58545	Completed Dozer Line	Repair Needed	Standard Repair
58547	Completed Dozer Line	Repair Needed	
59258	Completed Dozer Line	Repair Needed	repair very low priority, rocky lots of wood on it all ready, smaller side cast
59259	Completed Dozer Line	Repair Needed	Pull berms, seed water bar where necessary, do not pull slash in case it was a road bed
59267	Completed Dozer Line	Repair Needed	Standard
29737	Completed Dozer Line	Unknown	
58538	Completed Dozer Line	Unknown	107
50839	Completed Fuel Break	Repair Needed	Excavator made line ,low priority
26834	Completed Road as Line	Repair Needed	97, ćheck nvum map, standard
26836	Completed Road as Line	Repair Needed	Standard
28077	Completed Road as Line	Repair Needed	81, nvum
30114	Completed Road as Line	Repair Needed	Standard
50347	Completed Road as Line	Repair Needed	Standard
52440	Completed Road as Line	Repair Needed	Standard
52441	Completed Road as Line	Repair Needed	Standard also needs chipping or scattering of windrow
58539	Completed Road as Line	Repair Needed	Standard Repair
59260	Completed Road as Line	Repair Needed	Standard

OBJECTID	FC Line Type	Repair Status	Repair Comments
52120	Access or Improved Road	Repair Needed	Standard repair
54699	Access or Improved Road	Repair Needed	Standard class 2
54701	Access or Improved Road	Repair Needed	Standard, powder special
54705	Access or Improved Road	Repair Needed	Standard
55648	Access or Improved Road	Repair Needed	Standard repair. Dozer walked down, pushed trees and veg to open. Berm removed at gate at perimeter.
57340	Completed Dozer Line	In Progress	Needs seeding
32870	Completed Dozer Line	Repair Needed	Standard repair
42965	Completed Dozer Line	Repair Needed	176
42968	Completed Dozer Line	Repair Needed	Standard, lots of spurs, circles
42973	Completed Dozer Line	Repair Needed	
44782	Completed Dozer Line	Repair Needed	Standard repair.
44784	Completed Dozer Line	Repair Needed	Standard repair. Connects two roads.
46813	Completed Dozer Line	Repair Needed	Standard repair. Old road opened up with dozer.
46814	Completed Dozer Line	Repair Needed	Standard repair
46815	Completed Dozer Line	Repair Needed	Standard repair
47263		Repair Needed	Standard repair
47264	•	•	Standard repair. Wet area at the very top of loop.
47265			Standard Repair
48528	· ·	Repair Needed	·
48529	•	Repair Needed	
49480		Repair Needed	
49481	•	Repair Needed	
50112	·	Repair Needed	
50113		Repair Needed	
50114	•	•	Standard repair. Check with district fuels/ timber
51148			Standard repair
	·	•	Standard repair. CHECK ROAD LAYER AND LIGHT SALE
54698	•	Repair Needed	·
54700	•	•	Standard, moderate, the road that shows on the layer underneath does not exist
54702		Repair Needed	
54703	•	Repair Needed	
54704		•	Standard, low for machine high for seed two blades wide, around slash piles
55575	•	•	Standard repair. See suppression repair plan.
55577	•		Standard repair
55651	·	Repair Needed	·
57338			Mix of blade up blade down standard where blade down
57339	•	Repair Needed	•
59134	•		Standard repair.
59135	•		Standard repair.
59136	•	•	Standard repair
32872		-	Standard Repair
33169			Standard Repair
36637	·	•	Standard repair.
38444		•	Standard repair
38445	•	Repair Needed	
38446			Standard. Machine cut fuel break. Logs not yet decked
39712	•	•	Standard repair
46816			Standard repair
55653		•	Standard repair Standard ; many decks need chipped or other solution.
42966			This is the fire edge. No fire to the south of the line on the east side of the road. Very light in riparian, waterbar only where line was scratchedh
44783	Completed Road as Line	•	
44785	·	•	Standard repair. Completed fuel break. Standard repair. Chipping, scattering, pile and burn option on hand slash. Grade road.
44/85	COLLIDICION NOGO AS LITE	TOPAH NECUCU	Standard Topan, Completed ruci break, Standard Topan, Chipping, Stattering, pile and buril Option on Idahu Siash. Grade Toau,

OBJECTID	FC Line Type	Repair Status	Repair Comments
52121	Access or Improved Road	Repair Needed	Standard repair.
35642	Completed Dozer Line	Repair Needed	1 Standard Repair
36611	Completed Dozer Line	Repair Needed	4 Standard Repair
36612	Completed Dozer Line	Repair Needed	3 Standard Repair
46813	Completed Dozer Line	Repair Needed	Standard repair. Old road opened up with dozer.
46814	Completed Dozer Line	Repair Needed	Standard repair
46815	Completed Dozer Line	Repair Needed	Standard repair
47263	Completed Dozer Line	Repair Needed	Standard repair
47264	Completed Dozer Line	Repair Needed	Standard repair. Wet area at the very top of loop.
47265	Completed Dozer Line	Repair Needed	Standard Repair
48528	Completed Dozer Line	Repair Needed	Standard
55575	Completed Dozer Line	Repair Needed	Standard repair. See suppression repair plan.
59134	Completed Dozer Line	Repair Needed	Standard repair.
59135	Completed Dozer Line	Repair Needed	Standard repair.
59136	Completed Dozer Line	Repair Needed	Standard repair
32872	Completed Fuel Break	Repair Needed	Standard Repair
33169	Completed Fuel Break	Repair Needed	Standard Repair
33859	Completed Fuel Break	Repair Needed	Standard repair.
34949	Completed Fuel Break	Repair Needed	standard
36104	Completed Fuel Break	Repair Needed	Standard Repair
36112	Completed Fuel Break	Repair Needed	Standard repair
36637	Completed Fuel Break	Repair Needed	Standard repair.
38444	Completed Fuel Break	Repair Needed	Standard repair
39712	Completed Fuel Break	Repair Needed	Standard repair
39713	Completed Fuel Break	Repair Needed	
40542	Completed Fuel Break	Repair Needed	Mechanical fuel break.' Grade road clean ditchline
42195	Completed Fuel Break	Repair Needed	Standard repair.
43865	Completed Fuel Break	Repair Needed	Standard repair.
46816	Completed Fuel Break	Repair Needed	Standard repair
52117	Completed Fuel Break	Repair Needed	Standard repair
52118	Completed Fuel Break	Repair Needed	Standard Repair. Fuel break and dozer line.
58516	Completed Fuel Break	Repair Needed	Standard Repair
58518	Completed Fuel Break	Repair Needed	Standard Repair
42194	Completed Fuel Break	Unknown	
34942	Completed Road as Line	Repair Needed	2 Standard Repair
34947	Completed Road as Line	Repair Needed	13 standard, rolling dips knock berms, keep drivable for this year patrol

OBJECTID	FC Line Type	Repair Status	Repair Comments
33515	Access or Improved Road	Repair Needed	18 Standard Repair
36614	Access or Improved Road	Repair Needed	20 Standard Repair. Close with earthen berm
52137	Access or Improved Road	Repair Needed	Standard repair.
53612	Access or Improved Road	Repair Needed	Standard repair.
28257	Completed Dozer Line	Repair Needed	Standard repair.
31569	Completed Dozer Line	Repair Needed	22 Standard Repair
31570	Completed Dozer Line	Repair Needed	25 Standard Repair
33167	Completed Dozer Line	Repair Needed	Standard repair.
33513	Completed Dozer Line	Repair Needed	19 Standard Repair
33514	Completed Dozer Line	Repair Needed	17 Standard Repair
33516	Completed Dozer Line	Repair Needed	24 Standard Repair, raw line
33517	Completed Dozer Line	Repair Needed	23 Standard Repair
43952	Completed Dozer Line	Repair Needed	159 Standard Repair
43953	Completed Dozer Line	Repair Needed	153 Refer to READ
43964	Completed Dozer Line	Repair Needed	Standard Repair
43965	•	•	158 Standard Repair
43970	Completed Dozer Line	Repair Needed	Steep section West of 259rd, refer to READ. Steep section of dozer line that will need water bars - duplicate length
43971	•		155 Standard Repair
50992	•		Standard repair.
50993	•	Repair Needed	
50998	•	Repair Needed	
52129	•	Repair Needed	
52130	·	Repair Needed	
52132	•	Repair Needed	
52133	•	Repair Needed	
52134	•	Repair Needed	
52135	·	Repair Needed	
52136 52138	•	Repair Needed	
52139		Repair Needed	27;special attention needed; Steep section west of 259 RD needs water bars
56621	•	•	Standard repair. Not a complete line. Dozer walked up hill. Sections of the walk are torn up from difficulty getting up hill.
32867		Repair Needed	Standard repair. Not a complete line. Bozer walked up film. Sections of the walk are torn up from almedity getting up film.
32868	•	Repair Needed	Standard
33163		Repair Needed	
33164	•	•	Standard road repair
33168		Repair Needed	Ditches clean of slash, stab height no more than 6", contouring, spread slash. Roads graded, culverts clear. thinning existing shaded fuel break.
33859	•	Repair Needed	
36104	•	•	Standard Repair
36106	Completed Fuel Break	Repair Needed	Ditches clean of slash, stab height no more than 6", contouring, spread slash. Roads graded, culverts clear. Logging of established treatment approximately 2 chains into the east side of the road.
36107	Completed Fuel Break	Repair Needed	Ditches clean of slash, stab height no more than 6", contouring, spread slash. Roads graded, culverts clear
38005	Completed Fuel Break	Repair Needed	Standard repair
42195	Completed Fuel Break	Repair Needed	Standard repair.
47173	Completed Fuel Break	Repair Needed	Treat heavily trafficked skid trail like dozer line, standard repair. Where fuel break meets private- weak link in holdable line
58518		Repair Needed	Standard Repair
58519	•		Standard Repair
42194	•	Unknown	
43951		•	160 Standard Repair
43966	•		156 Standard Repair
43967		•	157 Standard Repair
43968		•	154 Standard Repair
50994		Repair Needed	
52127	•	Repair Needed	·
52128	•		Standard repair.
29770	Completed Road as Line		·
32879	Completed Road as Line		·
32880	Completed Road as Line	•	
33165	Completed Road as Line		·
34947 50997	Completed Road as Line Completed Road as Line	•	13 standard, rolling dips knock berms, keep drivable for this year patrol
52437	Completed Road as Line		18 Standard Renair
34948	Completed Road as Line		15
31310	completed Road as Line	OTINIOWII	40

OBJECTID	FC Line Type	Repair Status	Repair Comments
52137	Access or Improved Road		•
43952	Completed Dozer Line		159 Standard Repair
43964	Completed Dozer Line	•	Standard Repair
48546	Completed Dozer Line	Repair Needed	Standard - edited 8-29 to represent extent
48547	Completed Dozer Line	Repair Needed	
50993	Completed Dozer Line	Repair Needed	Standard
50998	Completed Dozer Line	Repair Needed	standard
52129	Completed Dozer Line	Repair Needed	standard
52130	Completed Dozer Line	Repair Needed	standard
52131	Completed Dozer Line	Repair Needed	Standard
52132	Completed Dozer Line	Repair Needed	Standard
52133	Completed Dozer Line	Repair Needed	Standard
52135	Completed Dozer Line	Repair Needed	Standard
52136	Completed Dozer Line	Repair Needed	Standard
53594	Completed Dozer Line	Repair Needed	Standard repair. Slash pile. Skidsteer plow line. Skidsteer push piles.
53596	Completed Dozer Line	Repair Needed	Standard repair.
36107	Completed Fuel Break	Repair Needed	Ditches clean of slash, stab height no more than 6", contouring, spread slash. Roads graded, culverts clear
53622	Completed Fuel Break	Repair Needed	Standard repair. Mechanical thinned fuel break, width varies 100-250 ft wide. South side of 33 road
43951	Completed Hand Line	Repair Needed	160 Standard Repair
43967	Completed Hand Line	Repair Needed	157 Standard Repair
50994	Completed Hand Line	Repair Needed	33
52127	Completed Hand Line	Repair Needed	Standard repair
52128	Completed Hand Line	Repair Needed	Standard repair.
33165	Completed Road as Line	Repair Needed	Standard Repair
50997	Completed Road as Line	Repair Needed	
53595	Repair Line	Repair Needed	Big Tree Trail No. 311 Crushed white aggregate. Slash, heavy equipment tracks, Boulder fragments & timber. Tracked trail damage in fuel break only.
55027	Repair Line	Repair Needed	Standard repair. Dozer opened old road bed. Check snowmobile route. Ensure drainage. Block for OHV if not needed by forest

OBJECTID	FC Line Type	Repair Status	Repair Comments
45459	Access or Improved Road	Repair Needed	Standard Repair. Burnt log bunches
56623	Access or Improved Road	Repair Needed	Standard repair.
50983	Completed Dozer Line	Completed - Ready for Inspection	
28257	Completed Dozer Line	Repair Needed	Standard repair.
32277	Completed Dozer Line	Repair Needed	42 Standard Repair
32278	Completed Dozer Line	Repair Needed	41 Standard Repair
33166	Completed Dozer Line	Repair Needed	Standard repair.
33167	Completed Dozer Line	Repair Needed	Standard repair.
44294	Completed Dozer Line	Repair Needed	See plan
45450	Completed Dozer Line	Repair Needed	Standard Repair
45452	Completed Dozer Line	Repair Needed	Standard Repair
45453	Completed Dozer Line	Repair Needed	Standard Repair
45454	Completed Dozer Line	Repair Needed	Standard Repair
45456	Completed Dozer Line	Repair Needed	Standard Repair
45457	Completed Dozer Line	Repair Needed	
45460	Completed Dozer Line	Repair Needed	Standard Repair
45461	Completed Dozer Line	Repair Needed	Standard Repair, Raw dozer ties in to wetland- part fs part private land talk to landowner where line continues across their property
50980	Completed Dozer Line	Repair Needed	Standard repair, 36
50981	Completed Dozer Line	Repair Needed	Standard
50982	Completed Dozer Line	Repair Needed	Standard
50984	Completed Dozer Line	Repair Needed	Standard
50985	Completed Dozer Line	Repair Needed	Standard
50986	Completed Dozer Line	Repair Needed	Standard, 35
50987	Completed Dozer Line	Repair Needed	Standard repair.
50988	Completed Dozer Line	Repair Needed	Standard
50989	Completed Dozer Line	Repair Needed	Standard, 35
50991	Completed Dozer Line	Repair Needed	Standard repair.
50992	Completed Dozer Line	Repair Needed	Standard repair.
50993	Completed Dozer Line	Repair Needed	Standard
52135	Completed Dozer Line	Repair Needed	Standard
52136	Completed Dozer Line	Repair Needed	Standard
53613	Completed Dozer Line	Repair Needed	Standard
53614	Completed Dozer Line	Repair Needed	Natural fallen trees exist across interior dozer line
53615	Completed Dozer Line	Repair Needed	
53616	Completed Dozer Line	Repair Needed	Standard
53617	Completed Dozer Line	Repair Needed	Standard
56621	Completed Dozer Line	Repair Needed	Standard repair. Not a complete line. Dozer walked up hill. Sections of the walk are torn up from difficulty getting up hill.
56739	Completed Dozer Line	Repair Needed	Standard repair. Ties into fuel break
56740	Completed Dozer Line	Repair Needed	Standard repair
56741	Completed Dozer Line	Repair Needed	Standard repair. Two steep sections. Check excavator ability
56855	Completed Dozer Line	Repair Needed	
56856	Completed Dozer Line	Repair Needed	Standard repair.
28996	Completed Fuel Break	Repair Needed	40 Standard Repair. Green Logs still bunched
29772	Completed Fuel Break	Repair Needed	Scratch out skid trails where present, refer to READ about burned over log decks
36108	Completed Fuel Break	Repair Needed	Standard repair.
38004	Completed Fuel Break	Repair Needed	Standard repair.
50990	Completed Fuel Break	Repair Needed	Riparian area, heavy slash, rec area
55028	Completed Fuel Break	Repair Needed	Standard repair.
56846	Completed Fuel Break	Repair Needed	Standard Repair. Burnt log bunches
45451	Completed Hand Line	Repair Needed	Standard Repair
50994	Completed Hand Line	Repair Needed	33
33165	Completed Road as Line	Repair Needed	Standard Repair
38003	Completed Road as Line	·	Standard Repair
45458	Road Repair	Repair Needed	

OBJECT	ID FC Line Type	Repair Status	Repair Comments
56623	Access or Improved Road	Repair Needed	Standard repair.
50983	Completed Dozer Line	Completed - Ready for Ins	·
44294	Completed Dozer Line  Completed Dozer Line	Repair Needed	See plan
45450	Completed Dozer Line  Completed Dozer Line	Repair Needed	Standard Repair
45452	Completed Dozer Line  Completed Dozer Line	Repair Needed	Standard Repair
45453	Completed Dozer Line  Completed Dozer Line	Repair Needed	Standard Repair
45454	Completed Dozer Line  Completed Dozer Line	Repair Needed	Standard Repair
45456	Completed Dozer Line	Repair Needed	Standard Repair
45457	Completed Dozer Line  Completed Dozer Line	Repair Needed	Standard Repail
45465	Completed Dozer Line  Completed Dozer Line	Repair Needed	Standard repair Dezer cut clid trail along banch above cteen section next to read
50980	Completed Dozer Line  Completed Dozer Line	Repair Needed Repair Needed	Standard repair. Dozer cut skid trail along bench above steep section next to road, Standard repair, 36
50981	•	•	Standard
50982	Completed Dozer Line	Repair Needed	
	Completed Dozer Line	Repair Needed	Standard
50984	Completed Dozer Line	Repair Needed	Standard
50985	Completed Dozer Line	Repair Needed	Standard
50986	Completed Dozer Line	Repair Needed	Standard, 35
50987	Completed Dozer Line	Repair Needed	Standard repair.
50988	Completed Dozer Line	Repair Needed	Standard
50989	Completed Dozer Line	Repair Needed	Standard, 35
53613	Completed Dozer Line	Repair Needed	Standard
53614	Completed Dozer Line	Repair Needed	Natural fallen trees exist across interior dozer line
53615	Completed Dozer Line	Repair Needed	
53616	Completed Dozer Line	Repair Needed	Standard
53617	Completed Dozer Line	Repair Needed	Standard
56741	Completed Dozer Line	Repair Needed	Standard repair. Two steep sections. Check excavator ability
29772	Completed Fuel Break	Repair Needed	Scratch out skid trails where present, refer to READ about burned over log decks
32276	Completed Fuel Break	Repair Needed	Rehab skid trail in FB to standard spec in repair plan. Use rubber tracked mini excavator to clear out roadside ditch
36640	Completed Fuel Break	Repair Needed	Heavily logged with cut material still on ground
47623	Completed Fuel Break	Repair Needed	Standard repair
53620	Completed Fuel Break	Repair Needed	Standard repair. Mechanical thinned fuel break, south side of road, GPS track from road FB approx 150-300 ft wide
53621	Completed Fuel Break	Repair Needed	Standard repair. Complete mechanical thinned fuel break above 33 RD. GPS tracked approx. N side of FB where it leaves 33 Rd
53622	Completed Fuel Break	Repair Needed	Standard repair. Mechanical thinned fuel break, width varies 100-250 ft wide. South side of 33 road
58522	Completed Fuel Break	Repair Needed	
45451	Completed Hand Line	Repair Needed	Standard Repair
47622	Completed Mixed Construction Line	e Repair Needed	Standard repair fuel break and dozer line. Thinned Fuel Break with Dozer line
38003	Completed Road as Line	Repair Needed	Standard Repair
55027	Repair Line	Repair Needed	Standard repair. Dozer opened old road bed. Check snowmobile route. Ensure drainage. Block for OHV if not needed by forest
45458	Road Repair	Repair Needed	

42882

Road Repair

Report: Re	epair Lines Table		Walker Creek WA-NES-002245 09/08/2021  Map Page Number:
OBJECTI	D FC Line Type	Donair Status	s Repair Comments
29730	Access or Improved Road		Standard Repair
50115	Access or Improved Road	Repair Needed	
52061	Access or Improved Road		Boulders need to put back to close road, standard
56623	Access or Improved Road  Access or Improved Road		Standard repair.
48692	•	•	Statidatu repail.
	Completed Dozer Line	In Progress	Cond?
49822	Completed Dozer Line	In Progress	Seed?
49850	Completed Dozer Line	In Progress	standard. water bars in place, berm pushed back and brushed.
52688	Completed Dozer Line	In Progress	Standard, equipment done needs seeding
52689	Completed Dozer Line	In Progress	Standard, needs seeding
55029	Completed Dozer Line	In Progress	Standard, Seeding?
55030	Completed Dozer Line	In Progress	Standard, heavy slash will be hard to seed
28071	Completed Dozer Line	Repair Needed	
28073	Completed Dozer Line		Standard Repair
29733	Completed Dozer Line	•	Standard Low priority, seeding needed
29740	Completed Dozer Line	Repair Needed	Standard
29742	Completed Dozer Line	Repair Needed	Standard Repair
48690	Completed Dozer Line	Repair Needed	
48693	Completed Dozer Line	Repair Needed	Standard
49813	Completed Dozer Line	Repair Needed	
49819	Completed Dozer Line	Repair Needed	Standard repair.
49820	Completed Dozer Line	Repair Needed	Standard repair.
49821	Completed Dozer Line	Repair Needed	Standard
49824	Completed Dozer Line	Repair Needed	
49826	Completed Dozer Line	Repair Needed	
49851	Completed Dozer Line	Repair Needed	
49852	Completed Dozer Line	Repair Needed	
49853	Completed Dozer Line	Repair Needed	
52063	Completed Dozer Line		Standard or seed only
52124	Completed Dozer Line	Repair Needed	·
58545	Completed Dozer Line  Completed Dozer Line		Standard Repair
58547	Completed Dozer Line  Completed Dozer Line	Repair Needed	
	·	Repair Needed	
59267 32276	Completed Dozer Line	•	
	Completed Fuel Break	•	Rehab skid trail in FB to standard spec in repair plan. Use rubber tracked mini excavator to clear out roadside ditch
36640	Completed Fuel Break	•	Heavily logged with cut material still on ground
40063	Completed Fuel Break		Standard repair
47623	Completed Fuel Break	•	Standard repair
47625	Completed Fuel Break	•	Standard repair. Fuel break and rd. Completed Mechanical thinned fuel break along road
47627	Completed Fuel Break	•	Standard repair. Completed Mechanical thinned Fuel break along road.
47629	Completed Fuel Break		Standard repair. Mechanical thinned fuel Break along road. GPS track of road in continuous fuel break
49810	Completed Fuel Break	•	Completed Mechanical thinned shaded fuel break. Width varies, approx 100-150 ft on average. Road will need standard repair
49811	Completed Fuel Break		Standard repair. Fuel break with dozer line. GPS track of Dozer line b/w Improved road in mechanical thinned fuel break. DL width 10 ft. FB width approx 200 ft
49812	Completed Fuel Break	Repair Needed	Standard repair. Fuel break with dozer line.
49815	Completed Fuel Break	Repair Needed	Standard repair
49816	Completed Fuel Break	Repair Needed	Standard repair.
49817	Completed Fuel Break	Repair Needed	See road repair track previously represented
49818	Completed Fuel Break	Repair Needed	See road repair track previously represented. Completed Mechanical thinned fuel break along improved road. GPS track of road, FB approx 100 ft wide. Part of continuous mixed FB
53620	Completed Fuel Break	Repair Needed	Standard repair. Mechanical thinned fuel break, south side of road, GPS track from road FB approx 150-300 ft wide
58522	Completed Fuel Break	Repair Needed	
53699	Completed Hand Line	Repair Needed	
53700	Completed Hand Line	Repair Needed	
53701	Completed Hand Line		Standard repair.
53702	Completed Hand Line	Repair Needed	
53702	Completed Hand Line	Repair Needed	
58548	Completed Hand Line	Repair Needed	
58549	Completed Hand Line	Repair Needed	
47622	•	•	Standard repair fuel break and dozer line. Thinned Fuel Break with Dozer line
47624	•	•	Standard repair fuel break and dozer line. Completed mechanical thinned fuel break with Dozer line
47626	•		Standard repair Fuel break and dozer line. Completed Mechanical thinning with dozer line. GPS track of dozer line
	·	•	·
47628	,		Standard repair. Fuel break and dozerline on old skid trail
49814	•	•	Standard repair. Fuel break and dozer line. GPS track of Dozer line in mechanical thinned Fuel break. DZ line width 10 ft. FB width 150 -200 ft
42951	Completed Mixed Construction Line		Reshape draw, pull in berms and slash, seed
26836	Completed Road as Line	Repair Needed	
36826	Completed Road as Line		59 Rehab, closed to vehicles, ohv
52440	Completed Road as Line	Repair Needed	
52441	Completed Road as Line	•	Standard also needs chipping or scattering of windrow
53698	Completed Road as Line	•	Standard repair.
59260	Completed Road as Line	Repair Needed	Standard

Repair Needed Standard repair. Add drainage, pull in side berms, road was previously closed with earthen berms at each end

OBJECTID	FC Line Type	Repair Status	Repair Comments
38008			Road will need attention post suppression, possibly gravel
45459	·		Standard Repair. Burnt log bunches
52061	·	•	Boulders need to put back to close road, standard
26824	Completed Dozer Line	•	Standard low priority
26825	Completed Dozer Line	Repair Needed	1 1
26826	Completed Dozer Line	•	Standard Repair, Some sections are on non system roads
26827	Completed Dozer Line	•	Standard Repair
26828		Repair Needed	·
26829	Completed Dozer Line		113 Standard Repair
26830	Completed Dozer Line	•	Standard Repair
26833	Completed Dozer Line	-	114 Standard Repair
28993	Completed Dozer Line	Repair Needed	45 Standard Repair
29735	Completed Dozer Line	Repair Needed	Standard
29738	Completed Dozer Line	Repair Needed	
30115	Completed Dozer Line	Repair Needed	Hazard trees everywhere , lots of downfall and other debris no mechanical repair needed
30116	Completed Dozer Line	Repair Needed	Standard
32277	Completed Dozer Line	Repair Needed	42 Standard Repair
32278	Completed Dozer Line	Repair Needed	41 Standard Repair
40744	Completed Dozer Line	Repair Needed	Standard repair.
43511	Completed Dozer Line	Repair Needed	Standard
45452	Completed Dozer Line	Repair Needed	Standard Repair
45460	Completed Dozer Line	Repair Needed	Standard Repair
45461	Completed Dozer Line	Repair Needed	Standard Repair, Raw dozer ties in to wetland- part fs part private land talk to landowner where line continues across their property
48681	Completed Dozer Line	Repair Needed	Standard repair
48682	Completed Dozer Line	Repair Needed	Standard. GPS track of previously represented dozer line
48683	Completed Dozer Line	Repair Needed	Standard
50346	Completed Dozer Line	Repair Needed	Standard,
50840	Completed Dozer Line	Repair Needed	Standard
50980	Completed Dozer Line	Repair Needed	Standard repair, 36
50981	Completed Dozer Line	Repair Needed	Standard
50982	Completed Dozer Line	Repair Needed	Standard
52058	Completed Dozer Line	Repair Needed	DI around slash pile
52059	Completed Dozer Line	Repair Needed	Around slash piles
52125	Completed Dozer Line	Repair Needed	Standard
52126	Completed Dozer Line	Repair Needed	Standard
52439	Completed Dozer Line	Repair Needed	Standard Low priority
53618	Completed Dozer Line	Repair Needed	Standard
56534	Completed Dozer Line	Repair Needed	49 Standard Repair
56536	Completed Dozer Line	Repair Needed	
56739	Completed Dozer Line	Repair Needed	Standard repair. Ties into fuel break
56740	Completed Dozer Line	Repair Needed	Standard repair
56741	Completed Dozer Line	-	Standard repair. Two steep sections. Check excavator ability
58032	•	Repair Needed	Standard
58035	Completed Dozer Line	Repair Needed	Starting at Boy Scout shooting rang very visible and steep section of line. No slash to grab. DI becomes road near intersection. Waterbar and seed
58036	Completed Dozer Line	Repair Needed	Seed
58037	Completed Dozer Line	Repair Needed	
58038	Completed Dozer Line	Repair Needed	
58525	Completed Dozer Line	Repair Needed	Standard repair
58528	Completed Dozer Line	Repair Needed	Standard repair
58530	Completed Dozer Line	Repair Needed	Standard repair.
58536	Completed Dozer Line	Repair Needed	
59258	Completed Dozer Line	•	repair very low priority, rocky lots of wood on it all ready, smaller side cast
59259	Completed Dozer Line		Pull berms, seed water bar where necessary, do not pull slash in case it was a road bed
59266	Completed Dozer Line	-	Standard low priority, minimal sidecast, if resources are limited seed only hand crew could handle adding slash back on line
29737	Completed Dozer Line	Unknown	
28996	Completed Fuel Break	•	40 Standard Repair. Green Logs still bunched
29772	Completed Fuel Break	•	Scratch out skid trails where present, refer to READ about burned over log decks
47629	Completed Fuel Break	•	Standard repair. Mechanical thinned fuel Break along road. GPS track of road in continuous fuel break
50839	Completed Fuel Break	•	Excavator made line ,low priority
56846	Completed Fuel Break		Standard Repair. Burnt log bunches
43512	Completed Hand Line	-	Standard repair.
45462	Completed Hand Line		Standard Repair
50841	Completed Hand Line	-	Pull hose does not need other repair
58033	Completed Hand Line	Repair Needed	
58034	Completed Hand Line	Repair Needed	·
26834	•	•	97, ćheck nvum map, standard
28077	Completed Road as Line	•	·
28994	Completed Road as Line	•	
28995	Completed Road as Line	•	·
30114	Completed Road as Line	•	
38007	Completed Road as Line	•	·
50347	Completed Road as Line	•	
52440	Completed Road as Line	-	
52441		•	Standard also needs chipping or scattering of windrow
58534	Completed Road as Line	•	
59260	Completed Road as Line	•	Standard
53619	Completed Road as Line	Unknown	