OBJECTID	FC Point Type	Repair Status	Repair Comments
30534	Dozer Push	Repair Needed	30' x 50'
36513	Dozer Push	Repair Needed	Standard 0.3 acre dozer push
36805	Dozer Push	Repair Needed	Standard repair. See suppression repair plan. Approximately 80 x 50 feet
37422	Dozer Push	Repair Needed	
22389	Drop Point	Other - See Comments	
28336	Drop Point	Repair Needed	Standard repair. 50' x 300' seed
30533	Landing or Log Deck	Repair Needed	Standard repair. No timber was stacked here. Just made ready.
36512	Repair Point	Repair Needed	1.5 acre staging area with non fire related logging equipment staged in it. Check with district concerning current or future use of the area prior to standard repair
36808	Repair Point	Repair Needed	Gather hose before beginning dozer repair.
40493	Repair Point	Repair Needed	Remove dam created for pump.
40535	Repair Point	Repair Needed	Replace berm

Report: Repair Point Table

Walker Creek WA-NE

OBJECTID	FC Point Type	Repair Status	Repair Comments
32306	Clean Up Area	Repair Needed	
33330	Clean Up Area	Unknown	
33422	Clean Up Area	Repair Needed	Clean up hose prior to repair
35498	Clean Up Area	Repair Needed	
32875	Dozer Push	Repair Needed	
21450	Drop Point	Unknown	
21451	Drop Point	Unknown	
21452	Drop Point	Repair Needed	Standard, seeding needed
25588	Fence - Cut/Damaged	Repair Needed	
32873	Fence - Cut/Damaged	Repair Needed	standard
22851	Safety Zone	Repair Needed	Refer to READ

Walker Creek WA-NES-002245 09/08/2021 Map Page Number: 10

OBJECTID	FC Point Type	Repair Status	Repair Comments
32304	Culvert	Repair Needed	Crushed culvert, will need to be replaced 32' long 18" cmp
30534	Dozer Push	Repair Needed	30' x 50'
36513	Dozer Push	Repair Needed	Standard 0.3 acre dozer push
36804	Dozer Push	Repair Needed	Standard repair. 60' diameter
36805	Dozer Push	Repair Needed	Standard repair. See suppression repair plan. Approximately 80 x 50 feet
28336	Drop Point	Repair Needed	Standard repair. 50' x 300' seed
24515	Gate	No Repair Needed	
32210	Helispot	Repair Needed	Standard repair - move merch. timber to be processed
39013	Landing or Log Deck	Repair Needed	Standard repair
39014	Landing or Log Deck	Repair Needed	Standard repair
39015	Landing or Log Deck	Repair Needed	Standard repair.
35566	Mobile Weather Unit	Unknown	
36808	Repair Point	Repair Needed	Gather hose before beginning dozer repair.
39282	Repair Point	Repair Needed	Spring/ drainage pull fill from rd base
40535	Repair Point	Repair Needed	Replace berm
38942	Stream Crossing	Repair Needed	Excavator work, pull material out of earthen dam, match channel to upstream or downstream size and grade, high priority
39281	Stream Crossing	Repair Needed	Standard. Pull fill return grade

OBJECTID	FC Point Type	Repair Status	Repair Comments
26024	Culvert	Repair Needed	Blocked by fuel break machine activity
36804	Dozer Push	Repair Needed	Standard repair. 60' diameter
21557	Drop Point	Unknown	
24099	Drop Point	Unknown	
24101	Drop Point	Unknown	
35942	Fence - Cut/Damaged	Repair Needed	50 ft 3-strand barbed wire
	Gate	Unknown	currently open need to check mvum
24388	Helispot	Unknown	
	Landing or Log Deck	Repair Needed	Recontour and seed when ready, possibly plant trees
	Landing or Log Deck	•	Recontour and seed when ready
	Landing or Log Deck	•	Recontour and seed when ready
	Landing or Log Deck	·	Recontour and seed when ready
	Landing or Log Deck	•	Recontour and seed when ready
	Landing or Log Deck	•	Recontour and seed when ready
	Landing or Log Deck	•	
	Landing or Log Deck	·	
	Landing or Log Deck	•	Standard repair
	Landing or Log Deck	•	Standard repair
	Landing or Log Deck	•	Standard repair
	Landing or Log Deck	•	Standard repair
	Landing or Log Deck	•	Standard repair
	Landing or Log Deck	•	Standard repair
	Landing or Log Deck	•	Standard repair
	Landing or Log Deck	·	Standard repair
	Landing or Log Deck	•	Standard repair
	Landing or Log Deck	•	Standard repair
	Landing or Log Deck	•	Standard repair
	Landing or Log Deck	•	Standard repair
		Repair Needed	Standard repair.
	Repair Point	Repair Needed	Standard repair. Repair drainage feature to original shape. 3 more rolling dips east of this dip to be included in the repairs of these drainage features.
	Repair Point	Repair Needed	Standard repair. Fuel break. End of dozer push.
	Repair Point	Repair Needed	Block access to old skid road used
	Resource Location	No Repair Needed	
	Safety Zone	Repair Needed	Recontour and seed when ready, possibly plant trees, line safety zone with boulder obstructions to keep from turning into parking lot/dispersed camping
	Stream Crossing	Repair Needed	Excavator work, pull material out of earthen dam, match channel to upstream or downstream size and grade, high priority
	Structure Wrap	Unknown	
	Value at Risk	Unknown	
	Value at Risk		Standard Repair, pull berms and blend disturbed areas around trees behind building and around building
	Value at Risk	No Repair Needed	• • • •
	Water Source	Unknown	
[Trace Source	CHRIOWII	

Report: Repair Point Table Walker Creek WA-NES-002245 09/08/2021 Map Page Number: 4

OBJECTID	FC Point Type	Repair Status	Repair Comments
	Culvert	-	Water bar west approach to stream crossing. east okay water bar if time allows
29893	Culvert	•	Compromised from shaded full break replace 16", unknown length. Need to find joint cannot replace down stream end
	Culvert	•	Crushed inlet. Buried outlet. Clear out
36241	Dozer Push	Repair Needed	
38947	Dozer Push	•	Standard repair.
21557	Drop Point	Unknown	
22414	Drop Point	Unknown	
21137	Fence - Cut/Damaged	Repair Needed	Standard
35562	Fence - Cut/Damaged	Repair Needed	
35951	Fence - Cut/Damaged	Repair Needed	Standard repair.
35952	Fence - Cut/Damaged	Repair Needed	Standard repair.
35953	Fence - Cut/Damaged	Repair Needed	standard
29892	Gate	Unknown	currently open need to check mvum
25080	Landing or Log Deck	Repair Needed	Recontour and seed when ready. Product of completed fuel break
25081	Landing or Log Deck	Repair Needed	Recontour and seed when ready. Product of completed fuel break
25082	Landing or Log Deck	Repair Needed	Recontour and seed when ready
26491	Landing or Log Deck	Repair Needed	Recontour and seed when ready
27971	Landing or Log Deck	Repair Needed	Standard repair. Recontour and seed when ready
27974	Landing or Log Deck	Repair Needed	Recontour and seed when ready
27976	Landing or Log Deck	Repair Needed	Recontour and seed when ready
27977	Landing or Log Deck	Repair Needed	Recontour and seed when ready
27979	Landing or Log Deck	Repair Needed	Standard repair. Recontour and seed when ready
28737	Landing or Log Deck	Repair Needed	Recontour and seed when ready
28738	Landing or Log Deck	Repair Needed	Recontour and seed when ready
28739	Landing or Log Deck	Repair Needed	Recontour and seed when ready
31102	Landing or Log Deck	Repair Needed	Recontour and seed when ready
26500	Repair Point	Repair Needed	Ground baserecountour. Logging on steep slope, soil disturbance 55% slope
28057	Repair Point	Repair Needed	Road damage, refer to engineering
31103	Repair Point	Repair Needed	Return road barrier (boulders). Road barrier boulders moved
24875	Road Repair	Repair Needed	Fill in dip on top of the culvert to avoid water routing. Water bar both approaches to stream crossing.
24876	Road Repair	Repair Needed	Fill in dip on top of the culvert to avoid water routing. Water bar both approaches to stream crossing.
24877	Road Repair	Repair Needed	Fill in ditch on top culvert & water bar both approaches to stream crossing
40459	Road Repair	Repair Needed	Buried and crushed culvert, clear inlet and assess damage, replace or repair as needed
24860	Stream Crossing	Repair Needed	Remove road fill/dozer push from stream, on upstream side, cleanup pipe inlet blockage
24861	Stream Crossing	Repair Needed	Cleanup outlet
31372	Stream Crossing	Repair Needed	Refer to READ
22412	Water Source	Unknown	

OBJECTID	FC Point Type	Repair Status	Repair Comments
22414	Drop Point	Unknown	
35562	Fence - Cut/Damaged	Repair Needed	
35951	Fence - Cut/Damaged	Repair Needed	Standard repair.
35952	Fence - Cut/Damaged	Repair Needed	Standard repair.
35953	Fence - Cut/Damaged	Repair Needed	standard
28151	Helispot	Unknown	
25082	Landing or Log Deck	Repair Needed	Recontour and seed when ready
27971	Landing or Log Deck	Repair Needed	Standard repair. Recontour and seed when ready
27979	Landing or Log Deck	Repair Needed	Standard repair. Recontour and seed when ready
31660	Landing or Log Deck	Repair Needed	Recontour and seed when ready, scratch out skid trails
32230	Landing or Log Deck	Repair Needed	Standard repair.
32231	Landing or Log Deck	Repair Needed	Standard Repair
32232	Landing or Log Deck	Repair Needed	Standard repair.
35954	Landing or Log Deck	Repair Needed	Firewood deck. All snags
32751	Repair Point	Repair Needed	Check with district, clean slash piles
25101	Resource Location	No Repair Needed	
22390	Staging Area	Unknown	
22412	Water Source	Unknown	

OBJECTID	FC Point Type	Repair Status	Repair Comments
38947	Dozer Push	Repair Needed	Standard repair.
22603	Drop Point	Repair Needed	Seed; 2.5 acres
35560	Fence - Cut/Damaged	Repair Needed	
35561	Fence - Cut/Damaged	Repair Needed	
35562	Fence - Cut/Damaged	Repair Needed	
35563	Fence - Cut/Damaged	Repair Needed	Standard repair. 4 strand barbed wire with spacer. ~ 60 ft
35564	Fence - Cut/Damaged	Repair Needed	Standard repair. 3 strand barbed wire.
35945	Fence - Cut/Damaged	Repair Needed	4 strand barbed wire. Damaged in multiple places around pump house. Unable to determine length due to multiple log trees still on ground.
39001	Fence - Cut/Damaged	Completed - Inspected	Might need access if repair on private happens
40534	Fence - Cut/Damaged	Repair Needed	2 T-posts. 30' 4 strands of wire
40537	Fence - Cut/Damaged	Repair Needed	Two T posts. 4 strand fence. 50 feet
40539	Fence - Cut/Damaged	Repair Needed	1 T-post. 20' four strand wire
27970	Landing or Log Deck	Repair Needed	Standard repair.
31197	Landing or Log Deck	Repair Needed	Standard repair.
28053	Repair Point	Repair Needed	Seed about an acre
28054	Repair Point	Repair Needed	Seed skid trails
31188	Repair Point	Repair Needed	Seed about an acre
36233	Repair Point	Repair Needed	Cut water pipe going to Lost Lake pump house to the north.
25118	Value at Risk	No Repair Needed	

OBJECTID	FC Point Type	Repair Status	Repair Comments
27960	Culvert	Repair Needed	Unbury culvert
40446	Culvert	Repair Needed	Clear out buried inlet
40447	Culvert	Repair Needed	Clear out buried inlet of culvert
40448	Culvert	Repair Needed	Clear out inlet and outlet
40528	Culvert	Repair Needed	Pull slash out of culvert.
40530	Culvert	Repair Needed	Pull slash out of opening.
40533	Culvert	Repair Needed	Pull slash and debris from opening
31657	Dozer Push	Repair Needed	Standard repair.
35560	Fence - Cut/Damaged	Repair Needed	
40534	Fence - Cut/Damaged	Repair Needed	2 T-posts. 30' 4 strands of wire
40537	Fence - Cut/Damaged	Repair Needed	Two T posts. 4 strand fence. 50 feet
40539	Fence - Cut/Damaged	Repair Needed	1 T-post. 20' four strand wire
28085	Landing or Log Deck	Repair Needed	Standard repair. 1.5 acres
28837	Landing or Log Deck	Repair Needed	Standard repair. Unprocessed logs on fire side of FB
31658	Landing or Log Deck	Repair Needed	Standard repair.
31660	Landing or Log Deck	Repair Needed	Recontour and seed when ready, scratch out skid trails
32228	Landing or Log Deck	Repair Needed	Standard repair.
32229	Landing or Log Deck	Repair Needed	Standard repair.
32230	Landing or Log Deck	Repair Needed	Standard repair.
28053	Repair Point	Repair Needed	Seed about an acre
28058	Repair Point	Repair Needed	Scratch out skid trails and seed where possible
28059	Repair Point	Repair Needed	25 mph sign is down
32305	Road Repair	Repair Needed	250 cubic yards needed, grader, tender, shoulder removed 150' length at least 3' of road and shoulder. nOt standards
40449	Road Repair	Repair Needed	Sliver fill, dump truck, grader, water truck. 100 cubic yards
40450	Road Repair	Repair Needed	TBD, this a steep, deep repair, more measurements needed. Skidsteer, cat needed. Sliver fill, dump truck, grader, water. At least 200 cubic yards material.
40451	Road Repair	Repair Needed	Sliver fill, dump truck, grader, water truck. 70' long section , downhill side, 70 cubic yards material for downhill sides of road.
40452	Road Repair	Repair Needed	Sliver fill, dump truck, grader, water truck. 70' long section , downhill side, 70 cubic yards material for downhill sides of road.
40453	Road Repair	Repair Needed	Sliver fill, dump truck, grader, water truck, downhill side, 50 cubic yards material for downhill sides of road.
40454	Road Repair	Repair Needed	Sliver fill, dump truck, grader, water truck, downhill side, 100 cubic yards material for downhill sides of road.
40455	Road Repair	Repair Needed	Sliver fill, dump truck, grader, water truck, downhill side, 80 cubic yards material for downhill sides of road.
27967	Stream Crossing	Unknown	

OBJECTID	FC Point Type	Repair Status	Repair Comments
32306	Clean Up Area	Repair Needed	
33330	Clean Up Area	Unknown	
40446	Culvert	Repair Needed	Clear out buried inlet
40447	Culvert	Repair Needed	Clear out buried inlet of culvert
40448	Culvert	Repair Needed	Clear out inlet and outlet
40528	Culvert	Repair Needed	Pull slash out of culvert.
40530	Culvert	Repair Needed	Pull slash out of opening.
40533	Culvert	Repair Needed	Pull slash and debris from opening
31657	Dozer Push	Repair Needed	Standard repair.
32875	Dozer Push	Repair Needed	
36277	Dozer Push	Repair Needed	
36278	Dozer Push	Repair Needed	Standard repair.
36279	Dozer Push	Repair Needed	Standard repair.
39601	Dozer Push	Repair Needed	Standard repair.
21450	Drop Point	Unknown	
21451	Drop Point	Unknown	
21452	Drop Point	Repair Needed	Standard, seeding needed
25588	Fence - Cut/Damaged	Repair Needed	
32873	Fence - Cut/Damaged	Repair Needed	standard
36281	Fence - Cut/Damaged	Repair Needed	
28085	Landing or Log Deck	Repair Needed	Standard repair. 1.5 acres
28837	Landing or Log Deck	Repair Needed	Standard repair. Unprocessed logs on fire side of FB
32228	Landing or Log Deck	Repair Needed	Standard repair.
28058	Repair Point	Repair Needed	Scratch out skid trails and seed where possible
28059	Repair Point	Repair Needed	25 mph sign is down
30494	Repair Point	Repair Needed	Standard Repair. Log deck moved. Slash pile left
32305	Road Repair	Repair Needed	250 cubic yards needed, grader, tender, shoulder removed 150' length at least 3' of road and shoulder. nOt standards
40449	Road Repair	Repair Needed	Sliver fill, dump truck, grader, water truck. 100 cubic yards
40450	Road Repair	Repair Needed	TBD, this a steep, deep repair, more measurements needed. Skidsteer, cat needed. Sliver fill, dump truck, grader, water. At least 200 cubic yards material.
40451	Road Repair	Repair Needed	Sliver fill, dump truck, grader, water truck. 70' long section , downhill side, 70 cubic yards material for downhill sides of road.
40452	Road Repair	Repair Needed	Sliver fill, dump truck, grader, water truck. 70' long section, downhill side, 70 cubic yards material for downhill sides of road.
40453	Road Repair	Repair Needed	Sliver fill, dump truck, grader, water truck, downhill side, 50 cubic yards material for downhill sides of road.
40454	Road Repair	Repair Needed	Sliver fill, dump truck, grader, water truck, downhill side, 100 cubic yards material for downhill sides of road.
27967	Stream Crossing	Unknown	

Report: Repair Point Table

Walker Creek WA-NES-002245 09/08/2021

Map Page Number: 9

OBJECTID	FC Point Type	Repair Status	Repair Comments
33422	Clean Up Area	Repair Needed	Clean up hose prior to repair
35498	Clean Up Area	Repair Needed	
21 44 8	Drop Point	Unknown	
22415	Drop Point	Unknown	
22853	Drop Point	Unknown	
25590	Fence - Cut/Damaged	Repair Needed	
39001	Fence - Cut/Damaged	Completed - Inspected	Might need access if repair on private happens
39508	Fence - Cut/Damaged	Repair Needed	Standard, T post removed and lost
39511	Fence - Cut/Damaged	Repair Needed	Standard
31662	Gate	Unknown	
362 4 2	Landing or Log Deck	Repair Needed	Standard repair
31188	Repair Point	Repair Needed	Seed about an acre
37378	Road Repair	Completed - Inspected	
22413	Water Source	Unknown	
22854	Water Source	Unknown	