


Suppression Repair Tiles

Cedar Creek
OR-WF-2024-60
10/20/2022 24 Hour
126,222 acres at 10/19/2022 @ 815
1:1,100,000
Div R


Note: This map and associated tables have been filtered to only show Repair Points / Lines of Medium or High priority. There exists numerous other features of unknown or low priority repair needs throughout the fire area. The intended use of this map is to define/represent the repair work to be completed during IMT12 oversight of this incident. This map should **NOT** be considered a complete source for repair information.



Repair ID	Priority	Point Type	Status	Repairs Needed	Repair Comments	Latitude	Longitude
8007	High	Door Post	Repair Needed	Fill, 2000'	Waldo Lake, fill in door, add debris, add rock to rear natural bank, fill road	42° 38.672' N	121° 58.157' W
8008	High	Door Post	Repair Needed	Fill, 2000'	Waldo Lake, fill in door, add debris, add rock to rear natural bank, fill road	42° 38.672' N	121° 58.157' W
8009	High	Door Post	Repair Needed	Fill, 2000'	Waldo Lake, fill in door, add debris, add rock to rear natural bank, fill road	42° 38.672' N	121° 58.157' W



Div R



0 Miles
Map exported at 10/19/2022 21:13

Repair ID	Priority	Line Type	Status	Repairs Needed	Repair Comments	Len (ft)
1007	High	Completed Door Line	Completed / Inspected	None	WALDO LAKE & ROAD-Downer Inspected 10/20/2022	1068
1008	High	Completed Door Line	Repair Needed	None	WALDO LAKE & ROAD-Downer Inspected 10/20/2022	1068
1009	High	Completed Door Line	Repair Needed	Fill, 2000'	Waldo Lake, fill in door, add debris, add rock to rear natural bank, fill road	1068

Repair ID	Priority	Line Type	Status	Repairs Needed	Repair Comments	Len (ft)
8007	High	Completed Door Line	Repair Needed	Fill, 2000'	Waldo Lake, fill in door, add debris, add rock to rear natural bank, fill road	1068
8008	High	Completed Door Line	Repair Needed	Fill, 2000'	Waldo Lake, fill in door, add debris, add rock to rear natural bank, fill road	1068
8009	High	Completed Door Line	Repair Needed	Fill, 2000'	Waldo Lake, fill in door, add debris, add rock to rear natural bank, fill road	1068