

Repair Points - Low Priority

Point Type NOT IN ('Repair Point', 'Road Repair')
 Feature Status = 'Approved'
 Delete This NOT IN ('Yes - No Longer Needed', 'Yes - Editing Mistake')
 Repair Status NOT IN ('In Use - Fire Management', 'No Repair Needed')
 Repair Priority = Low

| GISS Misc | Point Type | Repair Status | Repairs Needed | Repair Comments |
|-----------|---------------------|------------------|------------------------------------|--|
| 312 | Culvert | Repair Needed | Clean out inlet | |
| 321 | Culvert | Repair Needed | Clean out inlet | |
| 340 | Resource Location | Repair Needed | Cut high stumps | |
| 468 | Culvert | Needs Assessment | Full repair | Clear uphill culvert entrance |
| 469 | Culvert | Needs Assessment | | Clear culvert of debris on uphill side |
| 611 | Landing or Log Deck | Repair Needed | Chip trees and slash. Small amount | Not to much material. Thrown on the downslope |
| | Other | Repair Needed | | READ Sargent 8/28/23. Lookout spot. Remove flagging when no longer needed. |

Repair Points - Medium Priority

Point Type NOT IN ('Repair Point', 'Road Repair')
 FeatureStatus = 'Approved'
 DeleteThis NOT IN ('Yes - No Longer Needed', 'Yes - Editing Mistake')
 Repair Status NOT IN ('In Use - Fire Management', 'No Repair Needed')
 Repair Priority = Medium

| GISS Misc | Point Type | Repair Status | Repairs Needed | Repair Comments |
|-----------|------------|---------------|--|--|
| 3 | Helispot | Repair Needed | READ Sargent 82723. Large landing converted to helispot. May need native re-seeding. | Light repair, part of POD |
| 174 | Dozer Push | Repair Needed | Light Repair | Leave as a permanent parking area, seed and mulch to prevent invasives. REAF Martin 8/27 |
| | Culvert | Repair Needed | Replace culvert. Pipe got hit by masticator and is now destroyed. REAF Olin 8/26 | |